

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEAD QUARTERS, DELHI FIRE SERVICE, NEW DELHI - 110001.

No.F.6/DFS/MS/NDZ/2025/ 958

Dated: 06/06/2025

To,

The Executive Engineer,
Vigyan Bhawan, Electric Division, CPWD,
Vigyan Bhawan Annexe, New Delhi.

Sub: Regarding issuance of FSC in r/o Udhayog Bhawan, New Delhi.

Sir,

This has reference to your mail id <eevhed@hotmail.com> dated 15.05.2025, on the subject cited above. In this connection it is to inform you that the site was visited by the officers concerned of this department on 30/05/2025 in the presence of Sh. Dharamvir Meena AE (E) and observed that the point no. 1 & 2 of shortcomings issued earlier vide letter no. F6/DFS/MS/2023/689 dated 06.04.23 (copy enclosed) is still not complied.

Therefore, you are requested to submit complete compliance of the shortcomings for further consideration in the matter.

Yours faithfully,

Encl. As Above.

Copy to:

The Chief Architect, NDMC, Palika Kendra, New Delhi.

(Virendra Singh)
Chief Fire Officer
Delhi Fire Service

5/6/2025
3/6

C/32

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEAD QUARTERS : DELHI FIRE SERVICE : NEW DELHI – 110001

No.F.6/DFS/MS/2023/ 689

Dated: 06/04/2023

To

The Executive Engineer,
Vigyan Bhawan, Electric Division, CPWD
Vigyan Bhawan Annexe, New Delhi

Sub:- Regarding issuance of fire safety certificate(FSC) in r/o Udhyog Bhawan , New Delhi.

Sir,

This has a reference to your letter no. 20(35)/V.B.E.Div./2022-23/622 dated 01.03.23 on the subject cited above, it is to inform you that the site was inspected by the officers concerned of this department on 28/03/2023 in the presence of Sh. Dharamvir, AE (E), Sh. Govind Kaji, JE, CPWD and the following shortcomings were observed:-

1. Compartmentation is not done by providing fire check doors as per letter no.F6/DFS/MS/BP/2014/ 47 dated 31.01.14 issued by this department.
2. Temporary offices are constructed in end of corridor which may make the building smoke logged/ nonventilated and create obstacle to safe escape of the occupants.
3. Electrical shafts are not sealed.
4. Detectors found nonfunctional.
5. MOEFA & PA system found nonfunctional.
6. Lift signages "not to use lift in case of fire" are not provided.

In view of above shortcomings, request for issuance of fire NOC is rejected. There for you are requested to rectify the above shortcomings at the earliest. Further, the occupancy of building /premises, in absence requisite fire & life safety arrangements, shall be at the risk and liability of the owner/occupier. The statutory/licensing authority may take suitable action as deemed fit.

Yours faithfully

(Atul Garg)

DIRECTOR

Delhi Fire Service

Copy to:-

The Chief Architect, NDMC, Palika Kendra, New Delhi.