

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE, NEW DELHI-110001



No: F.6/DFS/MS/School/2025/WZ/ 66 9

Dated: 21/08/2015

To,

The Principal, Utkrisht Vidyalaya (MCD), BB- Block, Shalimar Bagh, Delhi-110088.

Sub: Regarding issuance of Fire Safety Certificate in r/o Utkrisht Vidyalaya (MCD) located at BB- Block, Shalimar Bagh, Delhi- 110088.

Sir,

This has reference to your e mail id dated 23.06.2025 on the subject cited above. In this connection, it is to inform you that the above said assembly hall of school building was inspected by the officer concerned of this department on 17.07.2025 to ascertain the availability and operability of the fire prevention and fire safety measure, Sh. Harinder Singh was present at the time of inspection.

Your request for issuance of FSC is rejected due to the following shortcoming:-

- 1. There are 2 doors of 2.35 m width and 2 doors of 1.75 m width provided against the requirement of 4 doors of 2 m width each.
- 2. First aid hose reel not provided.
- 3. MOEFA not provided.
- 4. Internal hydrant not provided.
- 5. Terrace level pump of 900 lpm discharge capacity not provided.
- 6. Overhead tank of 5,000 ltrs capacity not provided.
- 7. Exit signages not provided.

You are advised to rectify the above-mentioned shortcomings under intimation to this department.

Yours Faithfully

(Virendra Singh) Chief Fire Officer

94 1 -

Copy to:-

1. Director of Education, Govt. of NCT of Delhi, Old Secretariat, New Delhi.