

C/53

**GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI**  
**HEAD QUARTERS: DELHI FIRE SEVRVICE, NEW DELHI-110001**

No. F.6/DFS/MS/2025/SZ/600  
To

Dated: 15/07/2025

The HOS/Vice Principal,  
Veer Chander Singh Garhwali,  
Govt. Sarvodaya BAL Vidyalaya,  
J Block, Saket, New Delhi.

Sub: Regarding renewal of Fire Safety Certificate in r/o M/s Veer Chander Singh Garhwali, Govt. Sarvodaya Bal Vidyalaya, J Block, Saket, New Delhi (ID 1923056)

Sir,

This has reference with your letter no VCSG/SBV/JBLK/SAKET/2025/217 dated 17/06/2025, received though DFS outdoor diary no 2834 dated 18/06/2025 on the subject cited above. In this connection it is to inform you that the above mentioned premise was visited by the officer concerned of this department on 11/07/2025 and observed that the Shortcoming intimated vide letter of even no 115 dated 12/03/2024 not been complied yet. (Copy Enclosed for ready reference).

In view of above observation the application for issuance Fire Safety Certificate is rejected. The occupancy of the building/premises in absence of requisite fire safety arrangements shall be at the risk and liability of the owner/occupier.

Yours faithfully,

(ATUL GARG)  
DIRECTOR  
DELHI FIRE SERVICE

9/11/25

**GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI**  
**HEADQUARTERS: DELHI FIRE SERVICE: CONNAUGHT PLACE**  
**NEW DELHI- 110001**

No. F.6/DFS/MS/School/2024/SZ/115.  
To

Dated: 12/03/2024

The HOS / Vice Principal,  
Veer Chander Singh Garhwali,  
Govt. Sarvodaya BAL Vidyalaya,  
J Block, Saket New Delhi

Sub: Reg. renewal of Fire Safety Certificate in r/o Veer Chander Singh Garhwali, Govt. Sarvodaya BAL Vidyalaya, J Block, Saket New Delhi (ID 1923056)

Sir,

This has reference with your letter no VCSG/SBV/Jblk/Saket/2023/24/93 Dated 22/02/2024 on the subject cited above. In this regard, school premises have been inspected by officer concerned of this department on dated 06.03.2024 in presence of Mr. Manoj Kumar to verify the status of existing fire prevention and fire safety measures. During the course of inspection, the shortcomings observed are as below;

1. Hose reel found non-functional in old block, (ground plus two) & new blocks ground plus three upper floors two blocks in the building.
2. Terrace pumps found non-functional in old block, (ground plus two) & new blocks ground plus three upper floors two blocks in the building

The same observation has already been issued and communicated earlier by this department vide letter of even no 213 dated 16.04.2021 & letter of even no 371 dated 31/08/2023.

In view of above Shortcomings, the application for issuance Fire Safety Certificate is rejected. The occupancy of the building/premises in absence of requisite fire safety arrangements shall be at the risk and liability of the owner/occupier. The Licensing authority/ Statutory Authority may take suitable necessary action as deemed fit.

Yours faithfully,

(ATUL GARG)  
DIRECTOR  
DELHI FIRE SERVICE

Copy to: -

1. The Director of Education, Govt. of NCT of Delhi, Old Secretariat Delhi 110054