0/20



## GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI- 110001



No. F6/DFS/MS/2025/School/NDZ/ 491

Dated: 06 /06/2025

To,

Vidhyanchal Public School, X-Block, Gali No.5, (Near Shiv Mandir), Brahampuri, Delhi-110053.

Subject: - Reg. Fire Safety Certificate in r/o Vidhyanchal Public School located X-Block, Gali No.5, (Near Shiv Mandir), Brahampuri, Delhi-110053.

Sir,

Please refer to your letter outdoor diary No.1210 dated 30/04/2025 on the subject cited above. In this connection, it is to inform you that the site was visited by officer concerned of this department on 23/05/2025 in the presence of Principal and observed that the shortcoming has still not complied with as issued by this department vide letter no. F6/DFS/MS/School/NDZ/2024/379 dated 04/07/2024 (copy overleaf).

In view of above, the application for issuance of Fire Safety Certificate is rejected. The occupancy of the building / premises in absence of requisite fire safety arrangements shall be at the risk and liability of the owner / occupier.

Yours faithfully,

Enclosed: As above

VIRENDRA SINGH CHIEF FIRE OFFICER OCDELHI FIRE SERVICE

Copy to: -

1. The Dy. Director of Education, MCD, Civic Centre, Jawahar Lal Nehru Marg, New Delhi - 110002.



## GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELIII HEADQUARTERS: DELIII FIRE SERVICE: NEW DELIII- 110001

आजारी व अमृत महोत्सव

No. F6/DFS/MS/School/NDZ/2024/ 379

Dated: 04/07/2024

To.

Mr. Mahesh Bhatt (Manager), Vidhyanchal Public School X-79, Gali No. 5, Near Shiv Mandir, Brahmpuri, Delhi – 110053.

Subject: - Regarding grant of Fire Safety Certificate in r/o Vidhyanchal Public School located at X-79, Gali No. 5, Near Shiv Mandir, Brahmpuri. Delhi – 110053.

Sir,

This has a reference to your email dated 12/06/2024, on the subject cited above. In this connection, it is to inform you that premises was inspected by the officer concerned of this department on 24/06/2024 in the presence of Mr. Mahesh Bhatt (Manager), and observed that building comprised of ground plus two upper floors only.

Following shortcomings were observed during time of inspection:

- 1. One staircases of width 1.10 meter is provided against the requirement of two having width of 1.50 meters each.
- 2. The width of corridor is 0.75 meter against the requirement of 1.50 meters.
- 3. The class room door size is 0.85 meter against the requirement of 1.20 meter.
- 4. All fire extinguishers found empty.
- 5. First-Aid-Hose Reel not provided.
- 6. Fire pump of 450 LPM not provided.
- 7. Overhead tank of capacity 10,000 liters not provided.
- 8. Exit signage's not provided in strategic location in the building.

In view of above shortcomings, the application for issuance for Fire Safety Certificate is rejected. The occupancy of the building/premises in absence of requisite fire safety arrangements shall be at the risk and liability of the management. The Authority/Statutory Authority may take suitable necessary action as deemed fit.

Yours faithfully,

DIRECTOR

OC DELHI FIRE SERVICE

Copy to:-

1. The Dy. Director of Education, B - Block, Yamuna Vihar, Delhi - 110053.