

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: NEW DLEHI - 110 001 F.6/DFS/MS/Motel/2025/SZ/ 2 Q 4 Dated: 03 / 06 / 2025

No. F.6/DFS/MS/Motel/2025/SZ/ 2 84

FIRE SAFETY CERTIFICATE

Certified that the M/s Vista Motel located at 162, M. G Road New Delhi - 110030 comprised of Basement (Closed with brick wall), Ground floor & One upper floor owned/occupied by M/s Vista Hospitality Pvt. Ltd was issued FSC by this department vide letter F6/DFS/MS/Motel/SZ/2021/341 Dated 22/07/2021. The premise was re-inspected by the officer concerned of this department on 21/05/2025 in the presence of Mr. Prem Sharma (Account) and found to have deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010and that the building is fit for occupancy Group A "Residential (Motel) Building" with effect 03/06/2025 for a period of three years in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule-38 of the Delhi Fire Service Rules, 2010.

Issued on. O.3. f.a. 6. 1/2025 at New Delhi by

CHIEF FIRE OFFICER **DELHI FIRE SERVICE**

de

Copy to:-

1. The Joint Commissioner of Police (Lic.) 1st Floor, P.S. Defence Colony, New Delhi- 49

2. Mr. Rohan Sharma, M/s Vista Hospitality Pvt. Ltd at 162, M. G Road New Delhi -30

Conditions for the validity of fire safety certificate:

1. All the means of escape/entry/exit shall be kept free from any obstruction.

2. All the fire safety arrangements provided therein shall be maintained in good working condition at all time as seen during inspection. Any loss of life or property due to nonfunctional fire safety measures shall be at the responsibility of the management.

3. All the staff members must know the correct method of operation of firefighting system.

4. The owner/ occupier shall submit a declaration every year in Form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in.

5. This fire safety certificate may not in any way be treated as regularization of unauthorized construction, if any.

6. "The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in Form 'J' [sub rule (1) of rule 37] along with a copy of this Certificate, six months prior



Name & address of the building

INSPECTION REPORT

Vista Motel, (M/s Vista Hospitality Pvt. Ltd) 162, M. G Road,

Type of Occupancy 2. Type of Case 3.

: Group A "Residential" (Motel) Building

Comprised of 5. Details of Previous NOC

: Basement (Closed with brick wall), Ground + 01 Upper Floor : F6/DFS/MS/Motel/SZ/2021/341 Dated 22/07/2021 : F6/DFS/MS/GH/BP/2002/1042 Dated 02/07/2002

6. Fire Safety directives letter No 7. Date of inspection

: ADO (BCP)

8. Name of Inspecting Officer 9. Name and designation of officers

: Mr. Prem Sharma (Account)

From the building side 10. Year of Construction 11. Applicant's letter No

: outdoor diary no 1542 dated 13/05/2025

| S. No. | Minimum Standards on fire prevention and fire safety U/R 33 | BBL/NBC Requirement | Provided at site | Remarks | | |
|-----------|---|--|--------------------------|---------|--|--|
| 1. | Access to building | -rodan ement | | MR/NMR | | |
| | Road width | 9m | | - CONTR | | |
| . 1 | Gate width | 5m | Provided | MR | | |
| | Width of internal road | NΔ | Provided NA | MR | | |
| 2. | Number, Width, Type & Arrangement of Ex | its | INA | NA | | |
| | a. Number of staircases | | | | | |
| | Upper Floors | 02 Nos | Dept. 1 | | | |
| 70 | Basements | -NA- | Provided | MR | | |
| | SREA DESCRIPTION DE LA COST | -114- | (Basement closed | -NA- | | |
| | b. Width of staircases | | | | | |
| | Upper Floor | 1.50 mtr | 1.50 mtr each | 100 | | |
| | a Posamonta | -NA- | (Basement closed | MR | | |
| | | amages | with brick wall | -NA- | | |
| | c. Protection of exits | | | | | |
| | Fire check door | -NA- | -NA- | -NA- | | |
| | Pressurization | -NA- | -NA- | -NA- | | |
| | d. No. of continuous staircases to terrace | 02 | Provided | MR | | |
| | e. Width of Corridor | 1.50 mtr | Provided | MR | | |
| | f. Door Size | lm | Provided | MR | | |
| 3. | Compartmentation MR | | | | | |
| | Fire check door | -NA- | -NA- | -NA- | | |
| | Sealing of electrical shafts | -NA- | -NA- | -NA- | | |
| | Fire Rating of shaft door Water Curtain | Required | Provided | MR | | |
| | Fire Dampers | -NA- | -NA- | NA- | | |
| | Since Painpers | -NA- | -NA- | -NA- | | |
| 4. | Smoke Management System | | | | | |
| | Basements | Required | Provided | MR | | |
| | Upper floors | -NA- | -NA- | -NA- | | |
| 5. | Fire Extinguishers | | THE THE PERSON NAMED | | | |
| | Total numbers | | | MR | | |
| | Types | ABC/W.Co ₂ /Co ₂ | Provided 15/15/12 Nos | MR | | |
| | IS marking | ISI | Yes | MR | | |
| 6. | First-Aid Hose Reels | | | | | |
| | Total numbers on each floor | Required | Provided | MR | | |
| * | Length of hose reel hose | 30m | Provided | MR | | |
| | Nozzle diameter | 5mm | Provided | MR | | |
| 7. | Automatic fire detection and alarming system | | | | | |
| | Type of detectors | Co. Mo. Det. | Provided | MR | | |

| Α | 22 |
|---|-----|
| M | 121 |

आज़ादी अमृत

| | | $W_{1,2,1}$ | | |
|-----|---|------------------|--|----------|
| | Location of Main Panel | Required | Ground Floor | MR |
| | Location of Repeater Panel | -NA- | -NA- | NA |
| | Alternate source of power | Required | Provided | MR |
| - | Hooters' Location | Required | All Floors | |
| _ | B. MOEFA | Required | Provided | MR |
| | O. Public Address System | Required | Provided | MR |
| 1 | 10. Automatic Sprinkler System | required | riovided | MR |
| | Basement Upper Floors | | Basement closed with brick wall) | -NA- |
| | Sprinkler above false ceiling | Required | Provided | MR |
| _1 | 11. Internal Hydrants | -NA- | -NA- | -NA- |
| | Size of riser/down-comer | phe phe | | |
| | Number of hydrants per floor | 100mm | Provided | MR |
| _ | Hose Box | 02 Nos | Provided | MR |
| 1 | 2. Yard Hydrants | 02 Nos | Provided | MR |
| | Total number of hydrants | 11121 | ' ' ' ' ' ' ' ' ' ' ' ' ' ' ' ' ' ' ' | 7 10 10 |
| - | 110SE BOY | Required | Provided | MR |
| 1 | 3. Pumping Arrangements | Required | Provided | MR |
| | Ground Level | | | MK |
| | Discharge of main Power | ette I by become | | |
| | riedd of Main nume | 2280 LPM | Provided | MP |
| | Number of main num | 60m | Provided | MR |
| | Jockey Pump out rus | One | Provided | MR |
| | Jockey pump head | 180 LPM | Provided | MR |
| | Standby Pump out - | 60m | Provided | MR |
| | Standby Pump Head | 2280 LPM | Control of the contro | MR |
| | Auto Starting/Manual Cana | 60m | Provided | MR |
| | Pump House Access | Required | Provided | MR |
| | Terrace level | Required | Provided | MR |
| | Discharge of pump | quited | Provided | MR |
| | 11cad of the man | -NA- | | |
| | Power Supply | -NA- | -NA- | -NA- |
| | Auto Starting of pump | -NA- | -NA- | -NA- |
| 4. | | -NA- | -NA- | -NA- |
| 0.7 | Captive Water Storage for fire fighting | | - 11/1- | -NA- |
| | Underground tank capacity | 100 | tech Je I | Total F |
| | Draw-off connection | 1,00,000 Ltrs | Provided | MR |
| | | Required | Provided | |
| ľ | The service inlet | Required | Provided | MR |
| | Access to tank Overhead Tonk | Required | Provided | MR |
| 5. | Overhead Tank capacity Exit Signage. | 10,000 Ltrs | Provided | MR MR |
| 5. | Provision of Lifts. | Required | Provided | MR |
| T. | | | Flovided | MR |
| | Pressurization of Lift Shaft | -NA- | | |
| | Pressurization of Lift lobby | | -NA- | -NA- |
| | • Communication In lift Car | -NA- | -NA- | -NA- |
| | • Fireman's Grounding Switch | -NA- | Provided | -NA- |
| | Lift Signage | -NA- | Provided | -NA- |
| | C. II | -NA- | Provided | |
| | Standby power supply | Required | | -NA- |
| | Refuge Area. | required | Provided | MR |
| | Total Area | 3 | | |
| - 1 | > Location | -NA- | -NA- | -NA- |
| | Location | -NA- | -NA- | T 47 Z |

| | | | | 75- | | | | | | |
|--|--|---------------------|--------------------|---------------------------------------|--|--|--|--|--|--|
| A | | | W/38 | आज़ादी ^{ग्य} अमृत महोत्सव | | | | | | |
| State of the state | Arm Panel | -NA- | -NA- | -NA- | | | | | | |
| 18 | Detector System Panel Spritch Panel | -NA- | -NA- | -NA- | | | | | | |
| MR | Detector System Flow Switch Panel Flow Sam Panel | -NA- | -NA- | -NA- | | | | | | |
| NA. | PA System 1 | -NA- | -NA- | -NA- | | | | | | |
| IR. | - HOTY DACKET | -NA- | -NA- | -NA- | | | | | | |
| R. | Building 1 Too | of special Risks, i | f any: | -NA- | | | | | | |
| J in | Caratam for Protection of Spotting | | | | | | | | | |
| Special | tion system provided in | n the building | were randomly | checked and found | | | | | | |
| The | The fire protection system provided in the building were randomly checked and found The fire protection system provided in the building were randomly checked and found The fire protection system provided in the building were randomly checked and found The fire protection system provided in the building were randomly checked and found The fire protection system provided in the building were randomly checked and found The fire protection system provided in the building were randomly checked and found The fire protection system provided in the building were randomly checked and found The fire protection system provided in the building were randomly checked and found The fire protection system provided in the building were randomly checked and found The fire protection system provided in the building were randomly checked and found The fire protection system provided in the building were randomly checked and found The fire protection system provided in the building were randomly checked and found The fire protection system provided in the building were randomly checked and found The fire protection system provided in the building were randomly checked and found The fire protection system provided in the building were randomly checked and found The fire protection system provided in the building were randomly checked and found The fire protection system provided in the building were randomly checked and found The fire protection system provided in the building were randomly checked and found The fire protection system provided in the building were randomly checked and found The fire protection system provided in the building were randomly checked and found The fire protection system provided in the building were randomly checked and found The fire protection system provided in the building were randomly checked and found The fire protection system provided in the building were randomly checked and found The fire protection system provided in the building were randomly checked and found The fi | | | | | | | | | |
| v ctional | at the management has complied | von no 212 date | d 07/05/2025. | | | | | | | |
| 7 | that this ucbaract | | | | | | | | | |
| communica | arther, the management has compared in the partner, the management wide letter of ented by this department vide letter of ented by this department vide letter of ented by measures as required under measures as required under measures as required 22/07/2021, 1/2007/ | the rules, t | he FSC issued | l vide letter no | | | | | | |
| safet | measures as required 22/07/2021, 1 | renewal under ri | ile 37 of the Deir | A | | | | | | |
| fire Salva | /Motel/SZ/2021/341 Dated == | 1 : ture nle | ease. | 1.06 | | | | | | |
| 2010 is reco | ordingly, DFA is put up for approval a | and signature pro | ,430. | 26/2/2015 | | | | | | |
| Acc | ordingly, Direct | | 0.1 | | | | | | | |
| | No. | | Signature of the | ne Inspecting Officer Rajesh Kumar | | | | | | |
| | | | Name: Sii. | : ADO (BCP) | | | | | | |
| | | | Design | | | | | | | |
| | . 1 | | Ē. | | | | | | | |
| 1 | Imiller, mis | | | | | | | | | |
| DO (South) | 11100 160 ps | | | | | | | | | |
| DO | 1 // | | | | | | | | | |
| l | Mulerusps Gol (Mas) Mugh | | | | | | | | | |
| | (Ray (Mas) III | | | | | | | | | |
| | 30 51 Sav | | | | | | | | | |
| | 1 -1 -1 -1 | | | | | | | | | |
| | 3015/() | 2 | | | | | | | | |
| | / V | | | | | | | | | |
| | DO (South) | | | | | | | | | |
| | De (South) M | Wyloho | | | | | | | | |
| | | -01 | * | | | | | | | |
| | | | | | | | | | | |
| | Dog BURI | | | · b but | | | | | | |
| | As opposed. | | 1 Alex | y francis | | | | | | |
| | | F.T. | fence | , | | | | | | |
| | As oppositely | rature 6 | 11 | · 1/1 | | | | | | |
| | 100 | rature 6 | <i>,</i> . | (<u>Al</u> | | | | | | |
| | der your | | | 3/8 | | | | | | |
| | 4. 2 | | | | | | | | | |
| | ~ | | | | | | | | | |
| | 0/- 1/- 1/- 8 | / | | | | | | | | |
| | CG M2 Mug | | | 1 (40 | | | | | | |
| | CF 1/12 Must | Sors | | | | | | | | |
| | 1 2 | | | Water and | | | | | | |
| | | | | | | | | | | |
| | 1 mscell | | | | | | | | | |
| | | | | | | | | | | |