GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: CONNAUGHT PLACE NEW DELHI-110 001.

No. F.6/DFS/MS/School/2025/SZ/ 1142

Dated: 16/09/2025

FIRE SAFETY CERTIFICATE

Certified that the Vivekanand Internatinal School located at Haibatpura, Najafgarh, New Delhi- 110043, building comprised of ground floor only, owned/occupied by Vivekanand Internatinal School. The school building was inspected by the officer concerned of this department on dated 11.09.2025 in the presence of Smt. Kokindra Devi (Headmistress), and found that the school building have complied with the fire prevention and fire safety requirements in accordance with the fire prevention and fire safety requirements in accordance with Rule 33 of the Delhi Fire Service Rules, 2010 and that the building/ premises (ground floor only) is fit for occupancy class B "Educational Building" with effect from 16 0 9 2025 for a period of three years in accordance with the Rule 36 unless renewed under Rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under Rule 38 of the Delhi Fire Service Rules, 2010, printed below. 16191201

Issued on 16 0 9 2025 at New Delhi.

(Virendra Singh) Chief Fire Officer %en_

Copy to:-

1. Director of Education, Govt. of NCT of Delhi, Old Secretariat, New Delhi - 110054.

2. The Headmistress, Vivekanand Internatinal School at Haibatpura, Najafgarh, New Delhi- 43.

Conditions for validity of fire safety certificate: -

- 1. All the fire safety arrangements provided therein shall be maintained in good working condition at all times.
- 2. The means of escape shall be kept unlocked and unobstructed for unhindered evacuation of occupants in case of emergency.
- 3. Any loss of life or property due to non-functional fire safety measures shall be at the risk and responsibility of the management.
- 4. The trained staff should be available round the clock.
- 5. Any deviations w.r.t. construction shall be verified by the concerned building sanctioning
- 6. The certificate may not be treated in any case for the regularization of the unauthorized construction, if any.
- 7. The owner/occupier shall submit a declaration every year in the form 'K' provided in the Fire Service Rules 2010, form is available first schedule of Delhi www.dfs.delhigovt.nic.in.
- 8. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in the Form 'J' [sub rule (1) of rule 37] along with a copy of this Certificate, six months prior to its expiry.

.. 1

INSPECTION REPORT

1. Name & address of the building

Vivekanand International School at Haibatpura, Najafgarh, New

Delhi- 110043

2. Building is comprised of

Ground floor only

3. Type of Occupancy

Educational

4. Type of Case

New Case

5. Details of Previous FSC

6. Fire Safety directives letter No

N/A

7. Date of inspection

N/A

8. Name of Inspecting Officer

11.09.2025 A.D.O. R.K. Yadav

9. Name and designation of officers

From the building side

Smt. Kokindra Devi (Headmistress)

10. Year of Construction

2020-21

S. No.	"Annual Standards on 6mg	VIS/2025-26/CFS/0	Provided at site				
1.	Surety O/R 33	1 smont	1 Tovided at site	Remarks MR/NMR			
	Access to building						
	 Road width 	Accessible 06 m					
	 Gate width 	4.5 m	06 m Directly accessible from road	MR			
	 Width of internal road 	N/A	N/A	MR			
2.	Number, Width, Type & Arrangement o	f Fyite		N/A			
	a. Number of staircases						
	• Upper Floors		School running at	GF only			
	Basements	N/A	N/A	N/A			
	b. Width of staircases	N/A	N/A	N/A			
	• Upper Floor			IVA			
	Basements	N/A	N/A	27/4			
	c. Protection of exits	N/A	N/A	N/A N/A			
	Fire check door		100005	IN/A			
	Pressurization	N/A	N/A				
		N/A	N/A	N/A			
	d. No. of continuous staircases to terrace	N/A	N/A	N/A			
	e. Width of Corridor		IVA	N/A			
	f. Door Size	N/A	N/A	27/4			
		1.20 m	Provided	N/A			
3.	Compartmentation			MR			
	Fire check door						
	Sealing of electrical shafts	N/A	N/A				
	Fire Rating of shaft door	N/A	N/A	N/A			
	Water Curtain	N/A	-0.0 W/NW	N/A			
1	• Fire Dampers	N/A	N/A	N/A			
1.		N/A	N/A	N/A			
•	Smoke Management System	13/11	N/A	N/A			
	Basements	0.00					
	Upper floors	N/A	N/A				
i.		Required	Natural ventilation provided	N/A			
	Fire Extinguishers		provided	MR			
	Total numbers	00					
	• Types	08 no's ABC/CO ₂ type	Provided) m			
	IS marking	ISI marked	Provided	MR			
	First-Aid Hose Reels	-Si marked	Provided	MR MR			
	Total numbers on each floor		School running a				
	Length of hose reel hose	N/A					
	Nozzle diameter	N/A	N/A	N/A			
1	- Annotoj	N/A	N/A	N/A			
4			N/A	N/A			

7.	Automatic fire detection and alarming		27/4			
	Type of detectors	N/A	N/A	N/		
	Location of Main Panel	N/A	N/A	N/		
	Location of Repeater Panel	N/A	N/A	N/		
	 Alternate source of power Hooters' Location 	N/A	N/A	N/.		
	TO THE PARTY OF TH	N/A	N/A	N/		
8.	MOEFA	N/A	N/A	N/A		
9.	Public Address System	N/A	N/A	N/A		
10.	Automatic Sprinkler System					
	Basement	N/A	N/A	N/A		
	Ground Floor	N/A	N/A	N/A		
	Sprinkler above false ceiling	N/A	N/A	N/A		
11.	Internal Hydrants					
	Size of riser/down-comer	N/A	N/A	N/A		
	 Number of hydrants per floor 	N/A	N/A	N/A		
	Hose Box	N/A	N/A	N/A		
12.	Yard Hydrants					
	Total number of hydrants	N/A	N/A	N/A		
	Hose Box	N/A	N/A	N/A		
13.	Pumping Arrangements School running at GF on					
	Ground Level					
	Discharge of main Pump	N/A	N/A	N/A		
	➤ Head of Main pump	N/A	N/A	N/A		
	Number of main pumps	N/A	N/A	N/A		
	Jockey Pump out put	N/A	N/A	N/A		
	> Jockey pump head	N/A	N/A	551.005.059		
	Standby Pump out put	N/A	N/A	N/A		
	Standby Pump HeadAuto Starting/Manual	N/A	N/A	N/A		
	Stopping	N/A	N/A N/A	N/A N/A		
		7930771000	1471	N/A		
	 Pump House Access Terrace level 	N/A	N/A	N/A		
	- isonai ge of pump	N/A	N/A	N/A		
	➢ Head of the pump➢ Power Supply	N/A	N/A	N/A		
	> Auto Starting of pump	N/A	N/A	N/A		
14.	547 380 47	N/A	N/A	N/A		
4.	Captive Water Storage for fire-fighting	+	School running	at GF onl		
	 Underground tank capacity Draw-off connection 	N/A	N/A	N/A		
	Fire service inlet	N/A	N/A	N/A		
	Access to tank	N/A	N/A	N/A		
	Overhead Tank capacity	N/A	N/A	N/A		
5.	Exit Signage.	N/A	N/A	N/A		
6.	Provision of Lifts.	N/A	N/A	N/A		
0.	Control tempore Manager Brown Company Control		(No Lift)			
	Pressurization of Lift Shaft	N/A	N/A			
	Pressurization of Lift lobby	N/A		N/A		
	Communication In lift Car	N/A	N/A N/A	N/A		
	Fireman's Grounding Switch	N/A	N/A	N/A		
	Lift Signage	N/A	N/A N/A	N/A		
			1VA	N/A		

17.	Standby power supply					
	\$2,455,178	N/A	N/A	NI		
18.	Refuge Area.			N/A		
	> Total Area					
	> Location	N/A	N/A	N/A		
19.	Fire Control Room	N/A	N/A	N/A N/A		
	Detector System PanelFlow Switch Panel	N/A	N/A	N/A		
	Flow Switch PanelPA System Panel	N/A	N/A N/A	N/A N/A		
	 Flow Switch Panel PA System Panel Battery backup 	N/A N/A				
	Flow Switch PanelPA System Panel	N/A	N/A	N/A N/A		
20.	 Flow Switch Panel PA System Panel Battery backup 	N/A N/A	N/A N/A	N/A		

The fire protection systems provided in the building were test checked and found not functional at the time of inspection.

Keeping in view of the above compliance of the minimum standards of fire prevention and fire safety measures under Rule 35 of the Delhi Fire Service Rules 2010, it's recommended to grant Fire Safety Certificate.

Signature of the Inspecting

Name- R.K. Yadav Designation- ADO (JKP)