## **GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE, CONNAUGHT PLACE NEW DELHI- 110001**

No. F.6/DFS/MS/GH/2025/SZ/ 12.3

10/03/2025 Dated:

## FIRE SAFETY CERTIFICATE

Certified that the M/s Western Blu Guest House located at Property No. A-7, Shubham Enclave, Paschim Vihar, , New Delhi- 110063, running at upper ground floor (05 guest rooms), 1st floor (04 guest rooms) & 2<sup>nd</sup> floor only (04 guest rooms) in a building comprised of basement, stilt, upper ground plus two upper floors (total 13 guest rooms only), was issued FSC by this department vide letter No. F.6/DFS/MS/GH/2022/WZ/318 dated 01.07.2022. The premises was re-inspected by the officer concerned of this department on dated 21.02.2025 in the presence of Sh. Hemant Khurana (Occupier), and found that the guest house have deemed complied with the fire prevention and fire safety requirements in accordance with Rule 33 of the Delhi fire service Rules 2010 and that the building/premises is fit for occupancy class "Residential" (Guest house) (13 guest rooms only at upper ground, 1st & 2nd floor) w.e.f. 10 03 2025 for a period of three years in accordance with Rule 36 unless renewed under Rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under Rule-38 of the Delhi Fire Service Rules, 2010 printed below.

10 03 12025 at New Delhi.

Copy to: -

1 The Commissioner, MCD, Delhi: to ensure the occupancy as detailed above and deviation,

2 Online application Id 2025021101701 dated 11.02.2025.

3 The Executive Engineer (Bldg.), MCD, Civic Centre, New Delhi.

: - for information regarding use of basement.

## Conditions for the validity of fire safety certificate: -

- 1. All the fire safety arrangements provided therein shall be maintained in good working condition at all times.
- 2. The means of escape arrangements shall be kept unlocked & unobstructed for speedy evacuation of occupants in case of an emergency.
- 3. Any loss of life or property due to non-functional fire safety measures shall be at the risk and responsibility of the management.
- 4. The trained staff should be available round the clock.
- 5. Any deviations w.r.t. construction shall be verified by the concerned building sanctioning agency.
- 6. The certificate may not be treated in any case for the regularization of the unauthorized construction, if any.
- 7. Basement shall be used as per the building bye laws.
- 8. The owner/occupier shall submit a declaration every year in the form 'K' provided in the first schedule of Delhi Fire Service Rules 2010, form is available on www.dfs.delhigovt.nic.in.
- 9. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in the Form 'J' [sub rule (1) of rule 37] along with a copy of this Certificate, six months prior to its expiry.

## INSPECTION REPORT

Name & address of the building

: M/s. Western Blu Guest House at Property No. A-7, Shubham

Enclave, Paschim Vihar, New Delhi- 110063.

2. Building is comprised of

: B, Stilt, Upper ground plus two upper floors but guest house running at

upper ground, 1st & 2nd floor only.

Type of Occupancy

: Residential (Guest House)

4. Type of Case

Renewal

: F.6/DFS/MS/GH/2022/WZ/318 dated 01.07.2022

5. Details of Previous FSC letter 6. Fire Safety direction letter No

: N/A

7. Date of Inspection

: 21.02.2025

8. Name of the Inspecting officers

: ADO R.K. Yadav (JKP)

9. Name and designation of officer

from the building side

: Sh. Hemant Khurana (Owner/Occupier)

10. Year of construction

2020

11 Applicant's letter No

ID No. 2025021101701 dated 11.02.2025

Sr. No.	Minimum Standards on Fire Prevention and Fire Safety U/R33	Requirement	Provided at Site	Remarks MR/NMR		
1	Access to Building.					
	Road width Gate width Width of internal road	6.0 m	Provided	MR		
		4.5 m	Direct accessible from road	MR		
		N/A	N/A	N/A		
2	Number, Width, Type and Arrange	1				
	a. Number of Staircases			) (D		
	Upper floor	02 Nos.	02 Nos.	MR		
	Basement	02 Nos.	02 Nos.	MR		
	B. Width of Staircases		2 11 1	MR		
	Upper floor	1.50 m each	Provided	THE CASE		
	Basement	1.50 m each	Provided	MR		
	c. Protection of Exits	· · · · · · · · · · · · · · · · · · ·	7-	N/A M		
	Fire check door	Required (	N/A Prantish	N/A		
	<ul> <li>Pressurization</li> </ul>	N/A	N/A	MR		
	d. No. of Continuous Staircases to Terrace	02 no's	02 no's			
	e. Width of Corridor	1.8 m	Provided	MR		
	f. Door Size	1.0 m	Provided	MR		
	Compartmentation.					
	Fire check door	N/A	Provided	N/A		
	Sealing of electrical shafts	N/A	N/A	N/A		
	Fire rating of shaft door	N/A	N/A	N/A		
	Water curtain	N/A	N/A	N/A		
	Fire dampers	N/A	N/A	N/A		
1	Smoke Management System.					
	D	30 ACPH	Provided	MR		
	Basement Upper floor	12 ACPH	Provided	MR		
•	Fire Extinguishers.					
	Total numbers	12 nos.	Provided	MR		
	Types	ABC /CO <sub>2</sub>	Provided	MR		
	IS marking	ISI marked	Provided	MR		



1
1

06	First-Aid-Hose Reels.				
	Total numbers on each floor	01 No	Provided	M M	
	Length of hose reel hose	30 m	Provided	M M	
	Nozzle diameter	05 mm	Provided	MI	
07	Automatic Fire Detection, CO detection and Alarming System.				
		Carbon Monoxide	Provided	MF	
	<ul> <li>CO Type of detectors</li> <li>Location of main panel</li> </ul>	Required	Provided at GF	MF	
	Location of main paner     Location of repeater panel	Required	Provided	MR	
	Alternate source of power	Required	Provided	MR	
	Hooter's location	Required	Provided	MR	
08	MOEFA	Required	Provided	MR	
09	Public Address System.	N/A	N/A	N/A	
10	Automatic Sprinkler System.				
	Basement & Stilt	Required	Provided	MR	
	upper floor	N/A	N/A	N/A	
	sprinkler above false ceiling	N/A	N/A	N/A	
11	Internal Hydrants				
	size of riser/down-comer	100 mm	100 mm	MR	
	Number of hydrants per floor	01	01	MR	
	Hose box	01	01	MR	
12	Yard Hydrants.				
	Total number of hydrants	N/A	N/A	N/A	
	Hose box	N/A	N/A	N/A	
13	Pumping Arrangements.				
	> Ground Level				
	Discharge of main pump				
25/1	Head of main pump	N/A	N/A	N/A	
	Number of main pumps	N/A	N/A	N/A	
	Jockey pump out put	N/A	N/A	N/A	
- 1	Jockey pump head     Standburger	N/A	N/A	N/A	
	Standby pump out put     Standby pump head	N/A N/A	N/A	N/A	
	Auto starting /manual	N/A N/A	N/A	N/A	
	stopping	N/A	N/A N/A	N/A	
	<ul> <li>Pump house access</li> </ul>	e.m.e.b	17/A	N/A	
	> Terrace Level				
	Discharge of pump	450 LPM	450 LPM	MR	
	<ul><li>Head of the pump</li><li>Power supply</li></ul>	40 m	40 m	MR	
	Auto Starting of pump	Required Required	Provided Provided	MR MR	
1	Captive Water Storage for Fire Fightin			AMIX	
-	Underground tank capacity	N/A	NT/A		
	Draw-off connection	N/A	N/A	N/A	
		N/A N/A	N/A N/A	N/A	
	Fire service inlet		IV/A	N/A	
	Fire service inlet     Access to tank				
	Access to tank     Overhead Tank capacity	N/A 15,000 ltrs	N/A 15,000 ltrs	N/A MR	



	Provision of Lifts.			Y 4 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1		
	1	Pressurization of Lift Shaft	N/A	N/A	N/A	
		Pressurization of Lift lobby	N/A	N/A	N/A	
		Communication in lift car	N/A	N/A	N/A	
		Firemen's grounding switch	N/A	N/A	N/A	
		Lift Signage	N/A	N/A	N/A	
17	Stand	by power supply	Required	Provided	MR	
18	Refuge Area.					
	•	Total area	N/A	N/A	N/A	
		Location	N/A	N/A	N/A	
19	Fire Control Room					
		Detector system panel	N/A	N/A	N/A	
		Flow switch panel	N/A	N/A	N/A	
		PA system panel	N/A	N/A	N/A	
		Battery backup	N/A	N/A	N/A	
		Building Floor Plans	N/A	N/A	N/A	
20		Fire Protection systems for ion of special Risks, if any:	Required	ABC typer Fire Ext. provided near elect. panel	MR	

The fire protection systems provided in the building were tested, checked and found functional at the time of inspection.

Note: - The guest house running at upper ground floor, first floor & second floor only in building comprised of basement, stilt, upper ground floor, first floor & second floor.

In view of the deemed compliance of the minimum standards of fire prevention and fire safety measures as required under the rules the FSC issued vide letter No. F.6/DFS/MS/GH/2022/WZ/318 dated 01.07.2022, renewal under rule 37 of the Delhi Fire Service Rules 2010 is recommended.

Signature of Inspecting

Name: - R.K. Yadav Designation: - ADO (JKP)

please Check fui Check door in stairerse previous inspection report & purup accord

DCF0/550-MA