

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: CONNAUGHT PLACE NEW DELHI-110 001.

No.F.6/DFS/MS/BNQT./2025/SZ/39

Dated: 25/06/2025

FIRE SAFETY CERTIFICATE

Certified that the M/s Amora Banquet Hall, running at ground & first floor in a building comprised of basement, ground plus three upper floors, using basement as storage, second & third floor (guest house), located at Khasra No. 72/6/1, Plot No. 2, Data Ram Marg, Palam Extension, New Delhi- 110045, owned/occupied by Amora Banquet Hall, was issued FSC by this department vide letter No. F.6/DFS/MS/SZ/2022/BNQT./28 dated 13.06.2022. The premises was re-inspected by the officer concerned of this department on dated 11.06.2025 in the presence of Sh. Vijender Solanki, and found that the banquet hall buildinghave deemed complied with the fire prevention and fire safety requirements in accordance with Rule 33 of the Delhi Fire Service Rules, 2010 and that the banquet hall building/premises (ground and first floor only) is fit for occupancy class Group "D" Assembly Building" w.e.f. 25/06/2015 for a period of three years in accordance with Rule 36 unless renewed under Rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under Rule-38 of the Delhi Fire Service Rules, 2010 printed below.

Issued on 95/06/2025 at New Delhi.

Delki Fire Service

Copy to: -

- 1 The Commissioner, MCD, Delhi: for information regarding use of basement and to ensure theoccupancy as detailed above and deviation, if any.
- 2. Online application Id 2025050808105 dated 04.06.2025.

Conditions for validity of Fire Safety Certificate: -

- 1. This FSC is valid only for ground & first floor.
- 2. All the fire safety arrangements provided therein shall be maintained in good working condition at all times.
- 3. The means of escape arrangements shall be kept unlocked & unobstructed for speedy evacuation of occupants in case of an emergency.
- 4. Any loss of life or property due to non-functional fire safety measures shall be at the risk and responsibility of the management.
- 5. The trained staff should be available round the clock.
- 6. Any deviations w.r.t. construction shall be verified by the concerned building sanctioning agency.
- 7. The certificate may not be treated in any case for the regularization of the unauthorized construction, if any.
- 8. Basement shall be used as per BBL/UBBL.
- 9. The owner/occupier shall submit a declaration every year in the form 'K' provided in the first schedule of Delhi Fire Service Rules 2010, form is available on www.dfs.delhigovt.nic.in.
- 10. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in the Form 'J' [sub rule (1) of rule 37] along with a copy of this Certificate, six months prior to its expiry.

INSPECTION REPORT

Name & address of the building: M/s Amora Banquet at ground and first floor, Kh. No. 72/6/1, Plot

No. 2, Data Ram Marg, Palam Extension, New Delhi.

Building is comprised of Basement, ground plus three upper floors.

Assembly (Banquet running at Ground and First Floor Only) Type of Occupancy

Type of Case Renewal

4. 5. Details of Previous NOC F.6/DFS/MS/SZ/2022/BNQT./28 dated 13.06.2022 Fire Safety directives letter No : F.6/DFS/BP/2020/BNQT/2497 dated 14.10.2020

Date of inspection 11.06.2025

8. Name of Inspecting Officer R.K. Yadav, ADO (JKP)

Name and designation of officers

Sh. Vijender Solanki From the building side

2017 10. Year of Constructi on

Online MHA Id 2025050808105 dated 04.06.2025 11 Applicant's letter No.

).	Minimum Standards on fire prevention and fire safety U/R 33	Requirements as per UBBL/NBC-2016	Provided at site	Remarks MR/NMF	
-	Access to building		N. S.		
	Road width	09 m	18 m	M/R	
	Gate width	05 m	On Road	MR	
	 Width of internal road 	N/A	N/A	N/A	
	Number, Width, Type & Arrangement of	of Exits			
	a. Number of staircases				
	Upper Floors	Two	Two	M/R	
	Basements	Two	Two	M/R	
	b. Width of staircases				
		2.0 & 1.50 m	2.0 & 1.50 m	M/R	
	Upper Floor	2.0 & 1.50 m	2.0 & 1.50 m	M/R	
	Basements	2.0 & 1.50 m			
	c. Protection of exits	Required	Provided	MR	
	Fire check door	N/A	N/A	N/A	
	Pressurization	N/A	IVA		
	d. No. of continuous staircases to	Required	Provided	M/R	
	terrace	N/A	1.47 m	N/A	
	e. Width of Corridor	2.0 & 1.5 m	GF = 2.0 & 2.40 m	MR	
	f. Door Size	2.0 & 1.5 111	FF = 2.0 m & 1.50 m		
3.	Compartmentation		1 . 1		
	Fire check door	Required in basement	Provided	MR	
	Sealing of electrical shafts	N/A	N/A	N/A	
	Fire Rating of shaft door	N/A	N/A	N/A	
	Water Curtain	N/A	N/A	N/A	
	• Fire Dampers	N/A	N/A	N/A	
4.	Smoke Management System				
	30000000000000000000000000000000000000	Required	Provided	MR	
	Basements Upper floors	Required	Provided	MR	
5.	Fire Extinguishers				
٥.		15 no.'s	Provided	M/R	
	Total numbers	W/CO ₂ / CO ₂ type	Provided	M/R	
	TypesIS marking	ISI marked	ISI marked	M/R	
6.	First-Aid Hose Reels				
	Total numbers on each floor	01	01	M/R M/R	
	• Length of hose reel hose	30 m	30 m	M/R M/R	
	Nozzle diameter	5 mm	5 mm	IVI/K	

Ris

		19/23					
7.	Automatic Fire Detection, CO detection and Alarming System.						
	CO Type of detectors	Required	Provided	M/F			
	Location of Main Panel	Required	Ground Floor	MR			
	Location of Repeater Panel	Required	Provided	MR			
	Alternate source of power	Required	Provided	M/F			
	Hooters' Location	Required	Provided	MR			
8.	MOEFA	Required	Provided	M/R			
9.	Public Address System	Required	Provided	M/R			
10.	Automatic Sprinkler System		TO STORTON				
	Basement	Dogwinad	D 11.				
	Banquet hall	Required N/A	Provided N/A	M/R			
	Sprinkler above false ceiling	N/A		N/A			
11.	Internal Hydrants	IV/A	N/A	N/A			
	<u> </u>						
	Size of riser/down-comer	150 mm	150 mm	M/R			
	Number of hydrants per floor	01	01	M/R			
2.	Hose Box Vord Hydrox	01	01	M/R			
12.	Yard Hydrants						
	Total number of hydrants	N/A	01 Provided	N/A			
3.	Hose Box	N/A	01 Provided	N/A			
J.	Pumping Arrangements			3. v			
	Ground Level		,				
	Discharge of main Pump	2280 LPM	2280 LPM	M/R			
	> Head of Main pump	70 m	70 m	M/R			
	Number of main pumps	01 nos.	01 nos.	M/R			
	> Jockey Pump out put	180 LPM	180 LPM	M/R			
	 ▶ Jockey pump head ▶ Standby Pump out put 	70 m	70 m	M/R			
	Standby Pump out putStandby Pump Head	2280 LPM	2280 LPM	MR			
	➤ Auto Starting/Manual Stopping	70 m	70 m	MR			
		Required	Provided	-			
	Pump House Access	Required	Provided	MR			
	Terrace level		Tiovided	MR			
	Discharge of pump	900 LPM	900 LPM	MD			
	➤ Head of the pump	40 M	40 M	MR MR			
	➢ Power Supply	Required	Provided	MR			
	➤ Auto Starting of pump	Required	Provided	MR			
14.	Captive Water Storage for fire fighting						
	Underground tank capacity	2,00,000 ltrs	Provided	MR			
	> Draw-off connection	Required	Provided	MR			
	Fire service inlet	Required	Provided	M/R			
	Access to tank	Required	Provided	MR			
Personal Const	Overhead Tank capacity	10,000 ltrs.	Provided	M/R			
15.	Exit Signage.	Required	Provided	M/R			
16.	Provision of Lifts. (Lift shall run from Ground to upper floors)						
	Pressurization of Lift Shaft	N/A					
	Pressurization of Lift lobby	N/A	N/A	N/A			
	Communication In lift Car	Required	N/A Provided	N/A			
	Fireman's Grounding Switch	Required	- SAG - INCACCACION	M/R			
	Lift Signage	Required	Provided	M/R			
0		quilou	Provided	M/R			

W

	Standby power supply	Required	Provided	M/R		
1	Refuge Area.					
10.	> Total Area	N/A	N/A	N/A		
To	> Location	N/A	N/A	N/A		
	Fire Control Room					
19.	Detector System Panel	N/A	N/A	N/A		
	Flow Switch Panel	N/A	N/A	N/A		
	PA System Panel	N/A	N/A	N/A		
	Battery backup	N/A	N/A	N/A		
	Building Floor Plans	N/A	N/A	N/A		
20.	Special Fire Protection System for Protection of special Risks, if any:	N/A	N/A	N/A		

The fire protection systems provided in the building were checked and found functional at the time of inspection.

Note: - As per undertaking submitted by the guest house management (placed at C-128) that the banquet hall running at ground & first floor only in a building comprised of basement, ground plus three upper floors, using basement as storage, second & third floor (Guest house). Guest house having separate FSC by this department vide letter No. F.6/DFS/MS/GH/2025/SZ/36 dated 22.05.2025 (placed at C- 122).

In view the deemed compliance of the minimum standards on fire prevention and fire safety measures as required under the rules, the FSC issued vide letter No. F.6/DFS/MS/SZ/2022/BNQT./28 dated 13.06.2022, renewal under rule 37 of the Delhi Fire Service rules 2010 is recommended.

> Signature of the Name: - R.K. Yadav

Designation: - ADO(JKP)