
GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI **HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI- 110001** No. F6/DFS/MS/GH/2025/ 104



Dated:- 03/03/2025

FIRE SAFETY CERTIFICATE

Certified that the M/s. Anand Lok Inn Located at A-89, Road No. 4, Mahipalpur Extn., Near IGI Airport, New Delhi-110037, comprised of Basement + Ground + 04 Upper Floors (4th floor sealed by owner), but Guest House is running at Ground + 03 Upper Floors with 18 Guest Rooms was issued Fire Safety Certificate by this department vide letter no. F6/DFS/MS/GH/ 2022/SZ/19 dated 11/01/2022. The said premise was re-inspected by the officer concerned of this department on 25/02/2025 in the presence of Sh. Santosh Jha (Manager) and found that the said premises have deemed complied with the fire prevention and fire safety requirements in accordance with the Rule 33 of the Delhi Fire Service Rules, 2010 and that the premises/building is fit for occupancy "Residential & Lodging" Group-A, (Guest House 18 Guest Rooms only) with effect from 03/03/2025 and valid up to 31/03/28 in accordance with Rule 36 unless renewed under Rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under Rule 38 of the Delhi Fire Service Rules 2010 printed below.

Issued on 03/03/2025 at New Delhi by

Tel No. 011-23414000

Copy to:-

- 1. The Joint Commissioner of Police (Lic), 1st Floor, Licensing Unit, Police Station, Defence Colony, New Delhi: - in r/o computer id no. 2025020301401dated 03/02/2025
- 2. The Authorized Signatory, M/s. Anand Lok Inn, A-89, Road No. 4, Mahipalpur Extn. Near IGI Airport, New Delhi-110037.

Following fire safety directives must be adhered to:-

- 1. All the means of escape shall be kept free of all type of obstruction all the time.
- 2. All the employees shall be acquainted with the use and maintenance of all fire equipments and method of smooth and speedy safe evacuation of occupants in case of emergency.
- 3. All the fire fighting equipments shall be maintained in perfect working condition all the time and any lapse rendering non-functional if fire safety measures, management shall be responsible.
- 4. Any deviation, with regards to construction, ventilation, occupation, electric installation etc. may be got verified from the concerned authorities.
- 5. The Fire Safety Certificate may not be treated in any case for regularizations of unauthorized construction / unauthorized use of land if any.
- 6. All comments / directions of licensing Department shall always be permitted and followed.
- 7. The owner /occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rule 2010. The form is available on www.dfs.delhigovt.nic.in
- 8. The owner / occupier shall apply for renewal of this Fire Safety Certificate to the Director in 'Form J' (sub Rule (1) of Rule 37) along with copy of the certificate, six months prior to its expiry.
- 9. The guest house management has given an undertaking that 4th floor not in use and sealed. Two temporary rooms constructed at terrace floor and pantry setup has been removed. If they found using of 4th floor & re-construct temporary structure then their FSC may be treated as null & void.

INSPECTION REPORT

1. Name & address of the building : M/s Anand Lok Inn, located at A-89, Road No. 4,

Mahipalpur Extn., Near IGI Airport, New Delhi-

110037

2. Type of Occupancy : Residential Building "Group-A", Basement (other

> property) Ground + 04 Upper Floor (4th floor sealed by owner) Guest House is running at Ground + 03 Upper

> > Total guest rooms: - 18 nos.

Basement: - Other property GF - 03 guest rooms

05 guest rooms

4th floor - sealed

1st. 2nd & 3rd floor each having

Floors

: Renewal 3. Type of Case

: F.6/DFS/MS/GH/2022/SZ/19 dated 11/01/2022 4. Details of previous NOC

5. Fire Safety directives Letter No. : Nil

: 25/01/2025 6. Date of inspection

: Aman Kumar Lathar, ADO (JWP) 7. Name of the Inspecting Officer

8. Name and designation of Officer

: Sh. Santosh Jha (Manager) from the building side

: 2008 9. Year of Construction

10. Applicant's online application no. : 2025020301401dated 03/02/2025

S No	Minimum standards on fire prevention and fire safety U/R 33	Old NOC Requirements	Provided at site	Remarks MR/NMR		
1.	Access of building) (D		
	Road width	06 m	06 m	MR		
	Gate width	NA	NA	NA		
	Width of internal road	NA	NA	NA		
2.	Number, width, Type & Arrangements of exits					
	a. Number of staircases) (D		
	Upper floors	01 no.	Provided	MR		
	Basements	NA	NA	NA		
	b. Width of staircases					
	Upper floors	1.25 m	Provided	MR		
	Basements	NA	NA	NA		
	c. Protection of exits					
	Fire check door	NA	Provided	NA		
	Pressurization	NA	NA	NA		
	d. No of continuous staircase to terrace	01	Provided	MR		
	vvv. 1.1. OC Comidon	NA	NA	NA		
	f. Door Size	1.0 m	1.10 m (final exit)	MR		
3.	Compartmentation					
٥.	Fire check door	NA	NA	NA		
	Sealing of electrical shafts	Required	Provided	MR		
	Fire Rating of shaft door	NA	NA	NA		
	Water Curtain	NA	NA	NA		
	No. of the second secon	NA	NA	NA		
1	Fire Dampers Smoke managements System					
4.	Basements	NA	NA	NA		
	Upper floors	Required	Natural Ventilation	MR		
5.	Fire Extinguishers			720 155 SEXX		
٥.	Total numbers	10 nos.	Provided	MR		
- 1	Types	ABC & CO ₂	Provided	MR		
	IS marking	ISI marked	Provided	MR		
	18 Q	h				

	In.				
6.	First	- Aid Hose Reels	r 01	Provided	MR
	•	Total numbers on each floo	30 m	Provided	MR
	•	Length of hose reel hose	5 mm	Provided	MR
_	•	Nozzle diameter		Trovided	ivity
7.		matic fire detection and alarm	Required	CO/Smoke t	ype MR
	•	. , p - 0		Ground Flo	
	•	Location of Main Panel	Required NA	NA	NA NA
	•	Location of Repeater Panel	Required	Provided	MR
	•	Alternate source of power	Required	Provided	MR
	•	Hooters' Location			
8.	MOE	FA	Required	Provided NA	MR NA
9.		c Address System	NA	INA	INA
10	. Autor	natic Sprinkler System	NA	NA	NA
	•	Basements	NA NA	NA NA	NA
		Upper Floor	NA NA	NA NA	NA
	•	Sprinkler above false ceiling	g NA	IVA .	
11.	Intern	al Hydrants:	1 10	100 mm	NA
		Size of riser/down- comer	NA	01 no.	NA
	•	Number of hydrants per	NA	OT HO.	1443
		floor	214	01 no.	NA
	•	Hose Box	NA	01 110.	
12.	Yard I	Hydrants	374	NA	NA
	•	Total number of hydrants	NA NA	NA NA	NA
	•	Hose Box	NA	11/2	
13.	Pumpi	ng Arrangements:			1
	•	Ground Level	NA	NA	NA
	•	Discharge of main pump	NA NA	NA	NA
	>	Head of main pump	NA NA	NA	NA
	>	Number of main pumps	NA NA	NA	NA
	>		NA	NA	NA
	>	Jockey pump head	NA	NA	NA
	>	Standby Pump out put Standby Pump Head	NA	NA	NA
		Auto Staring/Manual	NA	NA	NA
		stopping			
	A	Pump House Access	NA	NA	NA
		Terrace level			
	>	Discharge of pump	450 lpm	Provided	MR
	>	Head of the pump	40 m	Provided	MR
		Power supply	Required	Provided	MR
	>	Auto starting of pump	Required	Provided	MR
4.	Captive	water Storage for fire fightin	g:		
		Under ground tank capacity	NA	NA	NA
		Draw off connection	NA	NA	NA
		Fire service inlet	NA	NA	NA
	۲	Access to tank	NA	NA	NA
		Overhead Tank capacity	5, 000 ltrs.	10,000 ltrs.	MR
5	Exit Sig		Required	Provided	MR
6.	St. Steel & St. Co.	on of Lifts			
		Pressurization of Lift Shaft	NA	NA	NA NA
		Pressurization of lift lobby	NA	NA	NA
		Communication in lift Car	NA	NA	NA
		Fireman's Grounding Switch	NA	NA NA	NA NA
-		Lift Signage	NA NA	NA .	NA MB
7.		power supply	Required	Provided	MR
8.	Refuge		214	NIA II	NIA
		Total area	NA	NA NA	NA NA
		Joeation	NA	NA	NA
		1		- 11	
		IN CONTRACTOR OF THE PROPERTY		- 11	

Fire control room Detector system panel	NA	NA	NA
> Flow Switch Panel	NA	NA	NA
> PA System Panel	NA	NA	NA
> Battery backup	NA	NA	NA
> Building Floor Plans	NA	NA	NA
Special Fire Protection Systems for Protection of special Risks, if any;	NA	NA	NA

The fire protection systems provided in the building were checked and found functional at the time of inspection. In reply of earlier shortcomings issued vide letter no. F.6/DFS/MS/GH/2025/SZ/54 dated 31/01/2025. The guest house management has given an undertaking that 4th floor not in use and sealed. Two temporary rooms constructed at terrace floor and pantry setup has been removed. If I found using of 4th floor & re-construct temporary structure then our FSC may be treated as null & void.

Keeping in view of the deemed compliance of the minimum standards of fire prevention and fire safety measures as required under the rules, the FSC issued vide etter no. F.6/DFS/MS/GH/2022/SZ/19 dated 11/01/2022, renewal under rule 35 of the Delhi Fire Service Rule 2010, is recommended.

Accordingly, DFA is put up for approval & signature please.

ADO (JWP)