

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI- 110001



No. F6/DFS/MS/GH/NDZ/2025/ 475

Dated: 21/08/2025

FIRE SAFETY CERTIFICATE

Certified that the M/s Asian Guest House, Located at 1119-22, Baza Matia Mahal, Jama Masjid, Delhi-110006, comprised of Ground + 04 Upper Floors, Ground Floor- (commercial use), 1st floor- (04 guest rooms + 01 store room), 2nd floor- (04 guest rooms + 01 store room), 3rd floor- (03 guest rooms), Total 11 guest rooms, was issued Fire Safety Certificate by this department vide letter no. F6/DFS/MS/GH/NDZ/2022/359 dated 26/07/2022. The said premise was re-inspected by the officer concerned of this department on 12/08/2025 in the presence of Sh. Mohammad Nasir (Proprietor) and found that the building is comprised of Ground + 04 Upper Floors and now the floor wise occupancy is ground floor- (commercial use), 1st floor- (04 guest rooms + 01 store room), 2nd floor- (04 guest rooms + 01 store room), 3rd floor- (03 guest rooms), 4th floor-not in use as per an undertaking dated 12/08/2025. The building has deemed complied with the fire prevention and fire safety requirements in accordance with the Rule 33 of the Delhi Fire Service Rules, 2010 and that the premises/building is fit for occupancy class of Residential (Group A-1), 1st floor- (04 guest rooms), 2nd floor- (04 guest rooms), 3rd floor- (03 guest rooms), Total 11 guest rooms up to 3rd floor only, with effect from 2108 2025 for a period of three years in accordance with Rule 36 unless renewed under Rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under Rule 38 of the Delhi Fire Service Rules 2010 printed below.

Issued on 2108 2025 at New Delhi by

Virendra Singh

Virendra Singh
Chief Fire Officer

Copy to:-

1. The Commissioner, Municipal Corporation of Delhi, Civic Centre, Minto Road, New Delhi-110002:- in r/o computer id no. 2025072311757 dated 23/07/2025: to ensure occupancy as detailed above and deviation, if any.

2. The Authorized Signatory, M/s Asian Guest House, 1119-22, Baza Matia Mahal, Jama Masjid,

Delhi-110006.

Conditions for the validity of fire safety certificate:-

1. All the means of escape shall be kept free of all type of obstruction all the time.

2. All the employees shall be acquainted with the use and maintenance of all fire equipments and method of smooth and speedy safe evacuation of occupants in case of emergency.

3. All the fire fighting equipments shall be maintained in perfect working condition all the time and any lapse rendering non-functional if fire safety measures, management shall be responsible.

4. Any deviation, with regards to construction, ventilation, occupation, electric installation etc. may be got verified from the concerned authorities.

5. The Fire Safety Certificate may not be treated in any case for regularizations of unauthorized construction / unauthorized use of land if any.

6. All comments / directions of licensing Department shall always be permitted and followed.

7. The owner /occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rule 2010. The form is available on www.dfs.delhigovt.nic.in

8. The owner / occupier shall apply for renewal of this Fire Safety Certificate to the Director in 'Form J' (sub Rule (1) of Rule 37) along with copy of the certificate, six months prior to its expiry.

9. The occupancy of 4th floor not allowed as per clause 7.31 in UBBL-2016.

INSPECTION REPORT

Name & address of the building: M/s Asian Guest House, located at 1119-22, Bazar

Matia Mahal, Jama Masjid, Delhi-110006

2. Type of Occupancy : Residential, Group-A-1, Ground + 04 Upper Floors

Ground floor - Commercial (Mercantile), 1st floor - 04 guest rooms + 01 store room, 2nd floor - 04 guest rooms + 01 store, 3rd floor - 03 guest rooms & 4th floor - 03 wooden cabinets rooms + lobby (not in use as per

an undertaking dated 12/08/2025)

3. Type of Case : Renewal

4. Details of previous NOC : F6/DFS/MS/GH/NDZ/2022/359 dated 26/07/2022

5. Fire Safety directives Letter No.: Nil

6. Date of inspection : 12/08/2025

7. Name of the Inspecting Officer: Aman Kumar Lathar, ADO (JWP)

8. Name and designation of Officer

from the building side : Sh. Mohammad Nasir (Proprietor)

9. Year of Construction : 1980-81

10. Applicant's letter no. : 2025072311757 dated 23/07/2025

lo	Minimum standards on fire prevention and fire safety U/R 33	Requirements Existing fire safety arrangements	Provided at site	Remarks MR/NMR		
1.	Access of building					
	 Road width 	Accessibility	09 m) (D		
	 Gate width 	NA	NA NA	MR		
_	 Width of internal road 	NA	NA	NA NA		
2.	Number, width, Type & Arrangements of exits					
	a. Number of staircases					
	 Upper floors 	01 no.	Provided	MD		
	Basements	NA	NA	MR		
	b. Width of staircases	11		NA		
	 Upper floors 	0.80 m	Provided	MD		
	_	NA	NA	MR NA		
	Basements			NA		
	c. Protection of exits	NA	NA	214		
	Fire check door	NA	NA NA	NA		
1	Pressurization	01	Provided	NA		
1	d. No of continuous		1 Tovided	MR		
	staircase to terrace e. Width Of Corridor	NA	NA	NIA		
	f. Door Size	1.0 m	Provided	NA MR		
3.	Compartmentation			IVIK		
	Fire check door	N				
1	Sealing of electrical	NA	NA	NA		
	shafts	NA	NA	NA		
	Fire Rating of shaft door	NA	NA	NA		
}	Water Curtain	NA	NA	NI.		
	Fire Dampers	NA	NA	NA		
4.	Smoke managements System		11/1	NA		
	Basements	NA	NA	21.1		
	Upper floors	Required	Natural Ventilated	NA MR		

Fire	Extinguishers	08 nos.	Provided	MR		
1	Total numbers	ABC & CO ₂	Provided	MR		
1	• Types	ISI marked	Provided	MR		
	IS marking	1SI marked	1101111	C-33-8A \$1.		
Fin	rst – Aid Hose Reels	01	Provided	MR		
	Total numbers on each floor	30 m	Provided	MR		
1	 Length of hose reel hose 	5 mm	Provided	MR		
	Nozzle diameter		Tiovided			
A	Automatic fire detection and alarming system Required Provided					
	Type of detectors	Required		MR		
	 Location of Main Panel 	Required	Provided at 1 st floor	MR		
	 Location of Repeater Panel 	NA	NA	NA		
1	Alternate source of power	Required	Provided	MR		
	Hooters' Location	Required	Provided	MR		
8.	MOEFA	NA	NA	NA		
	Public Address System	Required	Provided	MR		
	Automatic Sprinkler System	Required	Tiovided	1411		
	Basements	NA	NA	NA		
	Upper Floor	NA	NA	NA		
	 Sprinkler above false ceiling 		NA	NA		
11.	Internal Hydrants:		· · · · · · · · · · · · · · · · · · ·			
	 Size of riser/down- comer 	NA	NA	NA		
	 Number of hydrants per floor 		NA	NA		
12	Hose Box	NA	NA	NA		
12.						
	Total number of hydrantsHose Box	NA NA	NA	NA		
13.		NA	NA	NA		
	Ground Level					
	Discharge of main pump	NA	NA	NA		
	Head of main pump	NA	NA NA	NA NA		
	Number of main pumps	NA	NA	NA		
	Jockey pump out putJockey pump head	NA	NA	NA		
1	Standby Pump out put	NA NA	NA	NA		
	Standby Pump Head	NA NA	NA	NA		
	Auto Staring/Manual	NA NA	NA NA	NA		
	stopping	NA	NA NA	NA		
1	Pump House AccessTerrace level		INA	NA		
	Discharge of pump	225 1 70 4				
	> Head of the pump	225 LPM 30 m	Provided	MR		
	Power supply	Required	Provided	MR		
12.00	Auto starting of pump	Required	Provided Provided	MR MR		
14.	4. Captive water Storage for fire fighting:					
	 Under ground tank capacity 	NA NA	NA	NA		
	 Draw off connection Fire service inlet 	NA	NA	NA		
	Access to tank	NA NA	NA	NA		
	Overhead Tank capacity	Required	Provided	MR		
15	Exit Signage	2500 ltrs.	Provided	MR		
16.	Provision of Lifts	Required	Provided	MR		
	➤ Pressurization of Lift Shaft	NA				
	> Pressurization of lift lobby		NA NA	NA		
	Communication in lift Car	NA	NA NA	NA		
			I INA	NA		
	Fireman's Grounding SwitLift Signage	ch NA	NA	NA		

	Standby power supply	Required	T:	
8.	Refuge Area	- toquired	Provided	MR
	➤ Total area	NIA		····
	> Location	NA	NA	NA
19.	Fire control room	NA	NA	NA
	Detector system panel	NIA		
1	Flow Switch Panel	NA	NA	NA
	➤ PA System Panel	NA	NA	NA
	Battery backup	NA	NA	NA
	Building Floor Plans	NA	NA	NA
20.		NA	NA	NA
35 535		NA	NA	NA
	The fire protection systems pr	oridad: u		

The fire protection systems provided in the building were checked and found functional at the time of inspection.

Keeping in view of the deemed compliance of the minimum standards of fire prevention and fire safety measures as required under the rules, the FSC issued vide letter no. F6/DFS/MS/GH/NDZ/2022/359 dated 26/07/2022, renewal under rule 37 of the Delhi Fire Service Rule 2010, is recommended.

Accordingly, DFA is put up for approval & signature please.

DO (LO)

14/8/25

Dy. C.FO (1002)

C.F.O

Bincipal Director

Aman Kumar Lathar
ADO (WP)

14/08/25

CGO to Dom

19/08/20

20/8/2006

sin, F.S. Ichu is patent for y

Il 8 sas

Ms uploaded for

21/18/21 AM (2008)

upo