



**GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI**  
**HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI- 110001**

C-32  
75  
आज़ादी का  
अमृत महोत्सव

No. F6/DFS/MS/School/NDZ/2025/640

Dated: 12/08/2025

To,

The Principal,  
Bal Bhavan Public School  
Pocket B, Mayur Vihar,  
Phase – II, Delhi - 110091.

**Subject: - Regarding grant of Fire Safety Certificate in r/o Bal Bhavan Public School located at Pocket B, Mayur Vihar, Phase – II, Delhi - 110091.**

Sir,

This has a reference to your Outdoor Dairy No. 3887 dated 18/07/2025 on the subject cited above. In this connection, it is to inform you that school was inspected by the officer concerned of this department on 26/07/2025 in the presence of Mr. Vividh Gupta (Principal) and observed that school building comprised of Basement, Ground plus three upper floors.

**Following shortcomings were observed during time of inspection:**

1. Fire Check door found removed.
2. Corridors at 2<sup>nd</sup> & 3<sup>rd</sup> floors encroached by making conference room/library that is not allowed.
3. First-Aid-Hose Reel nozzle found removed.
4. Sprinkler system not provided on wooden stage for cultural programmed.
5. Fire pump not auto mode.
6. Overhead tank capacity of 10,000 liters provided against the requirement of 20,000 liters.
7. Exit & floors Signage's found removed in strategic location in the building.

In view of above shortcomings, the application for issuance for Fire Safety Certificate is rejected. The occupancy of the building/premises in absence of requisite fire safety arrangements shall be at the risk and liability of the management. The Authority/Statutory Authority may take suitable necessary action as deemed fit.

You're faithfully,

*[Signature]*  
11/08/2025

**VIRENDRA SINGH**  
**CHIEF FIRE OFFICER**  
o/c **DELHI FIRE SERVICE**

**Copy to: -**

1. Director of Education, GNCT of Delhi, Old Secretariat, Civil Lines, Delhi-110054.
2. The Principal, Bal Bhavan Public School located at Pocket B, Mayur Vihar, Phase – II, Delhi - 110091.