



GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEAD QUARTERS: DELHI FIRE SERVICE: NEW DELHI - 110001

No F6/DFS/MS/2025/WZ/BNQT/ 22

Dated: 04/04/2025

FIRE SAFETY CERTIFICATE

Certified that **M/s Banquet Mehak (A unit of Amour Banquets)** located at **Plot No.43, Road No.35, Main Rohtak Road, West Punjabi Bagh, New Delhi-110026**, comprised of Basement + Stilt + Upper Ground + 03 upper floors but **Banquet Mehak is running at Ground & 01 floor only** has already been issued FSC by this department vide letter No. **F.6/DFS/MS/BNQT/WZ/2022/03 dated 18.01.2022**. The premises was re-inspected by the officer concerned of this department on **28.03.2025** in the presence of **Mr. Rohit Kochhar** and found that the said building have deemed complied with the fire prevention and fire safety requirements in accordance with Rule 33 of the Delhi Fire Service Rules, 2010 and that the premises fit for occupancy **Class Group D "Assembly" for (Ground & 01 floor only)** with effect from 04/04/2025 for a period of **three years** in accordance with Rule 36 unless renewed under Rule 37 or sooner cancelled under Rule 40 and subjected to compliance of the conditions under Rule 38 of the Delhi Fire Service Rules, 2010.

Issued on 04/04/2025 at New Delhi by

(Atul Garg)
DIRECTOR

Ph; 011-23414000

Copy to:-

1. MCD Portal Id-2025011500540 dated 08.03.2025.
2. Mr. Rohit Kochhar M/s Banquet Mehak (A unit of Amour Banquets) located at Plot No.43, Road No.35, Main Rohtak Road, West Punjabi Bagh, New Delhi-110026.
3. The Dy. Health Officer, West Zone, South Delhi Municipal Corporation, Shivaji Enclave, Raja Garden, New Delhi-110017.

Conditions for the validity of Fire Safety Certificate:

1. All the fire safety arrangement provided there-in shall be maintained in good working conditions at all times.
2. Loss of life or property due to non functional fire safety measure shall be at the responsibility of the management/occupier.
3. The trained fire fighting staff should be available round the clock.
4. Any deviation with regard to the construction etc shall be verified by the concerned building sanctioning agency.
5. This certificate cannot be treated in any case for regularizations of unauthorized construction.
6. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director of Form 'J' [sub rule (1) of rule 37] along with a copy of this Certificate, six months prior to its expiry".
7. The owner / occupier shall submit a declaration every year in form "K" provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on
8. All the means of escape shall be kept free of any obstruction all the time to evacuate the occupant, in a safe manner, in the event of emergency.

http://www.delhi.gov.in/wps/wcm/connect/doit_fire/FIRE/Home/Fire+Safety+Acts+and+Rules/
http://www.delhi.gov.in/wps/wcm/connect/doit_fire/FIRE/Home/Forms

N/29

INSPECTION REPORT

1. Name & address of the building	M/s Banquet Mehak (A unit of Amour Banquets) located at Plot No.43, Road No.35, Main Rohtak Road, West Punjabi Bagh, New Delhi-110026.			
2. Type of Occupancy	Assembly (Banquet Hall)			
3. Comprised of building	Basement + Stilt + Upper Ground + 03 upper floors			
4. Type of Case	Renewal (Banquet Mehak is running at Ground + 01 upper floor only)			
5. Details of Previous NOC	F.6/DFS/MS/BNQT/WZ/2022/03 dated 18.01.2022.			
6. Fire Safety directives letter No	-NA-			
7. Date of inspection	28.03.2025			
8. Name of Inspecting Officer	Sh. Ajay Kumar Sharma (ADO Rohini)			
9. Name and designation of officers From the building side	Mr. Rohit Kochhar			
10. Year of Construction	2014 on MCD Portal			
11. Applicant's letter No.	Online application No.2025011500540 dated 08.03.2025.			
S. No	Minimum Standards on fire prevention and fire safety U/R 33	BBL/NBC Requirement / as per prev. Ins Report 04.08.2018	Provided at site	Remarks MR/NMR
1.	Access to building			
	• Road width	12m	Provided	MR
	• Gate width	5m	On main road	MR
	• Width of internal road	-NA-	-NA-	-NA-
2.	Number, Width, Type & Arrangement of Exits			
	a. Number of staircases			
	• Upper Floors	02nos.	03nos.	MR
	• Basements	-NA-	-NA-	-NA-
	b. Width of staircases			
	• Upper Floor	2m & 1.5m	2.05, 1.5m & 1m	MR
	• Basements	-NA-	-NA-	-NA-
	c. Protection of exits			
	• Fire check door	Required	Provided	MR
	• Pressurization	-NA-	-NA-	-NA-
	d. No. of continuous staircases to terrace	01nos.	02nos.	MR
	e. Width of Corridor	-NA-	-NA-	-NA-
	f. Door Size	2 x 2m	2 x 52m	MR
3.	Compartmentation			
	a) Fire check door	-NA-	-NA-	-NA-
	b) Sealing of electrical shafts	-NA-	-NA-	-NA-
	c) Fire Rating of shaft door	-NA-	-NA-	-NA-
	d) Water Curtain	-NA-	-NA-	-NA-
	e) Fire Dampers	-NA-	-NA-	-NA-
4.	Smoke Management System			
	a) Basements	-NA-	-NA-	-NA-
	b) Upper floors	12 a/c per hour	Provided	MR
5.	Fire Extinguishers			
	a) Total numbers	08nos.	Provided	MR
	b) Types	ABC/CO2	ABC/CO2	MR
	c) IS marking	ISI marked	Yes	MR
6.	First-Aid Hose Reels			

Ch

	a) Total numbers on each floor	01nos.	Provided	MR
	b) Length of hose reel hose	30mm	Provided	MR
	c) Nozzle diameter	5m	Provided	MR
7.	Automatic fire detection and alarming system			
	a) Type of detectors	Smoke/ heat	Provided	MR
	b) Location of Main Panel	Required	Provided	MR
	c) Location of Repeater Panel	Required	Provided	MR
	d) Alternate source of power	Required	Provided	MR
	e) Hooters' Location	Required	Provided	MR
8.	MOEFA	Required	Provided	MR
9.	Public Address System	Required	Provided	MR
10.	Automatic Sprinkler System			
	a) Basement	-NA-	-NA-	-NA-
	b) Ground & Upper Floors	-NA-	Provided	-NA-.0
	c) Sprinkler above false ceiling	-NA-	-NA-	-NA-
11.	Internal Hydrants			
	a) Size of riser/down-comer	100mm	Provided	MR
	b) Number of hydrants per floor	01nos.	Provided	MR
	c) Hose Box	01nos.	Provided	MR
12.	Yard Hydrants			
	a) Total number of hydrants	-NA-	-NA-	-NA-
	b) Hose Box	-NA-	-NA-	-NA-
13.	Pumping Arrangements			
	• Ground Level			
	➤ Discharge of main Pump	-NA-	2280lpm	-NA-
	➤ Head of Main pump	-NA-	70m	-NA-
	➤ Number of main pumps	-NA-	02nos.	-NA-
	➤ Jockey Pump out put	-NA-	180lpm	-NA-
	➤ Jockey pump head	-NA-	70m	-NA-
	➤ Standby Pump out put	-NA-	-NA-	-NA-
	➤ Standby Pump Head	-NA-	-NA-	-NA-
	➤ Auto Starting/Manual Stopping	-NA-	-NA-	-NA-
	➤ Pump House Access	-NA-	-NA-	-NA-
	Terrace level			
	➤ Discharge of pump	900lpm	Provided	MR
	➤ Head of the pump	40m	Provided	MR
	➤ Power Supply	Required	Provided	MR
	➤ Auto Starting of pump	Required	Provided	MR
14.	Captive Water Storage for fire fighting			
	• Underground tank capacity	-NA-	54000/ltrs	-NA-
	➤ Draw-off connection	Required	Provided	MR
	➤ Fire service inlet	Required	Provided	MR
	➤ Access to tank	Required	Provided	MR
	• Overhead Tank capacity	15,000ltr	Provided	MR
15.	Exit Signage.	Required	Provided	MR
16.	Provision of Lifts.			
	a) Pressurization of Lift Shaft	-NA-	-NA-	NA(as lift is terminating as still floor)
	b) Pressurization of Lift lobby	-NA-	-NA-	-NA-

MR	c) Communication In lift Car	Required	Provided	MR
MR	d) Fireman's Grounding Switch	-NA-	-NA-	-NA-
MR	e) Lift Signage	-NA-	-NA-	-NA-
MR	17. Standby power supply	Required	Provided	MR
MR	18. Refuge Area.			
	a) Total Area	-NA-	-NA-	-NA-
	b) Location	-NA-	-NA-	-NA-
	19. Fire Control Room			
	a) Detector System Panel	-NA-	-NA-	-NA-
	b) Flow Switch Panel	-NA-	-NA-	-NA-
	c) PA System Panel	-NA-	-NA-	-NA-
	d) Battery backup	-NA-	-NA-	-NA-
	e) Building Floor Plans	-NA-	-NA-	-NA-
	20. Special Fire Protection System for Protection of special Risks, if any:	-NA-	-NA-	-NA-

Accordingly, the fire protection systems provided in the building were tested/ checked randomly and found in working condition at the time of inspection.

In view of the deemed compliance of the minimum standards of the fire prevention and fire safety measures as required under the rules the NOC issued vide letter no. F.6/DFS/MS/BNQT/WZ/2022/03 dated 18.01.2022 is recommended for renewal under rule 37 of the Delhi Fire Service rules 2010.

Signature of the Inspecting Officer
Name Ajay Kumar Sharma
Designation ADO(Rohini)

DO (WD) - NA

DCFO (WZ)

DCFO 1199-01/10

Dated 28/03/25

cfo

31/03/25

Director

TE-RT Cor & UT
round

MV

Sir, it is case of renewal only and DFA along with fr is put up again for kind perusal & approval please. Error is regretted.

Director

28/03/25