

## GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEAD QUARTERS : DELHI FIRE SERVICE : NEW DELHI – 110001

No. F6/DFS/MS/NDZ/Petr./2025/ 6 0 0

Dated: 1.2./!/../2025

## FIRE SAFETY CERTIFICATE

Issued.../.2/!//...at New Delhi by.

(Dr. S. K. Tomar) Dy. Chief Fire Officer

## Copy to:-

- The Manager, BPCL Modern Service Station, Janpath, Connaught Place, New Delhi. Conditions for the validity of Fire Safety Certificate
  - 8. "No Smoking" and "Not to use Mobile Phone" sign board should be displayed in such a manner as to be easily readable by all persons.

9. No trade Susceptible to Cause Ignition Petroleum vapors by generating heat, mechanical/electric spark should be allowed within the premises and its vicinity.

- 10. 04 nos of CO2 gas type ISI capacity of 4.5 kg, 02 nos of ABC stored pressure power type ISI capacity 05 kg and 01 number of AFFF type ISI capacity 50 ltrs provided should be maintained in proper working order all the time.
- 11. The working employed at the petrol pump must be taught the correct method of operation and maintenance of record of the extinguishers be ensured.

12. Overhead electric cable not passing across the licensed premises.

- 13. The owner / occupier shall submit a declaration every year in Form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on <a href="https://www.dfs.delhigovt.nic.in">www.dfs.delhigovt.nic.in</a>.
- 14. "The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in Form 'J' [sub rule (I) of rule 37] along with a copy of this Certificate, six months prior to its expiry.

NIIS

## INSPECTION REPORT

BPCL Modern Service Station at 35 Janpath, 1. Name & address of the building

Connaught Place, New Delhi

Hazardous Group J 2. Type of occupancy: -

Ground floor & 1st floor

Renewal 3. Type of case: -

No. F6)/DFS/MS/NDZ/2022/Petr./64 dated

11/02/2022

5. Fire safety directives No.-

4. Details of previous NOC: -

N/A 01/11/2022

6. Date of inspection:-

Sh. Bhupender Prakash (ADO/CC)

7. Name of the inspecting officer:-8. Name & designation of officer From the building side:-

Sh. Dinesh Kumar (Manager)

9. Year of construction:-Nil dated 20.09.2025 10. Applicant's letter No:-Remarks Provided at site Requirement Minimum Standards on fire MR/NMR S.No. Existing fire Prevention and fire safety U/R 33 safety arrangements Access to Building 1. MR 15 mtr. 06 mtr. 1) Road width MR Accessible Accessible 2) Gate width directly N/A N/A N/A 3) Width of internal road Number, Width Type & Arrangement of Exits 2. A. Number of staircases MR 01 01 1. Upper floors N/A N/A N/A 2. Basements B. Width of staircase MR 1.2 mtr. 1.2 mtr. 1. Upper floors N/A N/A N/A 2. Basements C. Protection of exits N/A N/A N/A 1. Fire check door N/A N/A N/A 2. Pressurization N/A N/A N/A D. No. of continuous staircase to terrace N/A N/A N/A E. Width of corridor N/A N/A N/A F. Door size Compartmentation 3. N/A N/A N/A 1) Fire check door N/A N/A 2) Sealing of electrical shafts N/A N/A N/A N/A 3) Fire rating of shaft door N/A N/A 4) Water curtain N/A N/A N/A N/A 5) Fire Dampers Smoke Management System 4. N/A N/A N/A 1) Basements N/A N/A N/A 2) Upper floors Fire Extinguishers 5. MR 08 07 1) Total numbers MR Provided 2) Types ABC, Foam, Co2 Required MR Required Provided 3) ISI marking First-Aid Hose Reel 6. N/A N/A N/A 1) Total number of eachfloor N/A N/A 2) Length of hose reel hose N/A N/A N/A N/A 3) Nozzle diameter **Automatic Fire Detection & Alarming System** 7. N/A N/A 1) Type of detectors N/A N/A 2) Location of main panel N/A N/A N/A 3) Location of repeater panel N/A N/A N/A 4) Alternate source of power N/A N/A N/A 5) Hooter's Location N/A N/A 8. MOEFA N/A N/A N/A

BPCL Modern Service Station, Januarh, Connaught Pla

V	10	
	,	

\$1		100	15507	N/A		
9.	Public Address System	N/A	N/A	IV/A		
10.	Automatic Sprinkler System			77/4		
	1) Basement	N/A	N/A	N/A		
	2) Upper floors	N/A	N/A	N/A		
	3) Sprinkler above false	N/A	N/A	N/A		
	ceiling					
11.	Internal Hydrants					
	1) Size of riser/down-comer	N/A	N/A	N/A		
*,5	2) Number of hydrants per	N/A	N/A	N/A		
	floor	12 10 10 10 10 10 10 10 10 10 10 10 10 10	Sept. 200			
	3) Hose box	N/A	N/A	N/A		
12.	Yard Hydrants					
	1) Total number of hydrants	N/A	N/A	N/A		
	2) Hose box	N/A	N/A	N/A		
13.	Pumping Arrangement					
	1) Ground level	N/A	N/A	N/A		
	a) Discharge of main	N/A	N/A	N/A		
	pump	We 200 (2007)		3 1 2 2 2		
	b) Head of main pump	N/A	N/A	N/A		
	c) Number of main pump		N/A	N/A		
	d) Jockey pump out put	N/A	N/A	N/A		
	e) Jockey pump head	N/A	N/A	N/A		
	f) Stand by pump output	N/A	N/A N/A	N/A N/A		
	g) Stand by pump head	N/A	N/A N/A	N/A N/A		
	h) Auto starting/Manual	N/A	N/A	-		
	stopping	IV/A	IN/A	N/A		
	2) Terrace level	1				
	a) Discharge of pump	N/A	N/A	77/4		
	b) Head of pump	N/A	I III - FAME NAME OF	N/A		
	c) Power supply	N/A	N/A	N/A		
	d) Auto starting of pump	N/A	N/A	N/A		
14.	Captive Water Storage for F	ivo Fichtica	N/A	N/A		
	Under ground tank	N/A				
	capacity	IV/A	N/A	N/A		
	a) Draw-off connection	N/A	N/A			
	b) Fire service inlet	N/A	N/A	N/A		
	c) Access to tank	N/A		N/A		
	d) Over head tank	N/A	N/A	N/A		
	capacity	. 114.4	N/A	N/A		
15.	No Smoking Signage	Required	Provided in			
1/	English & Hindi		English & Hindi	MR		
16.	Provision of Lifts.		Zignon & Hindi			
	a) Pressurization of lift	27/1				
	shaft	N/A	N/A	N/A		
	b) Pressurization of lift	NT/ A	A	LVA		
	lobby	N/A	N/A	N/A		
	c) Communication in	NI/A		1071		
	lift car	N/A	N/A	N/A		
	d) Fireman's switch	NI/A	W1) (7)	1,1/1		
	e) Lift signage	N/A	N/A	N/A		
17.	Stand by Power Supply	N/A	N/A	N/A		
18.	Refuge Area	N/A	N/A	N/A		
	Total area location	N/A	N/A			
19.		N/A	N/A	N/A		
19,	Fire Control Room	N/A		N/A		
	a) Detector system	N/A	N/A	N/A		
	panel	IVA	N/A	N/A		
	b) Flow switch panel	N/A		IV/A		
-	c) PA system panel	N/A	N/A	N/A		
	1) Table					
	a) Battery backum	N/A N/A	N/A N/A	N/A		

		רווא		
	e) Building floor plan	N/A	N/A	N/A
20.	Special Fire Protection Syst Risk, if any: Provided Fire but	em for Protective with sand.	tion of special	MR
found	re protection systems provided functional at the time of inspect	in the building	g were randomly test	e prevention a
fire s F6)/D Fire S	view of the deemed compliance afety measures as required upper the property of	d 11/02/2022	renewal under rule	35 of the De
signat	ure please			
			Signature of the In	
ŧ			Nama: Bhun	DI U 2015 ender Prakash
			Designati	on: - ADO (C
DOJE	<u> ΄</u> Λ Λ			
DOJEL	8000 11/28			
	Go (201) (28)			
by- (	12 3/11/2	ŕ		_
, ,	Director	m.c	82 to	Jean !
rinci	pal Director	L		
	n Chris	72)	estu)	2
	My coole	2		
		f. h.pl.		
		OF	10/11/52 0001	
Asofa	ature please	f. T. lett	er is put e	p for
olyn	an a pease		Brahach	S

Long