



**GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI**  
**HEADQUARTERS: DELHI FIRE SERVICE: CANNAUGHT PLACE**  
**NEW DELHI- 110 001**

C/82



No.F.6/DFS/MS/EH/2025/SZ/ 289

Dated: 23/06/2025

To,

The Joint Commissioner (Lic.)  
1<sup>st</sup> floor Police Station Defence Colony,  
New Delhi

**Subject:-Regarding renewal of Fire Safety Certificate in r/o M/s Brims coffee House located at Shop No. HS-7,2<sup>nd</sup> Floor, Kailash Colony, Main Market, New Delhi-110048.**

Sir,

This has a reference to MCD online application ID No. 2025052108859 dated 06/06/2025 on the subject cited above. In this connection, it is to inform you that the said premises was re-inspected by the officer concerned of this department on dated 18/06/2025/06/2025 in presence of Sh. Kahid, Manager and During the inspection it was observed that the shortcomings as communicated earlier vide letter No. F.6/DFS/MS/EH/2024/NDZ/33 dated 22/01/2025 (copy enclosed) have not been complied yet.

In view of above shortcomings, the application for issuance Fire Safety Certificate is rejected. The occupancy of the building/premises in absence of requisite fire Safety arrangements shall be at the risk and liability of the owner/occupier. The Licensing Authority/Statutory Authority may take suitable necessary action as deemed fit.

Yours faithfully

(ATUL GARG)  
DIRECTOR  
DELHI FIRE SERVICE

Encl. As above

R.

e

=170 C181

**GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI**  
**HEAD QUARTERS : DELHI FIRE SERVICE : NEW DELHI - 110001**

No.F6/DFS/MS/GH/NDZ/ 33

Dated:- 22/01/2025

To,

The Manager  
M/S Brims Coffee House, Shop No. HS-7,  
Second Floor Kailash Colony, Main  
Market, Delhi.

**Sub: Issuance of FSC (Fire Safety Certificate) in r/o M/S Brims Coffee House, Shop no. HS-7,  
Second Floor Kailash Colony, Main Market, Delhi.**

Sir,

This has reference to online ID No. 2025010200057 dated 02/01/25, on the subject cited above. In this regard, it is to inform you that the site was inspected by the officer concerned of this department on 11/01/25 in the presence of Mr. Khalid and following shortcomings were observed:-

1. Alternate exit of 1.35 m is provided against the requirements of 1.5 meter.
2. Pumps, hose reel found nonfunctional and hydrant is also not provided at second floor.

Hence, the case is rejected and Fire Safety Certificate (FSC) cannot be renewed at this stage due to above shortcomings. Therefore, you are requested to rectify the above shortcomings and re-submit for further consideration in the matter.

Yours faithfully,

  
(Arul Garg)  
DIRECTOR

Delhi Fire Service

Copy to:

1. The Joint commissioner of Police ( Lic.) First floor, PS Defence Colony New Delhi.