

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEAD QUARTERS : DELHI FIRE SERVICE : NEW DELHI – 110001

No.F.6/DFS/MS/2025/ 476

Dated: 26 /09/2025

To

Authorized Signatory,
Continental Device India Pvt. Ltd.
C-120, Naraina, Industrial Area,
New Delhi-28.

Sub:- Regarding issuance of fire safety certificate in r/o Continental Device India Pvt. Ltd.
C-120, Naraina, Industrial Area, New Delhi.

Sir,

This has reference to your letter no. nil dated 01.09.2025, on the subject cited above in this regard, it is to inform you that the site was inspected by the officer concerned of this department on 15/09/2025 in the presence of Mr. Yogesh and the following shortcomings were observed:-

1. MCP not provided at upper floor, required to be provided at each floor .
2. Hose reel is not covering entire area, required to be extended to left out area.
3. Sprinkler is not provided at basement.
4. Smoke management in basement found nonfunctional.

In view of above, Fire Safety Certificate (FSC) cannot be renewed at this stage. Therefore you are requested to rectify the above shortcomings and re-submit for further consideration in the matter.

Yours faithfully


26/9/2025
(Virendra Singh)
Chief Fire Officer
✓