

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE, NEW DELHI-110001

Dated: 01 10

1/10/2025

No. F6/DFS/MS/2025/SZ/EH/ 339

FIRE SAFETY CERTIFICATE

Certified that the M/s Café De Flora A unit of Mehar Wing Services Pvt. Ltd. located at T-302-A, 3rd floor, Ambience Mall, 2 Nelson Mandela Marg, Vasant Kunj, Delhi-110070, comprised of 03 tire basement, ground + 03 upper floors and Restaurant is running at T-302-A, 3rd floor only was inspected by the officer concerned of this department on 17.09.2025 in the presence of Mr. Vijay Bajaj and found that the said premises have complied with the fire prevention and fire safety requirements in accordance with Rule 33 of the Delhi Fire Service Rules,2010 and that the premise is fit for occupancy class D "Assembly Building" for (Restaurant) T-302-A, 3rd floor only with effect from 01/10/2025 for a period of 03 (Three) years in accordance with Rule 36 unless renewed under Rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under Rule 38 of the Delhi Fire Service Rules, 2010.

Issued on 01 10 2025 at New Delhi by

May 912005

(Virendra Singh) Chief Fire Officer Delhi Fire Service

Copy to: -

MCD Portal ID-2025083013022 dated 03.09.2025.

CAR

- 2. The Dy. Health Officer, Public Health Department, South Zone, Green Park, Delhi-16.

 Conditions for the validity of Fire Safety Certificate:
- 1. All the fire safety arrangement provided there-in shall be maintained in good working conditions at all times.
- 2. Loss of life or property due to non functional fire safety measure shall be at the responsibility of the management.

3. The trained fire fighting staff should be available round the clock.

4. Any deviation with regard to the construction etc shall be verified by the concerned building sanctioning agency.

5. This certificate cannot be treated in any case for regularizations of unauthorized construction.

6. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director of Form 'J' [sub rule (1) of rule 37] along with a copy of this Certificate, six months prior to its expiry".

7. The owner / occupier shall submit a declaration every year in form "K" provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on

8. All the means of escape shall be kept free of any obstruction all the time to evacuate the occupant, in a safe manner, in the event of emergency.

http://www.delhi.gov.in/wps/wcm/connect/doit_fire/FIRE/Home/Fire+Safety+Acts+and+Rules/ http://www.delhi.gov.in/wps/wcm/connect/doit_fire/FIRE/Home/Forms

CAUSDAIMENT OF NATIONAL PAINTY

N/19

			TION REPORT	alle a			
. N	ame & address of the building	M/s Café De Flora A unit of Mehar Wing Services Pvt. Ltd. located at T-302-A, 3 rd floor, Ambience Mall, 2 Nelson Mandela Marg, Vasant Kunj, Delhi-110070.					
2. T	ype of Occupancy	Assembly Building					
3. C	Comprised of building	Three Tire Basements, Ground + 03 upper floors. Ambience Mall Plot No.2, FSC No.F.6/DFS/MS/Mall/2023/SZ/35					
4. Т	Type of Case	New Ca	ase (Café De Flora Restaurant is running in Unit T-302 floor only)				
5. I	Details of Previous NOC	NBC Pa	BC Part-IV				
6. I	Fire Safety directives letter No	N/A	c.				
	Date of inspection	17.09.2025.					
8. 1	Name of Inspecting Officer	A. K. Sharma, ADO (Rohini)					
	Name and designation of officers From the building side		ay Bajaj	0			
10.	Year of Construction	2010 on MCD Portal					
	Applicant's letter No.		application No.202:	5083013022 dated 03.0	9.2025. Remarks		
S.	Minimum Standards on fire prev		UBBL/NBC Requirement	Provided at site	MR/NMR		
1.	Access to building (Ambience Mall FSC I		F.6/DFS/MS/Mall/2	023/SZ/35 Dated 25/0	1/2023)		
	Road width		8-				
_ }	Gate width		Restaurant within	As Above	MR		
- 1	Width of internal road		Mall				
			20/4/2009				
2.	Number, Width, Type & Arrangement of		Exits [Provided &	Maintained by Mall m	anagement		
	a. Number of staircases			1 (4.5) (4.1)	NA		
	Upper Floors		Restaurant in mall	As Above	NA NA		
	Basements		Restaurant in mall	As Above	NA		
	b. Width of staircases			per cr	1 274		
	Upper Floor		Restaurant in mall	As Above	NA		
	Basements		Restaurant in mall		NA		
*			[Provided &	Maintained by Mall m			
	Fire check door		Required	Provided	MR		
			Restaurant in mall	As Above	NA		
	4 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1		Restaurant in mall	As Above	NA		
	d. No. of continuous staircases to e. Width of Corridor		Restaurant in mall	As Above	NA		
	f. Door Size		Required	1.5m x 2 & 1m	MR		
2	Compartmentation			s			
3.	a) Fire check door		Required	Provided	MR		
			Restaurant in mall	As Above	NA		
	b) Sealing of electrical shafts		Restaurant in mall		NA		
	c) Fire Rating of shaft door d) Water Curtain		Restaurant in mall		NA		
			Restaurant in mall		NA		
_	e) Fire Dampers		[Provided & Maintained by Mall management]				
4.	Smoke Management System		Restaurant in mall		NA NA		
	a) Basements		Restaurant in mall	A	NA		
	b) Upper floors		Restaurant in man	110.100.0	B. (5)		
5.			06nos.	Provided	MR		
	a) Total numbers			ABC/CO2	MR		
	b) Types		ABC/CO2	TOTAL ROLL	MR		
1	c) IS marking		ISI marked	Yes	1411		

6.	First-Aid Hose Reel	(Dec-23-3 o 5-					
7.	a) Total numbers on each floor	Noor to poster	intained by Mall mar	agement			
	b) Length of hose reel hose	Near to restaurant 30mm	Provided	MR			
	c) Nozzle diameter	5m	Provided	MR			
7.	Automatic fire detection and alarming sy		Provided				
2.6	a) Type of detectors						
	b) Location of Main Panel	Restaurant in mall	Provided	MR			
	c) Location of Repeater Panel	Restaurant in mail	As Above	NA			
	d) Alternate source of power	Restaurant in mail	As Above	NA			
	e) Hooters' Location	Common area's	As Above	NA			
8.	MOEFA		Provided	MR			
9.	Public Address System	Required Restaurant in mall	Provided	MR			
10.	Automatic Sprinkler System		As Above	NIA			
	a) Basement						
	b) Ground & Upper Floors	110-	As Above	NA			
	c) Sprinkler above false ceiling	Restaurant in mall	As Above	NA			
11.	Internal Hydrants	Restaurant in mall	As Above	NA			
oma#EIV	a) Size of riser/down-comer	Postswert					
	b) Number of hydrants per floor	Restaurant in mall	As Above	NA			
	c) Hose Box	Restaurant in mall	As Above	NA			
12.	Yard Hydrants	Restaurant in mall	As Above	NA			
	a) Total number of hydrants	[Provided & Maintai	ined by Mall managem	ent]			
	b) Hose Box	Restaurant in mall	As Above	NA			
13.		Restaurant in mall	As Above	NA			
	- Country of the coun						
	C accessional contra	Restaurant in mall	As Above	NA			
	Discharge of main PumpHead of Main pump	Restaurant in mall	4500lpm	NA			
	Number of main pumps	Restaurant in mall	70m	NA			
	> Jockey Pump out put	Restaurant in mall	02nos.	NA			
	> Jockey pump head	Restaurant in mall	450lpm	NA			
	> Standby Pump out put	Restaurant in mall	70m	NA			
	> Standby Pump Head	Restaurant in mall	4500lpm	NA			
	Auto Starting/Manual Stopping	Restaurant in mall	70m	NA			
	> Pump House Access	Restaurant in mall	As Above	NA			
	Terrace level	Restaurant in mall	As Above	NA			
				- P ME			
	- sommings of pump	Restaurant in mall	As Above	NA			
	or the pump	Restaurant in mall	As Above	NA			
	➤ Power Supply ➤ Auto Starting of pump	Restaurant in mall	As Above	NA			
14.	OI DUIID	Restaurant in mall	As Above	NA			
	Captive Water Storage for fire fighting [Provided & Maintained by Mall management]						
	Underground tank capacity	Restaurant in mall	5,00,000ltr	NA			
	Draw-off connection	Restaurant in mall	As Above	1			
	Fire service inlet	Restaurant in mall		NA			
	Access to tank	Restaurant in mall	As Above	NA			
	Overhead Tank capacity	No. of the last of	As Above	NA			
15.	Exit Signage.	Restaurant in mall	20,000ltr	NA			
16.	Provision of Lifts.	Required	Provided	MR			
		[Provided & M	faintained by Mall mar	nagement			
	The state of the s	Restaurant in mall	As Above	NA			
	b) Pressurization of Lift lobby	Restaurant in mall	As Above	NA			

V .	c) Communicati	13				
3	c) Communication In lift Car d) Fireman's Grounding Switch e) Lift Signage					
	e) Lift Sign	Restaurant in mall	As Above	NA		
17.	Standby power supply Refuge Area.	Restaurant in mall	As Above	NA NA		
18.		Restaurant in mall	As Above	NA NA		
-	Area.	Restaurant in mall	As Above	NA NA		
	a) Total Area	[Provided & Maintained by Mall management]				
19.	b) Location	Restaurant in mall	As Above			
19.	Fire Control Room	Restaurant in mall	As Above	NA NA		
	a) Detector System Panel Restaurant in a 11					
	b) Flow Switch Panel	Restaurant in mall	As Above	NA		
	c) PA System Panel	Restaurant in mall	As Above	NA NA		
	d) Battery backup	Restaurant in mall	As Above	NA NA		
	e) Building Floor Plans	Restaurant in mall	As Above	NA NA		
20.	Special Fire Production	Restaurant in mall	As Above	NA		
	Special Fire Protection System for Protection of special Risks, if any:	Restaurant in mall	As Above	NA NA		
	Accordingly the fire and di					

Accordingly, the fire protection systems provided in the building were tested/ checked randomly and found in working condition at the time of inspection.

Keeping in view the substantial compliance of the minimum standards on fire prevention and fire safety required under the rules it is recommended to grant Fire Safety Certificate under rule 35 of the Delhi Fire Service Rule 2010.

Signature of the Inspecting Officer Name: - Ajay Kumar Sharma Designation:- ADO/Rohini

DO(\$6) Mulernisher

Principal Director

Ofo to Jone

Grospo migisors

ADO (Rohini)

Fi lette to put up for third poured and sign Please.

uplander,