GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEAD QUARTERS: DELHI FIRE SERVICE, NEW DELHI-110001

No. F6/DFS/MS/NDZ/GH/2025/ 462

-331, 1st ---

FIRE SAFETY CERTIFICATE

Certified that M/s Clay Inn (A unit of Inn Hospitality), located at A-331, 1st , 2nd & 3rd Floors, Meera Bagh, Paschim Vihar, New Delhi-110087, is running at upper ground floor + 03 upper floors, upper ground floor (reception + waiting lounge), 1st floor (08 guest rooms), 2nd floor (08 guest rooms) & 3rd floor (09 guest rooms), in a building comprised of basement + stilt + upper ground + 03 upper floors, total 25 guest rooms, was issued FSC vide letter no. F6/DFS/MS/GH/2022/WZ/316 dated 29/06/2022. Now the premises was re-inspected by the officer concerned of this department on 24/07/2025 in the presence of Sh. Kanwal Preet Singh and found that the premises have deemed complied with the fire prevention and fire safety requirements in accordance with Rule 33 of the Delhi Fire service Rules, 2010 and the building/premises is fit for occupancy class Residential, (Sub Division A-1), upper ground floor + 03 upper floors, upper ground floor (reception + waiting lounge), 1st floor (08 guest rooms), 2nd floor (08 guest rooms) & 3rd floor (09 guest rooms), (total 25 guest rooms up to 3rd floor only), valid up to 31/03/2028 in accordance with Rule 36 unless renewed under Rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under Rule 38 of the Delhi Fire Service Rules, 2010 conditions mentioned below.

Issued on .Q.l. OS. J. 200.25... at New Delhi by.

(Chief Fire Officer)

Copy to: -

- 1. The Dy. Health Officer, MCD, West Zone, Vishal Enclave, Rajouri Garden, New31110027. (dhowest zone@gmail.com) Online application dated 03/07/2025.
- 2. The Owner/ Occupier, M/s Clay Inn (A unit of Inn Hospitality), located at A-331, 1st, 2nd & 3rd Floors, Meera Bagh, Paschim Vihar, New Delhi-110087.

Conditions for the validity of FSC:-

- 1. All the means of escape shall be kept free of all type of obstruction all the time. Any staircase may not be locked/blocked for the safe evacuation of occupants in case of any emergency.
- 2. All the employees shall be acquainted with the use and maintenance of all fire equipments and methods of smooth and speedy safe evacuation of occupants in case of emergency.
- 3. All the fire safety equipments shall be maintained in good working condition at all time and any lapse rendering non-functional of fire safety measures, management shall be responsible.
- 4. Any deviations w.r.t. construction, occupancy changement, electric installation etc. may be got verified from the concerned building sanctioning agency.
- 5. The certificate may not be treated in any case for the regularization of the unauthorized construction, if any.
- 6. All comments/directions of licensing department shall always be permitted and followed.
- 7. The owner/ occupier shall apply for renewal of this Fire Safety Certificate to the Director in Form 'J' [sub rule (1) of rule 37] along with a copy of this certificate, six months prior to its expiry.
- 8. The owner/occupier shall submit a declaration every year in the form 'K' provided in the first schedule of Delhi Fire Service Rules 2010, form is available on www.dfs.delhigovt.nic.in.
- 9. Basement shall be used as per UBBL.

N	14	in a

				CTION REP		E II	
W	Name &	address of the building	M/s Cl	lay Inn (A un	it of In	Hospitality), located a	t A-331 15
			- ~	J 110015.	Meera	Bagh, Paschim Vihar,	New Delh
_	T-ma of (Nagymánov.					THE DOM
-	Type of (Occupancy	Reside	ential, Sub Di	vision A	A-1 (Guest House)	
_		f previous NOC	Renew	val			
		ety directives letter No	IIDDI	S/MS/GH/20	22/WZ/	316 dated 29/06/2022	
		nspection	24/07/	/NBC Part-IV	/		
		the Inspecting Officers			0.00		
3.		nd designation of	Sh K	eet Singh AD anwal Preet S	U (MN)	
"		from the building side	Jii. IX	aiwai i icci S	ngn		
9.		Construction	2000 ((As per online	applica	ation)	
10.	Applicar	nt's letter No.				5070210821 dated 03/0	7/2025
(rece gues 25 g	eption + st rooms) uest rooi	est house is running at waiting lounge), 1 st floo), in a building comprise ms, was issued FSC vide	r (08 gr ed of ba letter n	uest rooms), sement + stil 10. F6/DFS/N	2 nd floo lt + upj /IS/GH/	or (08 guest rooms) & per ground + 03 upper 2022/WZ/316 dated 29	3 rd floor (floors, to 9/06/2022.
S.	775200 10 10 10 10 10 10 10 10 10 10 10 10 1	mum Standards on fire		uired as per		Provided at site	Remark
No	prevent	tion and fire safety U/R 33	35(6)	of DFS Rule	2010		MR/NM
1		to building		(200-20			1/D
		Road width		06 m	D'	Provided	MR MR
		Gate width		4.5 m	Direc	t accessible from road NA	NA
		Width of internal road		NA		IVA	
2	Numbe	er, Width, Type & Arran	ngement	t of Exits			
	a. Num	ber of staircases	-	00		Provided	MR
		Upper Floors		02		Provided	MR
		Basements	37.4	02		Provided	IVIIC
	b. Wid	th of staircases			- 10	0 0 15	MR
	•	Upper Floors		1.5 m eac		2 m & 1.5 m	MR
	•	Basements	1	1.5 m eac	h .	2 m & 1.5 m	IVIIX
	c. Prot	ection of exits				D 11.1	MR
	•	Fire check door		Required	l	Provided	NA
	•	Pressurization		NA		NA D	MR
	e. No	of continuous staircases to	terrace	.02	7.0	Provided	MR
	f. Wid	th of Corridor		1.8 m		Provided	MR
	g. Doc	or Size		1 m		Provided	IVIK
3	_	partmentation.		L			MR
3	2011	Fire check door		Requir		Provided	NA NA
100		Sealing of electrical shafts		NA		NA	0,022
		Fire Rating of shaft door	- EF	NA		NA	NA
1		Water Curtain		NA		NA	NA
		Fire Dampers		NA		NA	NA
	•						1
4	Smol	ke Management System.		Requir	red	Provided	MR
	•	Basements		Requir		Provided	MR
	•	Upper floors		l			
5	Fire	Extinguishers		10 no	S.	Provided	MR
		Total numbers		CO ₂ , AB		Provided	MR
	•	Types		ISI man		Provided	MR
	•	IS marking		G40-109-107/7 D.X			
- 1	First	-Aid Hose Reels.		01		nanded	MR
1	LHS	Total numbers on each	floor	01		Provided Provided	MR
6	E29 E1	I OTAL HUHIDOLD OF		22112			4744
6		Length of hose reel hos	е	30 r		Provided	MR

-				V			
7	Automatic fire detection and alarming system.						
	Type of detectors	Carbon monoxide/Smok	e Provided	MR			
	 Location of Main Panel 	Required	Provided	MR			
	 Location of Repeater Panel 	Required	Provided				
	Alternate source of power	Required	Provided				
	Hooters' Location	Required	Provided	MR			
8	MOEFA	Required	Provided	MR			
9	Public Address System.	NA	NA	NA NA			
10	Automatic Sprinkler System.	+		IIIA			
10	Basement	Required	Provided	1 100			
	Upper Floor	NA	NA	MR			
	Colombia contractor and a contractor and	NA NA	NA NA	NA			
W. 100	Sprinkler above false ceiling	IVA	NA	NA			
11	Internal Hydrants	100	2 7				
	 Size of riser/down-comer 	100 mm	Provided	MR			
	Number of hydrants per floor	01	Provided	MR			
	Hose Box	Required	Provided	MR			
12	Yard Hydrants.			•			
X	Total number of hydrants	NA	NA	NA			
	Hose Box	NA	NA	NA			
13	Pumping Arrangements.						
	Ground Level						
	 Discharge of main Pump 	NA	NA	NA			
	➤ Head of Main pump	NA	NA	NA			
	Number of main pumps	NA	NA	NA			
	Jockey Pump out put	NA	NA	NA			
	Jockey pump head	NA	NA	NA			
	Standby Pump out put	NA	NA	NA			
	Standby Pump Head	NA	NA	NA			
	Auto Starting/ Manual stopping	. NA	NA	NA			
	Pump House Access	NA	NA	NA			
	Terrace level						
	Discharge of pump	450 LPM	Provided	MR			
	Head of the pump	40 m	Provided	MR			
	Power Supply	Required	Provided	MR			
	Auto Starting of pump	Required	Provided	MR			
14	Captive Water Storage for fire fighting.						
	 Underground tank capacity 	NA	NA	NA			
	Draw-off connection	NA	NA	NA			
	➤ Fire service inlet	NA	NA	NA			
	Access to tank	NA	NA	NA			
	Overhead Tank capacity	15,000 103	Provided	MR			
15	Exit Signage.	Required I	Provided	MR			
16	Provision of Lifts.						
	Pressurization of Lift Shaft		NA	NA			
	• Pressurization of Lift lobby		NA	NA			
	Communication In lift Car		NA	NA			
	 Fireman's Grounding Switch Lift Signage 		NA .	NA			
	Litt Signage	NA I	NA	NA			

		M CONTRACTOR							
	Standby power supply	Required	Provided	MR					
\ \ \	Refuge Area.	Suge Area.							
8	> Total Area	NA	NA	NA					
	> Location	NA	NA	NA					
7	Fire Control Room								
19	Detector System Panel	NA	NA	NA					
	Flow Switch Panel	NA	NA	NA					
	PA System Panel	NA	NA	NA					
- 1	Battery backup	NA	NA	NA					
· ·	Building Floor Plans	NA	NA	NA					
20	Special Fire Protection Systems for Protection of special Risks, if any:	Required	ABC type fire extinguisher provided near electrical panel	MR					

The fire protection systems provided in the building were randomly tested, checked & found functional at the time of inspection.

Keeping in view of the deemed compliance of minimum standards of fire prevention and fire safety measures as required under the rules, the NOC vide letter no F6/DFS/MS/GH/2022/WZ/316 dated 29/06/2022, renewal under the rule 35 of the Delhi Fire Service rules 2010 is recommended.

AROJUN

Signature of the Inspecting Officer Sarabjeet Singh ADO (MN)

Bincipal Director

Sir, F. T is pur up for your kinel persuel & Sir, please. 1 Sep. 1845