



GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEADQUARTERS: DELHI FIRE SERVICE, NEW DELHI-110001

C-84



No. F6/DFS/MS/2026/WZ/EH/ 392

Dated: 23/04/2026

FIRE SAFETY CERTIFICATE

Certified that the M/s Dasaprakash (A unit of DAS Kitchens) located Unit No.G-5, Aggarwal Millenium Tiwoer-1, NSP, Delhi-110034, in the building comprised of 02 Blocks, 1st Block- LG + G + 10 upper floors & 2nd Block- LG + G + 05 upper floors M/s Dasaprakash restaurant is running at Unit No.G-5, ground floor only has already been issued FSC by this department vide letter No. F.6/DFS/MS/EH/WZ/2023/276 dated 01.09.2023. The premises was re-inspected by the team of officers concerned of this department on 11.04.2026 in the presence of Mr. Anurag and found that the said building have deemed complied with the fire prevention and fire safety requirements in accordance with Rule 33 of the Delhi Fire Service Rules, 2010 and that the premises fit for occupancy class "Assembly Building" (Group-D) for Unit No.G-5, ground floor only with effect from 23/04/2026 for a period of three years in accordance with Rule 36 unless renewed under Rule 37 or sooner cancelled under Rule 40 and subjected to compliance of the conditions under Rule 38 of the Delhi Fire Service Rules, 2010.

Issued on 23/04/2026 at New Delhi by


(S. K. Dua)

Chief Fire Officer
Delhi Fire Service

Copy to: -

1. The Commissioner, MCD, Civic centre, New Delhi: to kindly ensure the occupancy as detailed above and deviation in construction if any: Online MCD Portal ID-2026040204155 dated 02.04.2026 & 2026041505075 dated 15/04/2026.
2. The Authorized Signatory, M/s Dasaprakash (A unit of DAS Kitchens) located Unit No.G-5, Aggarwal Millenium Tiwoer-1, NSP, Delhi-110034.

Conditions for the validity of Fire Safety Certificate:

1. All the fire safety arrangement provided there-in shall be maintained in good working conditions at all times.
2. Loss of life or property due to non functional fire safety measure shall be at the responsibility of the management.
3. The trained fire fighting staff should be available round the clock.
4. Any deviation with regard to the construction etc shall be verified by the concerned building sanctioning agency.
5. This certificate cannot be treated in any case for regularizations of unauthorized construction.
6. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director of Form 'J' [sub rule (1) of rule 37] along with a copy of this Certificate, six months prior to its expiry".
7. The owner / occupier shall submit a declaration every year in form "K" provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on
8. All the means of escape shall be kept free of any obstruction all the time to evacuate the occupant, in a safe manner, in the event of emergency.

http://www.delhi.gov.in/wps/wcm/connect/doit_fire/FIRE/Home/Fire+Safety+Acts+and+Rules/ http://www.delhi.gov.in/wps/wcm/connect/doit_fire/FIRE/Home/Forms

INSPECTION REPORT

1. Name & address of the building	M/s Dasaprakash (A unit of DAS Kitchens) located Unit No.G-5, Aggarwal Millenium Tiwoer-1, NSP, Delhi-110034.
2. Type of Occupancy	Assembly
3. Comprised of building	02 Blocks, 1 st Block- LG + G + 10 upper floors & 2 nd Block- LG + G + 05 upper floors.
4. Type of Case	Renewal (M/s Dasaprakash restaurant is running at Unit No.G-5, Ground floor only)
5. Details of Previous NOC	F.6/DFS/MS/EH/WZ/2023/276 dated 01.09.2023 previous name of M/s Punjab Grill (A unit of Lite Bite foods Pvt. Ltd.)
6. Fire Safety directives letter No	-NA-
7. Date of inspection	11.4.2026
8. Name of Inspecting Officer	Rajesh Kumar, DO (W), Ajay Kumar Sharma ADO (Wazirpur)
9. Name and designation of officers From the building side	Mr. Anurag
10. Year of Construction	2015 on MCD Portal
11. Applicant's letter No.	Online application No.2026040204155 dated 02.04.2026. 202604155

S. No	Minimum Standards on fire prevention and fire safety U/R 33	Requirement as per Rule 35 (6) of DFS Rule 2010.	Provided at site	Remarks MR/NMR
1.	Access to building (Aggarwal Millenium Tiwoer-1, NSP, issued FSC vide letter no.F.6/DFS/MS/2024/WZ/583 dated 24.09.2024.)			
	• Road width	06m	Provided	MR
	• Gate width	-NA-	-NA-	-NA-
	• Width of internal road	-NA-	-NA-	-NA-
2.	Number, Width, Type & Arrangement of Exits			
	a. Number of staircases			
	• Upper Floors	-NA-	-NA-	-NA-
	• Basements	-NA-	-NA-	-NA-
	b. Width of staircases			
	• Upper Floor	-NA-	-NA-	-NA-
	• Basements	-NA-	-NA-	-NA-
	c. Protection of exits			
	• Fire check door	-NA-	-NA-	-NA-
	• Pressurization	-NA-	-NA-	-NA-
	d. No. of continuous staircases to terrace	-NA-	-NA-	-NA-
	e. Width of Corridor	-NA-	-NA-	-NA-
	f. Door Size	Old case	Old case	Old case
3.	Compartmentation			
	a) Fire check door	-NA-	-NA-	-NA-
	b) Sealing of electrical shafts	-NA-	-NA-	-NA-
	c) Fire Rating of shaft door	-NA-	-NA-	-NA-
	d) Water Curtain	-NA-	-NA-	-NA-
	e) Fire Dampers	-NA-	-NA-	-NA-
4.	Smoke Management System			
	a) Basements	-NA-	-NA-	-NA-
	b) Upper floors	12 a/c per hour	Provided	MR
5.	Fire Extinguishers			
	a) Total numbers	05nos.	Provided	MR
	b) Types	ABC/CO2	ABC/CO2	MR
	c) IS marking	ISI marked	Yes	MR

6.	First-Aid Hose Reels			
	a) Total numbers on each floor	01nos.	Provided	MR
	b) Length of hose reel hose	30mm	Provided	MR
	c) Nozzle diameter	5m	Provided	MR
7.	Automatic fire detection and alarming system			
	a) Type of detectors	Smoke & Heat	Provided	MR
	b) Location of Main Panel	Required	Provided	MR
	c) Location of Repeater Panel	-NA-	-NA-	-NA-
	d) Alternate source of power	Required	Provided	MR
	e) Hooters' Location	Required	Provided	MR
8.	MOEFA	Required	Provided	MR
9.	Public Address System	-NA-	-NA-	-NA-
10.	Automatic Sprinkler System			
	a) Basement	Required in LG	Provided	MR
	b) Ground & Upper Floors	Required	Provided	MR
	c) Sprinkler above false ceiling	Required	Provided	MR
11.	Internal Hydrants			
	a) Size of riser/down-comer	1500mm	Provided	MR
	b) Number of hydrants per floor	01nos.	Provided	MR
	c) Hose Box	01nos.	Provided	MR
12.	Yard Hydrants			
	a) Total number of hydrants	-NA-	-NA-	-NA-
	b) Hose Box	-NA-	-NA-	-NA-
13.	Pumping Arrangements			
	• Ground Level			
	➤ Discharge of main Pump	Restaurant within building	2850lpm	-NA-
	➤ Head of Main pump	Restaurant within building	75m	-NA-
	➤ Number of main pumps	Restaurant within building	02nos.	-NA-
	➤ Jockey Pump out put	Restaurant within building	220lpm	-NA-
	➤ Jockey pump head	Restaurant within building	75m	-NA-
	➤ Standby Pump out put	Restaurant within building	Provided	-NA-
	➤ Standby Pump Head	Restaurant within building	Provided	-NA-
	➤ Auto Starting/Manual Stopping	Restaurant within building	Provided	MR
	➤ Pump House Access	Restaurant within building	Provided	MR
	Terrace level			
	➤ Discharge of pump	900lpm	Common with the building	MR
	➤ Head of the pump	40m	Common with the building	MR
	➤ Power Supply	Required	Common with the building	MR
	➤ Auto Starting of pump	Required	Common with the building	MR
14.	Captive Water Storage for fire fighting			
	• Underground tank capacity	-NA-	2,00,000ltr	-NA-

N/20

	➤ Draw-off connection	-NA-	Provided	-NA-
	➤ Fire service inlet	Required	Provided	MR
	➤ Access to tank	Required	Provided	MR
	• Overhead Tank capacity	10,000ltr	30,000ltr	MR
15.	Exit Signage.	Required	Provided	MR
16.	Provision of Lifts.			
	a) Pressurization of Lift Shaft	-NA-	-NA-	-NA-
	b) Pressurization of Lift lobby	-NA-	-NA-	-NA-
	c) Communication In lift Car	-NA-	-NA-	-NA-
	d) Fireman's Grounding Switch	-NA-	-NA-	-NA-
	e) Lift Signage	-NA-	-NA-	-NA-
17.	Standby power supply	Required	Provided	MR
18.	Refuge Area.			
	a) Total Area	-NA-	-NA-	-NA-
	b) Location	-NA-	-NA-	-NA-
19.	Fire Control Room			
	a) Detector System Panel	-NA-	-NA-	-NA-
	b) Flow Switch Panel	-NA-	-NA-	-NA-
	c) PA System Panel	-NA-	-NA-	-NA-
	d) Battery backup	-NA-	-NA-	-NA-
	e) Building Floor Plans	-NA-	-NA-	-NA-
20.	Special Fire Protection System for Protection of special Risks, if any:	-NA-	-NA-	-NA-

Accordingly, the fire protection systems provided in the building were tested/ checked randomly and found in working condition at the time of inspection.

In view of the deemed compliance of the minimum standards of the fire prevention and fire safety measures as required under the rules the FSC issued vide letter no. **F.6/DFS/MS/EH/WZ/2023/276** dated **01.09.2023** is recommended for renewal of FSC under rule 37 of the Delhi Fire Service rules 2010.

Signature of the Inspecting Office

Name: - Rajesh Kumar
Designation:- DO/West

Signature of the Inspecting Officer

Name: - Ajay Kumar Sharma
Designation:- ADO (Wazirpur)

CFO/WZ

LVP
13/04/26

R. Director

CFO to Secy,

CFO (WZ)

13/04/26

F.T. please.

ADO (WZ)

LVP
20/04/26

fi little to mtr up
for kind favour and
to