



GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEADQUARTERS: DELHI FIRE SERVICE, NEW DELHI-110001



No: F.6/DFS/MS/School/2026/NZ/ 757

Dated: 06/08/2026

To,

The Principal,
D.A.V. Sr. Sec. School (Govt. Aided),
Samaipur Badli, Delhi-110042.
E Mail ID- davsp1310206@gmail.com

Sub: - Regarding issuance of Fire Safety Certificate in r/o D.A.V. Sr. Sec. School (Govt. Aided) located at Samaipur Badli, Delhi-110042.

Sir,

This has reference to your letter no. DAV/SP/2026/77 dated 10/06/2026 received through outdoor diary no. 2202 dated 11.06.2026 on the subject cited above. In this connection, it is to inform you that the inspection of above said school building has been carried out by officer concerned of this department on 15.07.2026 in presence of Sh. Ajay Kumar to see the compliance of requisite fire safety measures. During the course of inspection it is observed that school building is comprised of Two Blocks interconnected, Block 1- Ground floor and Block 2- Ground plus first floor. Your request for issuance of FSC is rejected due to the following shortcomings:

1. Main gate width found 3.5 m against the required width of 4.5 m as the distance from the main gate to the school building is more than 30 m.
2. There is only one staircase of width 1.25 m provided against the requirement of two staircases having width 1.5 m each, both the staircases shall reach up to the terrace.
3. The class rooms where the strength of students are more than 45, one more door of width 1 m is required.

You are advised to rectify the above-mentioned shortcomings under intimation to this department.

Yours Faithfully

(Dr. S.K. Tomar)
Chief Fire Officer
Delhi Fire Service

Copy to:-

1. Director of Education, Govt. Of NCT of Delhi, Old Secretariat, Delhi.