GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE, NEW DELHI-110001

No. F6/DFS/MS/WZ/2025/College 33

Dated: 15 04 2025

The Director,

Delhi School of Professional Studies & Research,

(DSPSR) at Plot No.9, Institutional Area,

Sector-25, Rohini,

Delhi-110085.

Sub:Issue of FSC in r/o Delhi School of Professional Studies & Research (DSPSR) at Plot No.9, Institutional Area, Sector-25, Rohini, Delhi-110085.
Sir,

Kindly reference to online e-mail dated 07.02.2025, received in this department on the subject cited above. The premise was inspected by the concern nominated authority of this department on 20.03.2025, in presence of Dr. R. S. Singh to ascertain the availability and operability of the fire prevention and fire safety measures. Your request for renewal of FSC is rejected under sub rule (3) of Rule 37 of DFS Rules-2010 due to following reason:

- 1. FCD is provided but some FCD Handle found missing.
- 2. Exhaust fan is found missing at some places in basement.
- 3. Hose reel provided but not functional.
- 4. Automatic sprinkler system in basement provided but not functional.
- One electric pump1620lpm, one stand by pump directly connected to D.G set of 900 LPM & one jockey pump capacity of 180 LPM provided but not functional.
- Terrace Fire pump with capacity 450 LPM provided but not functional against the required capacity of 900 LPM.
- 7. Terrace & ground level pump auto-start was not working.
- 8. The required exit signage are found missing at some places.
- 9. Canteen found running at terrace of 3rd floor.

In this regard as stipulated in sub Rule 37 of DFS Rules, 2010 you may apply with a fresh application for renewal of fire safety certificate under sub-rule (2) on Form "J" with compliance of above shortcomings. The web links for DFS Act-2007/ Rules 2010 & Form "J" are as under: http://www.delhi.gov.in/wps/wcm/connect/doit_fire/FIRE/Home/Forms

Yours faithfully

(Virendra Singh) Chief Fire Officer For DIRECTOR Ph; 011-23414000

Jy.