



GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEADQUARTERS: DELHI FIRE SERVICE, NEW DELHI-110001



No: F.6/DFS/MS/EH/2025/NDZ/ 389

Dated: 30/09/2025

To,

Sh. Rahul Tiwari,
M/s Dhaba Estd. 1986 Delhi,
B-42, 1st floor, Connaught Place,
Delhi- 110001.

Sub:- Regarding renewal of Fire Safety Certificate in r/o M/s Dhaba Estd. 1986
Delhi Restaurant located at B-42, 1st floor, Connaught Place, Delhi- 110001.


Sir,

This has reference to online application received through MCD portal vide ID-2025090113065 dated 10/09/2025 on the subject cited above. In this connection, it is to inform you that the above said assembly building was visited by the officer concerned of this department on 18/09/2025 to see the compliance of requisite fire safety measures. Sh. Himanshu (Manager) was present at the time of inspection. Following shortcoming were observed at the time of inspection.

1. Exit staircase found blocked by reception counter.
2. Detectors found provided but not functional at some places.
3. Terrace level pump not found in auto mode.
4. Exit signage's found removed at some places.

In view of above, the application for renewal of Fire Safety Certificate is not considered at this stage & rejected. The occupancy of the building/ premises in absence of requisites fire safety measures shall be at the risk and liabilities of the owner/ occupier.

Yours Faithfully


29/9/2025
(Virendra Singh)
Chief Fire Officer
