

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI- 110001



Delhi Fire Service

DFS/MS/EH/SZ/2025/ 202

Dated: 20/0.5/ 2

FIRE SAFETY CERTIFICATE

Certified that the Mc Donald's Family Restaurant, running at Ground floor of the building comprised of 03 tier Basement + Ground + 03 upper floors located at Eros Metro Mall, Plot No. -8, Sector - 14, Dwarka, New Delhi - 110075 & was granted Fire Safety Certificate by this department vide letter no. F6/DFS/MS/2022/EH/185 dated 21.06.2022. The building was re-inspected by officer concerned from this department on 10.05.2025 in the presence of Mrs. Kanchan Sharma (Store Manager) and found that the Restaurant has complied with the fire prevention and fire safety requirements in accordance with Rule 33 of Delhi Fire Service Rules, 2010.Accordingly, the said Restaurant is fit for occupancy of Group D "Assembly Building" (Restaurant) with effect from.. 2.9. 25. 2025... and valid upto 31.03.2028 in accordance with Rule 36 unless renewed under Rule 37 or sooner cancelled under Rule 40 and subject to conditions under Rule 38 of Delhi Fire service Rules, 2010 printed below.

Issued on 20/05/2025 at New Delhi by

Reference: etl.mcdonline application no. 2025042907470.

Conditions for the validity of Fire Safety Certificate

1. This Fire Safety Certificate is valid for restaurant at Ground floor only.

2. The means of escape shall be kept unobstructed/unlocked for unhindered evacuation in case of an

3. All the fire safety arrangements provided therein shall be maintained in good working conditions at all

- 4. Any loss of life or property due to non functional fire safety measures shall be at the responsibility of the
- 5. The trained fire fighting staff should be available round the clock.

6. Any deviation w.r.t. construction etc. shall be verified by the concerned building sanctioning authority.

7. This fire safety certificate may not be treated in any case for regularization of unauthorized construction,

8. The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in

9. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in form 'J' [sub rule (I) of rule 37] along with a copy of this Certificate, six month prior to its expiry".

10. Any change in the occupancy shall be intimated to this Deptt. and approval shall be obtained thereto

INSPECTION REPORT

l.	Na	me ar	nd address of the building:	M/s Mc Donald's Family Restaurant located at Ground Floor, Eros Metro Mall, Plot No8, Sector – 14, Dwarka, New Delhi 110075 (FSC issued to the entire Mall in the name of Eros Metro Mall Plot No 8, Sector – 14, Dwarka, New Delhi 110075).				
2.	Ту	pe of	occupancy	Group D "Assemb	ly" (Restaurant)			
3.		-	g comprised of	03 tier Basement + Ground + 03 upper floors. (Restaurant running at Ground floor of the building)				
4.	Type of case:			Danewal				
5.	Details of previous FSC			F6/DFS/MS/2022/EH/185 dated 21.06.2022				
6.	Fire safety directives no.			UBBL/NBC-2016				
7.	Date of inspection:			10.05.2025				
8.	Name of the inspecting officer:			Paiesh Kumar Shukla, ADO (M. Road)				
9.	N	ame a	nd designation of the officer e building side:	Mrs. Kanchan Sharma (Store Manager)				
10	A STATE OF THE STA	ATTACABLE IN CO.		2011				
10	Year of construction: Reference letter no.:			etl.mcdonline application no. 2025042907470				
S. No		Minimum standard of Fire Prevention and Fire Safety U/R		Requirements As per Rules 35 (6)	Provide at site	Remarks MR/NMR		
		33		(6)		1100		
1		100	ess to Building:	20.0 m	Provided	MR NA		
		A	Road width	NA	NA	282000		
		В	Gate width	NA	NA	NA		
	C Width of internal roads			4 of Evite				
2	Number, Width, Type & Arrangement of Exits: Restaurant at Ground floor only							
		A	No. of Staircase:	NA	NA	NA NA		
			a) Upper floor	NIA	NA			
			b) Basements	Restauran	t at Ground floor only	INIA		
		В	Width of the Staircase:	NA	NA	NA NA		
			a) Upper floors	NA	NA	NA		
		The '	b) Basement			INA		
		C	Protection of Exits	NA	NA	NA NA		
			a) fire check door	NA	NA	NA NA		
			b) pressurization No. of continuous staircase	NA	NA	INA.		
		D	to terrace	2	N. A.	NA		
		_	Width of the corridor	NA	NA 2.0 m x 2 nos. &	MR		
		F	Door Size	2.0 m &1.5 m	2.0 m x 2 nos. & 0.82 m	(A) = 1		
_	2	Car	npartmentation:		Provided	MR		
-	3	-	Fire check doors	Required	NA	NA		
		A B	Sealing of horizontal &	NA	INA			
		B	vertical opening	d./	NA	NA		
		C	Fire rating of shaft doors	NA	NA NA	NA		
		D	Water curtain	NA	NA NA	NA		
		E	Fire dampers	NA	141			
-	4	Sn	oke Management System:	1311	NA	NA		
-	*	A	Basements	NA Provinced	Provided	MR		
		B	Restaurant area	Required	110,100			
-	5	Fir	e Extinguishers:	1 San Campus	10 nos.	MR		
-		A	Total numbers	04 nos.	ABC	MR		
			Types	ABC	ISI marked	MR		
		B		ISI marked				

	.74	A	Total no. at each floor	02 nos.	building management	MR		
	-	В	Lanoth of L	02 1105.	exits	14114		
	-	C	Length of hose reel	30 m	30 m	MR		
7	_		Nozzle diameter	5 mm	5 mm	MR		
(Automatic Fire Detection and Alarm System (ADAS): (Provide building management)					ed by		
		A	Type of detectors	NA	Smoke/heat	NA		
		В	Location of main panel	NA NA	Provided	NA		
		C	Location of repeater panel	NA NA	NA	NA NA		
		D	Alternate power source	NA NA	NA NA	NA NA		
		E	Hooter's location	NA NA	Provided	NA NA		
8			EFA:			MR		
9			lic Address System:	Required NA	Provided Provided	NA		
10)].	Auto	omatic Sprinkler System: (Provide	d & maintained	by huilding managen	nent)		
	4	A I	Basement	NA	NA NA	NA		
]	В	Ground floor (Restaurant)	NA	Provided	NA		
	(_	Sprinklers above false ceiling	NA	NA NA	NA		
11	1			The Latinoval	building managemen			
			Size of down comer	100 mm	100 mm	MR		
	I		No. of hydrants per floor	02 nos.	Provided	MR		
	(Hose box	02 nos.	Provided	MR		
12	7	-			building managemen	260,000,000		
	A		Total no. of hydrants	NA NA	Provided Provided	NA		
	В		lose box	NA	Provided	NA		
	A		round Level Discharge & head of main pump	Required	2850 LPM & 70 m	MR		
		b)	Number of main pump	Required	02 nos.	MR		
		c)	Discharge & head of jockey pump	Required	2 x 180 LPM & 70 m	MR		
		d)	Discharge & head of standby pump	Required	2850 LPM & 75 m	MR		
		e) /	Auto starting/ manual stopping	Required	Provided	MR		
	B Terrace Level(Common fire fighting system provided & maintained by buil							
	1 }		nagement) Discharge of terrace pump	450 LPM	Dotton Cristons	MR		
		a)	Discharge of terrace pump	430 LFWI	Better System Provided	IVIK		
			Head of terrace pump	NA	NA	NA		
			Alternate power supply	NA	NA	NA		
			Auto starting of pump	NA	NA	NA		
1			e Water Storage for Fire Fighting	: (Common fire	e tank provided & mai	intained		
	building management) A Underground tank capacity NA 1,00,000 ltrs					NA		
- 1	A		derground tank capacity	Participation of the second	PARTITION CONT.	2002020		
	В		w off connection	NA	Provided	NA		
	C	153556	e service inlet	NA	Provided	NA		
	E	A STATE OF	cess to tank	NA	Provided	NA		
	-	_	erhead tank capacity	20,000 ltrs	Provided	MR		
	D		nage:	Required	Provided	MR		
	Exi	Provision of lift: (Provided & maintained by building management)						
	Exi			NA	NA	NA		
1	Exi Pro	Pres	ssurization of lift shaft					
-	Exi Pro A B	Pres	surization of lift lobby	NA	NA	NA		
	Exit Pro A B	Pres Pres Con	surization of lift lobby nmunication in lift car	NA NA	NA	NA		
	Exit Pro A B C	Pres Pres Con Fire	surization of lift lobby	NA				

18	Refuge Area:						
	A	location	NA	NA	NA		
	В	Total area	NA	NA .	NA		
19	Fire Control Room: (Provided & maintained by building management)						
	A	Fire detection system panel	NA	Provided	NA		
	В	Flow switch panel	NA	Provided	NA		
	C	P a system panel	NA	Provided	NA		
	D	Battery backup	NA	Provided	NA		
4	E	Building floor plan	NA	Provided	NA		
0	Special Fire Protection for special risk if any						
	A	Special Fire Protection system for Protection of Special Risk, if any:	NA	NA NA	NA		

S:-Meeting Requirement (MR), Not Meeting Requirement (NMR), Not Applicable (NA), Not Provided (NP) Provide But Not Functional (PNF).

The fixed fire installation has been provided & maintained by the building management which is common to the entire building. The installed fire system is of higher capacity and category then required for the individual restaurant and same was found functional at the time of inspection.

If agreed to the note above & in view of the decared compliance of minimum standards of fire prevention and fire safety measures as required under the Rules, the FSC issued vide letter no. F6/DFS/MS/2022/EH/185 dated 21.06.2022 is recommended to be renewed under Rule 37 of the Delhi Fire Service Rules 2010.

Signature of the Inspecting Officer Name Rajesh Kumar Shukla Designation ADO (M.Road)

D.Ø(SW)

CEO 12/2 2012

May ple upload

20/5/25

M.S. Cell

29/8/25