



## GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI-110001

NO. F-6/DFS/MS/EH/2024/SZ/95

Dated: 21/02 /2025

To

The Addl. Commissioner of Police, Lic/Branch, 1st Floor PS Defence Colony, New Delhi 110049

Sub: -Regarding issuance of fire safety certificate in r/o M/s ELINA VARA EARTH ROASTERY LLP at Khasra No 595, GF, Gadaipur Sultanpur, Mandi Road, New Delhi 110030.

Sir,

This has reference with MCD Portal ID 2025013001243 dated 30/01/2025 on the subject cited above. In this connection, this is to inform you that the above mentioned premise was visited by the officer concerned of this department on 17.02.2025 in the presence of Mr. Abhishek to verify the present status of fire safety measures installed in the building. The fire safety arrangements were tested / checked and found following observations:-

- 1. The first aid hose reel provided but found not working.
- 2. Internal hydrant provided but found not working.
- 3. Terrace level fire fighting pump capacity 450 LPM provided but found not working.
- 4. Overhead tank capacity 20,000 liters not provided.
- 5. Exit signage found removed at some places.

In view of above Shortcomings, the application for issuance Fire Safety Certificate is rejected. The occupancy of the building/premises in absence of requisite fire safety arrangements shall be at the risk and liability of the owner/occupier. The Licensing authority/ Statutory Authority may take suitable necessary action as deemed fit.

Myn

Yours faithfu

DELHY FIRE SERVICE