## GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE, NEW DELHI-110001



No. F6/DFS/MS/School/WZ/2025/ 6 16

Dated: 07 08 2025

To,

The Principal/Incharge, Flora Convent School, Maharana Pratap Enclave, Pitampura, Delhi-110034.

Sub:

Inspection report in r/o. Flora Convent School, located at Maharana Pratap Enclave,

Pitampura, Delhi-110034.

Sir,

With reference to your letter No. Nil dated 05/06/2025, received through outdoor dairy No. 2487 dated 06/06/2025, on the subject cited above. In this connection, it is to inform you that the said premises was inspected by the officer concerned of this department on 21/07/2025, in the presence of Ms. Geeta (Principal) to see the functioning of the fire safety arrangements/equipment's provided in the building.

During inspection, it has been observed that the said school is running at ground & 1<sup>st</sup> floor, in a building comprised of ground + 01 upper floor, was already issued FSC vide letter No. F6/DFS/MS/School/2018/WZ/1240 dated 28/05/2018. Fire safety arrangements such as, Fire Extinguishers, First Aid Hose Reels, Terrace pump, etc., are provided. However, following shortcomings were observed:-

- 1. First Aid Hose Reels are provided but not functional.
- 2. Terrace fire pump of 220 LPM is provided but not functional.
- 3. Over head water storage tank capacity of 2,500 ltrs found removed.
- 4. Exit Signage are found removed.

In view of above shortcomings, the application for renewal Fire Safety Certificate is rejected. The occupancy of the building/premises in absence of requisite fire safety arrangements shall be at the risk and liability of the owner/occupier.

Yours faithfully,

Virendra Singh (Chief Fire Officer)

Copy To:-

1. The Directorate of Education Old Secretariat Delhi - 110054.

al Jak 31/7/200