GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUATERS: DELHI FIRE SERVICE: NEW DELHI-110001

No: F.6/DFS/MS/School/SZ/2025/ 66 &

Dated: - 21/08/2025

To,

The Manager, Goodwill Public School, G-1 Block, Canara Bank Road, Uttam Nagar, New Delhi-110059.

Sub: - Regarding issuance of "FSC" from fire safety point of view in r/o Goodwill Public School at G-1 Block, Canara Bank Road, Uttam Nagar, New Delhi- 110059.

Sir,

Please refer to your letter No. GPS/115/06/25 dated 21.06.2025, on the subject cited above. In this connection it is to inform you that the above said school building has been inspected by the officer concerned of this department, in presence of the Manager on dated 16.07.2025, to check the status of the shortcomings already pointed out by this department vide letter No. F.6/DFS/MS/School/2022/SZ/300 dated 10.06.2022. During the course of inspection, it was observed that the shortcomings are not fully complied.

In view of the above issuance of 'Fire Safety Certificate' cannot be granted at this stage. You are requested to rectify the above-mentioned shortcomings under intimation to this department for taking further necessary action in this matter and running school in absence of requisite fire safety arrangements shall be at the risk & liability of the school management.

Yours faithfully

(Virendra Singh) Chief Fire Officer

Copy for information:-

1. Director of Education, Govt. of NCT of Delhi, Old Secretariat, New Delhi – 110054 –For necessary action in above matter.

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI **HEADQUARTERS: DELHI FIRE SERVICE, NEW DELHI-110001**

No: F.6/DFS/MS/School/2022/SZ/ 360

Dated: 10/06/2022

To,

The Principal, Goodwill Public School, G-1 Block, Canara Bank Road, Uttam Nagar, New Delhi-59.

Sub: - Regarding issuance of Fire Safety Certificate in r/o. Goodwill Public School, G-1 Block, Canara Bank Road, Uttam Nagar, New Delhi-59.

Sir,

This has reference to your Letter No. Nil dated 24/05/2022 on the subject cited above. In this connection this is to inform you that officer concerned of this department inspected the school on 31/05/2022 to verify the fire safety arrangements in accordance with the Rules. At the time of inspection Sh.Inderpal Gupta (Manager) was present and it was observed that the school building is comprised of ground plus three upper floors but school running at ground plus two upper floors and have following shortcomings.

- 1. Approach road of 06 m width is not provided.
- 2. Both staircases are required to be provided of 1.5 meter wide each.
- 3. Hose reels are not provided.
- 4. Fire pump having 450 lpm not provided at terrace.
- 5. Over head water tank capacity of 10,000 liters not provided.
- 6. Exits signage's are not provided

In view of above, the fire safety certificate cannot be considered at this stage. You are requested to rectify the above shortcoming under the intimation to this department for further course of action.

Delhi Fire Service

Copy to:-.

1. The Director of Education, Govt of NCT of Delhi, Old Secretariat, New Delhi-110054.(with a request to take further action as school does not have fire NOC)