





GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE, NEW DELHI-110001

F.6/DFS/MS/School/2025/SZ/185

Dated: 03 /04 /2025

To

No.

The Head of School, Govt. Co-Ed. Sr. Sec. School, Sector-03, Site-1, Dwarka, New Delhi-110075

Sub: Inspection report in r/o Govt. Co-Ed. Sr. Sec. School, Sector-03, Site-1, Dwarka, New Delhi-110075 (School ID: 11821203)

Sir,

Please refer to the e-mail received from Id. ggsss1821203@gmail.com dated 04.02.2025. In this connection, it is to inform you that the premise was inspected by the officer concerned of this department from fire safety point of view on 17/03/2025 in the presence of Sh. Dayal Paul (Estate Manager). During course of inspection, the shortcomings observed are as below.

- 1. The hose-reel hoses found provided but non-functional.
- 2. Terrace level fire pump provided but non-functional.
- 3. Overhead water storage tank exclusively for firefighting found empty.
- 4. Exit signage found removed at some locations in escape route.

In view of above, application for renewal of fire safety certificate cannot be considered at this stage. You are requested to rectify the shortcomings under intimation to this department for further action in the matter.

Yours fathfully

(ATUL GARG)

Ph. 011-23414000

Copy to: -

1. The Director of Education, Govt. of NCT of Delhi, Old Secretariat, New Delhi-110054.