

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI-110001

No. F.6/DFS/MS/2025/SZ/422

Dated: 11../.08.../2025

FIRE SAFETY CERTIFICATE

Certified that the M/s Guru Nanak foundation at 15-16 Qutab Institutional Area, Shaheed Jeet Singh Marg, Near Qutab Hotel New Delhi 110067 comprised of A-Wing (Ground plus 04 upper floors) B-Wing (Basement, Ground plus 04 upper floors) owned/occupied by Guru Nanak foundation was issued Fire Safety Certificate by this department vide letter No. F6/MS/DFS/93/110 dated 21/01/1993 (Clearance of 12 base minimum fire Safety point/ standard). The premise was re-inspected by the officers concerned of this department on 15/07/2025 in the presence of Mr. Rajender Singh (Admin) and found that the said building have deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of Delhi Fire Service Rules, 2010 and that the premises is fit for occupancy class "Business Group-E" with effect from 11 06 2025 for a period of Three years in accordance with Rule 36 unless renewed under Rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under Rule 38 of the Delhi Fire Service Rules, 2010.

(VIRENDRA SINGH) CHIEF FIRE OFFICER DELHI FIRE SERVICE

Copy to: -

1. M/s Guru Nanak foundation at 15-16 Qutab Institutional Area, Shaheed Jeet Singh Marg, Near Qutab Hotel New Delhi 110067

Conditions for the validity of Fire Safety Certificate:

- All the fire safety arrangement provided therein shall be maintained in good working condition at all time as seen during inspection. Any loss of life property due to nonfunctional fire safety measures shall be at the responsibility of the management.
- 2. The Building sanctioning authority may verify any deviation with regard to the construction/occupancy in the building. In case of any deviation, the fire safety certificate stands null and void.
- 3. The basement shall be used as per the provisions of BBL /NBC Part- IV.
- 4. All the staff members must know the correct method of operation of fire fighting system.
- 5. The owner/occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in
- 6. This fire safety certificate may not in any way be treated as regularization (Clause 2.8 of UBBL-2016) of unauthorized construction or Alteration (Clause 1.4.3 of UBBL-2016), if any.
- 7. "The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in form 'J' [sub rule (I) of rule 37] along with a copy of this Certificate, six month prior to its expiry." The form is available on www.dfs.delhigovt.nic.in



	INSPECTIO	N REPORT	Liv i h		
1	Name & Address of the Building	Guru Nanak foundation at 15-16 Qutab Institutiona Area, Shaheed Jeet Singh Marg, Near Qutab Hote New Delhi 110067			
2	Type of Occupancy	Class- E "Business"			
3	Building Comprised of				
3	7	A-Wing (Ground plus 04 upper floors) B-Wing (Basement, Ground plus 04 upper floors)			
4	Type of Case	Renewal			
5	Details of Previous NOC	F6/MS/DFS/93/110 dated 21/01/1993			
6	Fire Safety Directives Letter No	Clearance of 12 base minimum fire Safety point/ standard)			
7	Date of Inspection	15/07/2025	111		
8	Name of the Inspecting Officers	ADO (BCP)			
9	Name & Designation of Officers from the building side	Mr. Rajender Singh (Admin)			
10	Year of construction	1991			
11	Applicant letter No.	GNF/DFS/7751	dated 16/05/2025		
S. No.	Minimum standards on Fire Prevention and Fire Safety U/R 33	12 base min. Requirements	Provided at Site	Remarks MR/NMF	
1	Access to Building.		TWO IS TO SEE		
1	Road width	Accessible	Accessible	MR	
	Road width Gate width	Accessible	Accessible	MR	
		-NA-	-NA-	-NA-	
	Width of internal road		- H- I,		
2	Number, width, type & arrangement of e	XIIS.			
	a) Number of Staircase	03 No	Provided	MR	
	Upper floors.	01 No	Provided	MR	
	> Basement floor.	01 100	Tionas		
	b) Width of Staircase	Required	Provided	MR	
	> Upper floors	Required	Provided	MR	
	> Basement floor	Required	The latest the second		
	c) Protection of exits	Required	Provided	MR	
	> Fire check door	Required	Provided	MR	
	> Pressurization	Required 02 No's	Provided	MR	
	d) No. of continuous staircase to terrace	-NA-	-NA-	-NA-	
	e) Width of corridor	Required	Provided	MR	
	f) Door size				
3	Compartmentation. • Fire check door.	Required	Provided	MR	
	 Fire check door. Sealing of electrical shafts. 	-NA-	-NA-	-NA-	
	Sealing of electrical sharts. Fire rating of shaft door.	-NA-	-NA-	-NA-	
	Water curtain	-NA-	-NA-	-NA-	
	Fire dampers.	-NA-	-NA-	-NA-	
	Smoke Management system.	T R-		1 334	
4		-NA-	-NA-	-NA-	
	10 mm and 10 mm	12 ACPH	Natural ventilation	MR	
-	The state of the s	CLL - DI	Ty fire a second of	MR	
5	Total numbers	83.191	29 No's	MR	
	Types	ISI marked	ABC, CO2 & W.CO2	MR	
	ISI Marking		Provided	IVIIX	
-	LALEY Deals		Descrided	MR	
6	Total numbers on each floor.	02 Nos each	Provided Provided	MR	
	Length of hose-reel hose.	Hose-reels		MR	
	Nozzle Diameter	11030 10010	Provided	IVIK	
	Automatic fire detection & alarming system			3.00	
7	Automatic tire detection & and imag system		Provided	MR	
	Type of detectors Location of Main Panel	Required	Provided	MR MR	
	Location of Main Panel Location of Repeater Panel	Required	Provided	IVIK	

4/21

ाजादीका अमृत महोत्सव

	K/g,			
	Alternate source of power	Required	Provided	MR
8	Hooter's location	Required	Provided	MR
9	MOEFA	Required	Provided	MR
10	Public Address System	Required	Provided	MR
10	Automatic Sprinkler System		odna XII. U	
	Basement	-NA-	150sq mtr	-NA-
	Upper floors	-NA-	-NA-	-NA-
	 Sprinkler above false ceiling 	-NA-	-NA-	-NA-
11	Internal Hydrants.			
	 Size of Riser/Down-comer 	150 mm	Provided	MR
	Number of Hydrant per floor	02 no each	Provided	MR
	Hose box.	02 no each	Provided	MR
12	Yard Hydrants.	02 Ho each		
	Total number of hydrants.	-NA-	-NA-	-NA-
	Hose box.			-NA-
13		-NA-	-NA-	-1N/A-
13	Pumping arrangements.			
	Ground Level Discharge of main pump	2400 7 72 7	Descrided	MR
	Discharge of main pump.Head of main pump.	2400 LPM	Provided Provided	MR
	Number of main pumps.	60m	Provided	MR
	Jockey Pump output.	01	Provided	MR
	Jockey Pump head.	450 LPM 60m	Provided	MR
	Standby Pump output.	2400 LPM	Provided	MR
	Standby Pump head.	60m	Provided	MR
	➤ Auto Starting/Manual Stopping	Required	Provided	MR
	Pump house access	Required	Provided	MR
	Terrace Level		1 MM -	
	Discharge of pump.	450 LPM	Provided	MR
	➤ Head of pump.	40m	Provided	MR
	Power supply.	Required	Provided	MR
	Auto starting of pump.	Required	Provided	MR
14	Captive water storage for fire fighting.	A Zinga (mostare	in institution in the last	
	Underground tank capacity.	1,00,000 ltr (fire Provided		MR
		fighting)	tion of the street contract	
		50,000 ltr (domestic) Required Provided		MR
	Draw-off connection.	Required	Provided	MR
	Fire Service Inlet.	Required	Provided	MR
	Access to tank.	-NA-	-NA-	-NA-
	Overhead tank capacity.	Required	Provided	MR
15	Exit Signage.	Required	11011000	
16	Provision of Lifts.	Required	Provided	MR
	Pressurization of lift shaft.	Required	Provided	MR
	Pressurization of lift lobby.	-NA-	-NA-	-NA-
	Communication in lift car.	-NA-	-NA-	-NA-
	Fireman's switch.	-NA-	-NA-	-NA-
μFΣ	Lift signage.		Provided (125 KVA)	MR
17	Standby Power Supply	Required	11 s 1707 1 1 161 4	
18	Refuge Area	-NA-	-NA-	-NA-
17	Total area	-NA-	-NA-	-NA-
	• Location	-INA-	1111	

19	Fire Control Room.	भाजादी का अमृत महोत्सव		
1	Detector system panel.Flow switch panel.	-NA-	-NA-	-NA-
	PA system panel.	-NA-	-NA-	-NA-
1	Battery backup.	-NA-	-NA-	-NA-
	Building floor plan.	-NA-	-NA-	-NA-
20	Special Fine Ductoralia C	-NA-	-NA-	-NA-
20	Special Fire Protection System for the Protection of special Risk, if any.	-NA-		-NA-

The fire protection system provided in the building were randomly checked and found functional at the time of inspection. The pre-school is being run by dreaming child on Ground and first floor of wing -A are does not falls under the purview of building specified under sub Rule 4 of Delhi Fire Service Rules, 2010.

Further, the management has complied all the observation / Shortcoming already issued & communicated by this department vide letter of even no 267 dated 09/06/2025.

Keeping in view of the deemed compliance of the minimum standard on fire prevention and fire safety measures as required under the rules, the FSC issued vide letter no F6/MS/DFS/93/110 dated 21/01/1993, renewal under rule 37 of the Delhi Fire Service rules, 2010 is recommended.

Accordingly, DFA is put up for approval and signature please.

Signature of the Inspecting Officer Name: Sh. Rajesh Kumar Design: ADO (BCP)

DO (South) Miller 20/7)
2017/ 2015

Principal Director

Of the Same

Thy sors

ADO(ACE) F.1. Letter

is putub

for your signal

n

(folted/ 5/0/2005

nsul