0/26

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS, DELHI FIRE SERVICE, NEW DELHI

No. F6/DFS/MS/EH/NDZ/2025/ 157

Dated: 09/04/2015

To,

The Joint Commissioner of Police, Licensing Unit, 1st floor, Police Station, Defence Colony, New Delhi. addlcp.lic-dl@nic.in

Sub: Regarding renewal of fire safety certificate in respect of Haldiram (Haldiram Ethnic foods Pvt. Ltd.), located at GF. G3, Dilshad Garden Main Metro Station, Shahdara, Delhi-110095.

Sir,

Please refer to your online application no. 2025031003222 dated 11/03/2025on the subject cited above. In this connection, it is to inform you that the premises was inspected by officer concerned of this department on 24/03/2025 in the presence of Sh. Devender (HR.Maintenance) to see the functioning of fire safety equipments provided in the building.

During inspection, it has been observed that the above restaurant is running at Ground Floor in DMRC Mall Dilshad Garden Metro Station comprised of Ground + 02 upper floors. Fire safety arrangements such as Fire Extinguishers, MOEFA etc provided. However the following shortcomings were observed.

- 1. First Aid Hose reels are provided but not functional
- 2. Internal Hydrants are provided but not functional.
- 3. Smoke management system is found removed.

In view of above Shortcomings, the application for renewal of Fire safety Certificate is rejected. The occupancy of the Building/premises in absence of requisites fire safety arrangements shall be at the risk and liabilities of the Owner/occupier. The licensing issuing authority/statutory authority is requested that premises should not be allowed to run till it provided all necessary fire arrangements.

Yours faithfully

Copy to: -

1. The Dy. Health Officer, MCD, South Zone, Shahdara, Karkardooma, Delhi.

 The Owner/Occupier, Haldiram (Haldiram Ethnic foods Pvt. Ltd.), located at GF. G3, Dilshad Garden Main Metro Station, Shahdara, Delhi-110095.