

**GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI**  
**HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI-110001**

No. F.6/DFS/MS/EH/2025/SZ/171

Dated: 06/05/2025

**FIRE SAFETY CERTIFICATE**

Certified that the Eating House in the Name & Style of **M/s Haldiram Marketing Pvt Ltd** located at JA001 to JA005, Ground Floor, Plot No 10, DLF Tower District Centre Jasola New Delhi 110025 in the building comprised of 03 tiers Basement, Ground plus 12 Upper floors owner/occupied by M/s Haldiram Marketing Pvt Ltd was issued FSC by this department vide letter F6/DFS/MS/EH/SZ/2022/291 dated 18/10/2022. The restaurant premise was re-inspected by the officers concerned of this department on 01/05/2025 in the presence of Mr. Shivadhu and found that the said restaurant premises have deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rule, 2010 and that the building/premises is fit for occupancy **Class-D "Assembly Building"** and **validity upto 31/03/2028** in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules, 2010.

Issued on 06/05/2025 at New Delhi by

(ATUL GARG)  
DIRECTOR  
DELHI FIRE SERVICE

Copy to: -

1. The Addl. Commissioner of Police, Lic/Branch 1st Floor PS Defence Colony, New Delhi 110049 (Ref. MCD Portal ID 2025040105576 dated 08/04/2025)

**Conditions for the validity of Fire Safety Certificate: -**

1. All the means of escape/entry/exit shall be kept free from any obstruction.
2. All the fire safety arrangements provided therein shall be maintained in good working condition at all time as seen during inspection. Any loss of life or property due to non-functional fire safety measures shall be at the responsibility of the management.
3. All the staff members must know the correct method of operation of fire-fighting system.
4. The owner/ occupier shall submit a declaration every year in Form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on [www.dfs.delhigovt.nic.in](http://www.dfs.delhigovt.nic.in)
5. This fire safety certificate may not in any way be treated as regularization (Clause 2.8 of UBL-2016) of unauthorized construction or alteration (Clause 1.4.3 of UBL-2016), if any.
6. "The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in Form 'J' [sub rule (1) of rule 37] along with a copy of this Certificate, six months prior to its expiry."

N/5

## INSPECTION REPORT

1	Name & Address of the Building	M/s Haldiram Marketing Pvt Ltd at JA001 to JA005, Plot No 10, Ground Floor, DLF Tower District Centre Jasola New Delhi 110025.		
2	Type of Occupancy	Restaurant is running at Ground floor only		
3	Building Comprised of	03 tier Basements, Ground + 12 Upper Floors		
4	Type of Case	Renewal		
5	Details of Previous NOC	F6/DFS/MS/EH/SZ/2022/291 dated 18/10/2022		
6	Fire Safety Directives Letter No	F.6/MS/DFS/Mixed/SZ/2024/602 dated 03/10/2024 DLF Tower District Centre Jasola		
7	Date of Inspection	01/05/2025		
8	Name of the Inspecting Officers	ADO (BCP)		
9	Name & Designation of Officers from the building side	Mr. Mr. Shivadhu		
10	Year of construction	2007		
11	Applicant letter No.	MCD Portal ID 2025040105576 dated 08/04/2025		
S. No.	Minimum standards on Fire Prevention and Fire Safety U/R 33	Requirement/ Existing Fire Protection	Provided at Site	Remarks MR/NMR
1	Access to Building.	( F.6/MS/DFS/Mixed/SZ/2024/602 dated 03/10/2024 DLF Tower )		
	• Road width	06 m	Provided*	MR
	• Gate width	7m	Provided*	MR
	• Width of internal road	6m	Provided*	MR
2	Number, width, type & arrangement of exits.	Provided & Maintained by DLF Tower		
	a) Number of Staircase	Provided & Maintained by DLF Tower		
	➤ Upper floors.	NA	Provided*	NA
	➤ Basement floor.	N/A	N/A	N/A
	b) Width of Staircase	Provided & Maintained by DLF Tower		
	➤ Upper floors	NA	Provided*	NA
	➤ Basement floor	N/A	N/A	N/A
	c) Protection of exits	Provided & Maintained by DLF Tower		
	➤ Fire check door	NA	Provided*	NA
	➤ Pressurization	N/A	Provided*	N/A
	d) No. of continuous staircase to terrace	Restt within Mall	Provided*	MR
	e) Width of corridor	N/A	N/A	N/A
	f) Door size	1.50 mtr each	1.50 mtr each	MR
3	Compartmentation.	Provided & Maintained by DLF Tower		
	• Fire check door.	Restt within Mall	Provided*	MR
	• Sealing of electrical shafts.	Restt within Mall	Provided*	MR
	• Fire rating of shaft door.	N/A	N/A	N/A
	• Water curtain	N/A	N/A	N/A
	• Fire dampers.	N/A	N/A	N/A
4	Smoke Management system.	Provided & Maintained by DLF Tower		
	• Basement	30 ACPH	N/A	N/A
	• Upper floors	12 ACPH	Exhaust Fans Provided	MR
5	Fire Extinguishers.	Provided & Maintained by DLF Tower		
	• Total numbers	Required	06 Nos	MR
	• Types	ABC/CO <sub>2</sub>	ABC & CO <sub>2</sub>	MR
	• ISI Marking	Required	Provided	MR
6	First Aid Hose Reels.	Provided & Maintained by DLF Tower		
	• Total numbers on each floor.	One near Restt	Provided*	MR
	• Length of hose-reel hose.	30m	Provided*	MR
	• Nozzle Diameter	5mm	Provided*	MR
7	Automatic fire detection & alarming system.	(Provided & Maintained by DLF Tower)		
	• Type of detectors	Required	Smoke & heat	MR
	• Location of Main Panel	Required	Provided*	MR
	• Location of Repeater Panel	Required	Provided*	MR
	• Alternate source of power	Required	Provided*	MR
	• Hooter's location	Required	Provided*	MR



8	MOEFA	Required	Provided	
9	Public Address System	N/A	As above	
10	Automatic Sprinkler System	Provided & Maintained by DLF Tower		
	• Basement	Required	Provided*	MR
	• Ground floor.	Required	Provided*	MR
	• Sprinkler above false ceiling	N/A	N/A	MR
11	Internal Hydrants.	Provided & Maintained by DLF Tower		
	• Size of Riser/Down-comer	Required	Substituted by 02 Nos of yard hydrant	MR
	• Number of Hydrant per floor	One near Restt	Substituted by 02 Nos of yard hydrant	MR
	• Hose box.	One near Restt	Substituted by 02 Nos of yard hydrant	MR
12	Yard Hydrants.	Provided & Maintained by DLF Tower		
	• Total number of hydrants.	Required	Provided*	MR
	• Hose box.	Required	Provided*	MR
13	Pumping arrangements.	Provided & Maintained by DLF Tower		
	• Ground Level	Common pumping arrangements for entire bldg		
	➤ Discharge of main pump.	2280 LPM	4500 LPM	MR
	➤ Head of main pump.	105m	105m	MR
	➤ Number of main pumps.	02 Nos.	02 Nos.	MR
	➤ Jockey Pump output.	180 LPM	180 LPM	MR
	➤ Jockey Pump head.	105m	105m	MR
	➤ Standby Pump output.	2280 LPM	4500 LPM	MR
	➤ Standby Pump head.	105m	105m	MR
	➤ Auto Starting/Manual Stopping.	Required	Provided	MR
	➤ Pump house access.	Required	Provided	MR
	• Terrace Level			
	➤ Discharge of pump.	450 LPM	Provided*	MR
	➤ Head of pump.	40 m	Provided*	MR
	➤ Power supply.	Required	Provided*	MR
	➤ Auto starting of pump.	Required	Provided*	MR
14	Captive water storage for fire fighting.	Provided & Maintained by DLF Tower		
	• Underground tank capacity.	Required	2,00,000 Ltrs	MR
	➤ Draw-off connection.	Required	Provided	MR
	➤ Fire Service Inlet.	Required	Provided	MR
	➤ Access to tank.	Required	Provided	MR
	• Overhead tank capacity.	20,000 ltr	20,000 Ltrs	MR
15	Exit Signage.	Required	Provided	MR
16	Provision of Lifts.	Provided & Maintained by DLF Tower		
	• Pressurization of lift shaft.	Required	Provided*	MR
	• Pressurization of lift lobby.	Required	Provided*	MR
	• Communication in lift car.	Required	Provided*	MR
	• Fireman's switch.	Required	Provided*	MR
	• Lift signage.	Required	Provided*	MR
17	Standby Power Supply	Required	Provided	MR
18	Refuge Area			
	• Total area	N/A	N/A	N/A
	• Location	N/A	N/A	N/A
19	Fire Control Room.	Provided & Maintained by DLF Tower		
	• Detector system panel.	N/A	Provided*	N/A
	• Flow switch panel.	N/A	Provided*	N/A
	• PA system panel.	N/A	Provided*	N/A
	• Battery backup.	N/A	Provided*	N/A
	• Building floor plan.	N/A	Provided*	N/A

Special Fire Protection System for the  
Protection of special Risk, if any.

N/A

Provided\*

N/A

The Fire protection systems provided in the premises were test checked at random and found functional at the time of inspection.

Keeping in view of the deemed compliance of the minimum standard on fire prevention and fire safety measures as required under the rules, the FSC issued vide letter no F6/DFS/MS/EH/SZ/2022/291 dated 18/10/2022, renewal under rule 37 of the Delhi Fire Service rules, 2010 is recommended.

Accordingly, DFA is put up for approval and signature please.

*[Signature]*  
02/05/25

Signature of the Inspecting Officer

Name: Sh. Rajesh Kumar

Design: ADO (BCP)

DO (SD)

*[Signature]*  
02/05/25

*[Signature]*  
02/05/25

*[Signature]*  
02/05/25

Director

*[Signature]*  
02/05/25

*[Signature]*

*[Signature]*  
02/05/25

*[Signature]*