



No.F6/DFS/MS/EH/NDZ/2025/ 38

Dated: 30/01/2025

FIRE SAFETY CERTIFICATE

Certified that the **Haldiram Ethnic Foods Pvt. Ltd.** located at **GF Plot No. G 09 A and Upper Ground 09, Parasnath Games Village Metro Mall Akshardham, Delhi-91** of building comprised of **Lower basement, upper basement, lower ground & upper ground floor** at **Akshardham Metro Station, Delhi** owned/occupied by **M/s Haldiram Ethnic Foods Pvt. Ltd.** was granted FSC by this department vide letter No. **F6/DFS/MS/EH/NDZ/2021/370** dated **14/12/21**. The premises was re-inspected by the officer concerned of this department on **27/01/25** in the presence of **Mr. Kamil (Manager)** and found that the said premises have deemed complied with the fire prevention and fire safety requirements in accordance with Rule 33 of the Delhi Fire Service Rules, 2010 and that the premises fit for occupancy class **Assembly Building Group D, Restaurant running on upper ground floor only** with effect from **30/01/2025** for period of **three years** in accordance with Rule 36 unless renewed under Rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under Rule 38 of the Delhi Fire Service Rules, 2010 printed below.

Issued **30/01/2025** at New Delhi by.

(ATUL GARG)
DIRECTOR
DELHI FIRE SERVICE

Copy to:-

- 1 The Deputy Commissioner (Licensing),
1st Floor, Police Station Defence Colony, New Delhi.
Online application ID no. 2025012100816.
- 2 The Manager,
M/s Haldiram Restaurant,
H-154, Sector-63, Noida, U.P-201307.

Condition for the validity of fire safety certificate

- 1 All the fire safety arrangements provided therein shall be maintained in good working conditions at all times.
- 2 Any loss of life or property due to non functional fire safety measures shall be at the responsibility of the management.
- 3 The trained fire fighting staff should be available round the clock.
- 4 Any deviation w.r.t. construction etc. shall be verified by the concerned building sanctioning authority.
- 5 This fire safety certificate may not be treated in any case for regularization of unauthorized construction, if any.
- 6 The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in
- 7 The means of escape shall be kept unobstructed / unlocked for unhindered evacuation in case of an emergency.
- 8 The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in form 'J' [sub rule (I) of rule 37] along with a copy of this Certificate, six month prior to its expiry".
- 9 Any flammable material for interior decoration is prohibited.

INSPECTION REPORT

1. Name & address of the building Haldiram Ethnics Foods Pvt. Ltd. at GF Plot No. G 09 A and UG 09, Parasnath Games Village Metro Mall Akshardham, Delhi-91.
2. Type of occupancy:- Assembly Building
LB,UB, LG & UG floors
3. Type of case:- Renewal
4. Details of previous FSC:- F6/DFS/MS/EH/NDZ/2021/370 dated 14/12/21
5. Fire safety directives No.- F6/DFS/MS/BP/2008/1226 dated 29/04/2008
6. Date of inspection:- 27/01/2025
7. Name of the inspecting officer:- Sh. Suman Kumar (ADO)
8. Name & designation of officer
From the building side:- Mr. Kamil (Manager)
9. Year of construction:- 2008
10. Applicant's letter No:- 2025012100816 dated 21.01.2025

S.No.	Minimum Standards on fire Prevention and fire safety U/R 33	Requirement NBC-IV/UBBL/notification dt. 27.05.19	Provided at site	Remarks MR/NMR
1.	Access to Building			
	1) Road width	12 mtr.	16 mtr.	MR
	2) Gate width	4.5 M	4.5	MR
	3) Width of internal road	06 mtr.	06 mtr.	MR
2.	Number, Width Type & Arrangement of Exits			
	A. Number of staircases			
	1. Upper floors	07 Nos.	07 nos.	MR
	2. Basements	07 Nos.	07 nos.	MR
	B. Width of staircase			
	1. Upper floors	1.20 & 1.5 M	1.20,1.5, 2.5 M	MR
	2. Basements	1.20 & 1.5 M	1.20,1.5, 2.5 M	MR
	C. Protection of exits			
	1. Fire check door	Required	Provided	MR
	2. Pressurization	N/A	N/A	N/A
	D. No. of continuous staircase to terrace	N/A	N/A	N/A
	E. Width of corridor	N/A	N/A	N/A
	F. Door size	02 mtr.	02 mtr.	MR
3.	Compartmentation			
	1) Fire check door	Required	Provided	MR
	2) Sealing of electrical shafts	Required	Provided	MR
	3) Fire rating of shaft door	N/A	N/A	N/A
	4) Water curtain	N/A	N/A	N/A
	5) Fire Dampers	N/A	N/A	N/A
4.	Smoke Management System			
	1) Basements	N/A	N/A	N/A
	2) Upper floors	Required	Provided	MR
5.	Fire Extinguishers			
	1) Total numbers	05 Nos.	07 Nos.	MR
	2) Types	ABC & CO2	ABC & CO2	MR
	3) ISI marking	Required	Provided	MR
6.	First-Aid Hose Reel			
	1) Total number 1 st floor	02 no.	02 no.	MR
	2) Length of hose reel hose	30 mtr.	30 mtr.	MR
	3) Nozzle diameter	5 mm	5 mm	MR

7.	Automatic Fire Detection & Alarming System			
	1) Type of detectors	N/A	Smoke	MR
	2) Location of main panel	N/A	Provided	MR
	3) Location of repeater panel	N/A	Provided	MR
	4) Alternate source of power	N/A	Provided	MR
	5) Hooter's Location	N/A	Provided	MR
8.	MOEFA	Required	Provided	MR
9.	Public Address System	N/A	N/A	N/A
10.	Automatic Sprinkler System			
	1) Basement	N/A	N/A	N/A
	2) Upper floors	N/A	N/A	N/A
	3) Sprinkler above false ceiling	Required	Provided	MR
11.	Internal Hydrants			
	1) Size of riser/down-comer	100 mm	150 mm	MR
	2) Number of hydrants per floor	02 nos.	02 nos.	MR
	3) Hose box	02 nos.	02 nos.	MR
12.	Yard Hydrants			
	1) Total number of hydrants	N/A	N/A	N/A
	2) Hose box	N/A	N/A	N/A
13.	Pumping Arrangement			
	1. Ground level			
	a) Discharge of main pump	2850 LPM	2850 LPM	MR
	b) Head of main pump	80 mtr.	80 mtr.	MR
	c) Number of main pump	01 No.	01 No.	MR
	d) Jockey pump out put	180 LPM	180 LPM	MR
	e) Jockey pump head	80 mtr.	80 mtr.	MR
	f) Stand by pump output	2850 LPM	2850 LPM	MR
	g) Stand by pump head	80 mtr.	80 mtr.	MR
	h) Auto starting/Manual stopping	Required	Provided	MR
	2. Terrace level			
	a) Discharge of pump	N/A	N/A	N/A
	b) Head of pump	N/A	N/A	N/A
	c) Power supply	N/A	N/A	N/A
	d) Auto starting of pump	N/A	N/A	N/A
14.	Captive Water Storage for Fire Fighting			
	1) Under ground tank capacity	1,00,000 ltr.	1,00,000 ltr.	N/A
	a) Draw-off connection	Required	Provided	MR
	b) Fire service inlet	Required	Provided	MR
	c) Access to tank	Required	Provided	MR
	d) Over head tank capacity	N/A	N/A	N/A
15.	Exit Signage.	Required	provided	MR
16.	Provision of Lifts.			
	a) Pressurization of lift shaft	N/A	N/A	N/A
	b) Pressurization of lift lobby	N/A	N/A	N/A
	c) Communication in lift car	N/A	N/A	N/A
	d) Fireman's switch	N/A	N/A	N/A
	e) Lift signage	N/A	N/A	N/A
17.	Stand by Power Supply	Required	Provided	MR

N/14

18.	Refuge Area	N/A	N/A	N/A
	Total area location	N/A	N/A	N/A
19.	Fire Control Room	Provided for main building		
	a) Detector system panel	Required	Provided	MR
	b) Flow switch panel	N/A	N/A	N/A
	c) PA system panel	Required	Provided	MR
	d) Battery backup	Required	Provided	MR
	e) Building floor plan	Required	Provided	MR
20.	Special Fire Protection System for Protection of special Risk, if any:	Required	Provided at LT & HT Panels	MR

The fire protection systems provided in the building were randomly tested, checked and found functional at the time of inspection.

In view of the deemed compliance of the minimum standards of fire prevention and fire safety measures as required under the rules the FSC issued vide letter No. F6/DFS/MS/EH/NDZ/2021/370 dated 14/12/21, renewal under Rule 35 of the Delhi Fire Service Rules 2010, is recommended.

Signature of the Inspecting Officer

[Signature] 27/01/25

Name :- Suman Kumar
Designation :- ADO

[Signature] 27/01/25
DO (F.T.)

[Signature] 28/01/25
By: C.F.O. (NDZ)

[Signature] 28/01/2025
C.F.O.

[Signature] 29/01/25
Director

[Signature]
A.D.O. Suman

F.T. letter is put up for signature

[Signature] 31/01/25
Director

[Signature] 29/01/25

Uploaded
31/01/25