GOVERNMENT OF NATIONAL CAPITAL TER

C-28

Dated: 06 05 2025

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE, CONNAUGHT PLACE NEW DELHI- 110001

No. F.6/DFS/MS/EH/2025/SZ/170

FIRE SAFETY CERTIFICATE

Certified that the M/s Haldiram, located at Ground floor, Plot No. 1, Paras Cinema District Centre Nehru Palace, Kalkaji, New Delhi- 110019, in the building comprised of basement, ground, mezzanine plus three upper floors, owned/occupied by Haldiram Marketing Pvt. Ltd., was issued Fire Safety Certificate vide Letter No. F.6/DFS/MS/EH/2022/SZ/151 dated 01.06.2022. The Restaurant building was re-inspected by the officer concerned of this department on dated 24.04.2025 in the presence of Sh. Alok (Manager), and found that the restaurant have deemed complied with the fire prevention and fire safety requirements in accordance with Rule 33 of the Delhi Fire Service Rules, 2010 and that the restaurant building/premises (Ground Floor only) is fit for occupancy class Group "D" Assembly Building" w.e.f. DE DE 2025 and valid up-to 31.03.2028, in accordance with Rule 36 unless renewed under Rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under Rule-38 of the Delhi Fire Service Rules, 2010 printed below.

Issued on 06 05 2025 at New Delhi.

Delhi Fire Service

Online application Id 2025040705777 dated 07.04.2025

<u>Copy to</u>: - The Executive Engineer (Building), MCD, Civic Centre, Minto Road, New Delhi. :-for information regarding use of basement.

Conditions for validity of Fire Safety Certificate: -

- 1. This NOC is valid only for ground floor.
- 2. All the fire safety arrangements provided therein shall be maintained in good working condition at all times.
- 3. The means of escape shall be kept unlocked and unobstructed for unhindered evacuation of occupants in case of emergency.
- 4. Any loss of life or property due to non-functional fire safety measures shall be at the risk and responsibility of the management.
- 5. The trained staff should be available round the clock.
- 6. Any deviations w.r.t. construction shall be verified by the concerned building sanctioning agency.
- 7. Basement strictly shall be kept vacant as seen during inspection/used as per BBL.
- 8. The certificate may not be treated in any case for the regularization of the unauthorized construction, if any.
- 9. The owner/occupier shall submit a declaration every year in the form 'K' provided in the first schedule of Delhi Fire Service Rules 2010, form is available on www.dfs.delhigovt.nic.in.
- 10. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in the Form 'J' [sub rule (1) of rule 37] along with a copy of this Certificate, six months prior to its expiry.

INSPECTION REPORT

1. Name & address of the building: M/s Haldiram Marketing Pvt. Ltd at Plot No. 01, GF of Paras Cinema

District Centre Nehru Place, Kalkaji, New Delhi- 110019.

2. Building is comprised of : Basement, ground, mezzanine plus three upper floors

3. Type of Occupancy : Group D (Assembly) Restaurant running at Ground floor only

4. Type of Case : Renewal

5. Details of Previous NOC : F.6/DFS/MS/EH/2022/SZ/151 dated 01.06.2022

6. Fire Safety directives letter No : N/A

7. Date of inspection : 24.04.2025

8. Name of Inspecting Officers : A.D.O. R.K. Yadav

9. Name and designation of officers

From the building side : Sh. Alok (Manager)

10. Year of Construction : 2005

11. Applicant's letter No. : online application ID 2025040705777 dated 07.04.2025

S. No.	Minimum Standards on fire prevention and fire safety U/R 33	Requirements	Provided at site	Remarks MR/NMR		
1.	Access to building FSC No. F.6/DFS/MS/Assembly/2022/SZ/Cinema/132 dated 29.03.202 Paras Cinema District Centre Nehru Palace, Kalkaji.					
	Road width	Restaurant within	As above	M/R		
	Gate width	Cinema	As above	N/A		
	Wighth of internal road		As above	N/A		
2.	Number, Width, Type & Arrangement of Exits					
	a. Number of staircases	Provided & Maintained by Paras Cinema				
	Upper Floors	04 no.'s	As above	MR		
	Basements	N/A	As above	N/A		
	b. Width of staircases	Provided & Maintained by Paras Cinema				
	Upper Floor	1.5 M each	As above	MR		
	Basements	N/A	As above	N/A		
	c. Protection of exits	Provided & Maintained by Paras Cinema				
	Fire check door	Required	As above	MR		
	Pressurization	N/A	As above	N/A		
	1 31 6 6					
	d. No. of continuous staircases to terrace	Required	As above	MR		
	e. Width of Corridor	N/A	N/A	N/A		
	f. Door Size	1.5 m each	1.5 m & 1.5 m	M/R		
3.	Compartmentation	Provided & Maintained by Paras Cinema				
	Fire check door	Required	As above	M/R		
	 Sealing of electrical shafts 	N/A	As above	N/A		
	Fire Rating of shaft door	N/A	N/A	N/A		
	Water Curtain	N/A	N/A	N/A		
	Fire Dampers	N/A	N/A	N/A		
4.	Smoke Management System Provided & Maintained by Paras Cinema					
	Basements	N/A	As above	N/A		
	Upper floors	Required	Exhaust fans provided	MR		
5.	Fire Extinguishers					
	Total numbers in restaurant	06 no.'s	Provided	M/R		
	Types	ABC/CO ₂	Provided	M/R		
	IS marking	ISI marked	Provided	M/R		
6.	First-Aid Hose Reels Provided & Maintained by Paras Cinema					
	Total numbers for restaurant	1 Nos.	01 in restaurant	M/R		
	Length of hose reel hose	30 mtrs	Provided	M/R		
	Nozzle diameter	5 mm	Provided	M/R		

7.	Automatic fire detection				
	Automatic fire detection and alarming system-		Provided & Maintained b	y Paras Cine	
	 Type of detectors Smoke/Heat Location of Main Panel 	Heat & smoke	Provided	MR	
	Location of Repeater Panel	Required	As above	MR	
	Alternate source of nower	N/A	N/A	N/A	
	Hooters' Location	Required	As above	MR	
8.	MOEFA with talk back system	Required	As above	MR	
9.	Public Address System	Required	As above	MR	
10.		Required	As above	MR	
	Automatic Sprinkler System		Provided & Maintained by	y Paras Ciner	
	Basement	Required	As above	MR	
	Ground Floor at restaurant	Required	As above	MR	
11.	Sprinkler above false ceiling	N/A	N/A	N/A	
11.	Internal Hydrants		Provided & Maintained by	200430400	
	Size of riser/down-comer	Required	As above		
	Number of hydrantsHose Box	Required	As above	MR	
12.		Required	As above	MR MR	
12.	Yard Hydrants		Provided & Maintained by		
	 Total number of hydrants Hose Box 	N/A	As above	N/A	
	Control and Assert Control	N/A	As above	N/A	
13.	Pumping Arrangements		(A)		
	Ground Level		Provided & Maintained by I	aras Cinema	
	Discharge of main Pump	2280 LPM	A = of se		
	➤ Head of Main pump	60 mtrs	As above	M/R	
	Number of main pumps	two	As above	M/R	
	Jockey Pump out put	180 LPM	As above	M/R	
	Jockey pump head	60 mtrs	As above	M/R	
	N 0 " -	2280 LPM	As above	M/R	
	Standby Pump out put	60 mtrs	As above	M/R	
	Standby Pump HeadWater curtain Pump	Required	As above	M/R	
	> Auto Starting/Manual	Required	As above As above	M/R	
	Stopping	1	As above	M/R	
	dr . Triple I	Required	As above	M/R	
	> Pump House Access		Provided & Maintained by P		
	Terrace level Discharge of pump	N/A	N/A	N/A	
	> Head of the pump	N/A	N/A	N/A	
	> Power Supply	N/A	N/A	N/A	
	➤ Auto Starting of pump	N/A	N/A	N/A	
1.				5-5000	
**	Captive Water Storage for fire-fighting		Provided & Maintained by Paras Cinema		
	Underground tank capacity for entire bldg	75,000 ltrs	1,00,000 ltrs	M/R	
	entire bldg. > Draw-off connection	Required	As above	M/R	
	> Fire service inlet	Required	As above	M/R	
	> Access to tank	Required	As above	M/R	
	Overhead Tank capacity	10,000 ltrs	As above	M/R	
	Exit Signage.	Required	Provided	MR	
	Provision of Lifts	D,	rovided & Maintained by Pa	0 335	
	Pressurization of Lift Shaft		550		
	Pressurization of Lift lobby	N/A	N/A	N/A	
	Communication In lift Car	N/A	N/A	N/A	
	Fireman's Grounding Switch	N/A	N/A	N/A	
	Lift Signage	N/A	N/A	N/A	
لے	Dir Oignage	N/A	N/A	N/A	

1					
17.	Standby power supply	Required	Provided (DG Set)	M/R	
18.	Refuge Area.				
	> Total Area	N/A	N/A	N/A	
	> Location	N/A	N/A	N/A	
19.	Fire Control Room Provided & Maintained by Paras Cinema				
	Detector System Panel Flow Switch Panel PA System Panel Battery backup Building Floor Plans	N/A	As above	N/A	
		N/A	As above	N/A	
		N/A	As above	N/A	
		N/A	As above	N/A	
		N/A	As above	N/A	
20.	Special Fire Protection System for Protection of special Risks, if any:	N/A	As above	N/A	

The fire protection systems provided in the building were tested, checked and found functional at the time of inspection.

Keeping in view of the deemed compliance of the minimum standards of fire prevention and fire safety measures as required under the rules the FSC issued vide letter No. F.6/DFS/MS/EH/2022/SZ/151 dated 01.06.2022, renewal under rule 37 of the Delhi Fire Service Rules 2010 is recommended.

Note: - The restaurant is at ground floor in Paras Cinema building and having common fire safety installation. The FSC of the Paras Cinema has been issued vide latter No. F.6/DFS/MS/Assembly/2022/SZ/Cinema/132 dated 29.03.2022.

Accordingly, DFA, is put up for approval & signature please.

Signature of Inspecting Of

Name: - R.K. Yadav Designation: - ADO (JKP)

cho (Ca) Ilm

Director 15 25

AN INN