

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI- 110001

No.F6/DFS/MS/School/SZ/2025/630

Dated:

To

The Manager, M/s Hans Memorial School, D-3, Tajpur Road, Mohan Baba Nagar, Badarpur, New Dlhi-44.

Regarding issuance of Fire Safety Certificate in r/o M/s Hans Memorial School located at Sub:-D-3, Tajpur Road, Mohan Baba Nagar, Badarpur, New Dlhi-44.

Sir,

With reference to letter bearing outdoor diary no. 3670 dated 11.07.2025 on the subject cited above, it is informed that the school building was inspected by Assistant Divisional Officer (M. Road) from this department on 28.07.2025 in the presence of manager and it was observed that the school building is comprised of Ground + 03 upper floors. During the inspection following shortcomings were observed:-

- 1. Access to alternate staircase shall not be through occupied area at 2nd & 3rd floor.
- 2. First aid hose reel has not been provided at each floor.
- 3. Fire pump of 450 LPM with head 40 m has not been provided.
- 4. Overhand tank capacity of 10,000 liters for firefighting has not been provided.

5. Exit signage has not been provided.

In view of above shortcomings, the application for issuance of Fire Safety Certificate is rejected. The occupancy of the building/premises in absence of requisite fire safety arrangements shall be at the risk and liability of the school management. The Authority/Statutory Authority may take suitable necessary action as deemed fit.

Yours faithfully,

(Virendra Singh) Chief Fire Officer Delhi Fire Service

Copy to:-.

1. The Dy. Director of Education, GNCT of New Delhi DISST. South Block-C, Defence Colony, New Delhi-24.