



GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: CANNAUGHT PLACE NEW DELHI- 110 001

No.F.6/DFS/MS/EH/2025/NDZ/ 332

Dated: 22 09/2015

FIRE SAFETY CERTIFICATE

Certified that the M/s Hard Rock Café (A Unit of JSM JG Foods LLP) at 1st floor & 2nd floor located at show room no. 01, Atma Ram Mansion, Scindia House, Janpath Road, Connaught Circus, New Delhi-110001. The building is comprised of Ground, Mezzanine plus two upper floors but restaurant is running at 1st floor & 2nd floor only owned/occupied by M/s Hard Rock Café (A Unit of JSM JG Foods LLP) was issued FSC vide letter F.6/DFS/MS/EH/ 2022/NDZ/239 dated 30/08/2022. The premises was re-inspected by the officer concerned of this department on dated 09/09/2025in the presence of Sh. Dev, Manager and observed that all the fire prevention and fire safety arrangements provided in the premises and found that the said premises having deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and that the premises is fit occupancy class "Assembly" Group D (1st floor & 2nd floor only) with effect from 29 09 20% and up to valid 31/03/2028 in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under rule 40 and subject to compliance of the conditions under rule 38 of the DFS rules, 2010. Conditions mentioned below.

Issued on 22 09 2025 at New Delhi by.

Copy to: -

1. The Executive Engineer, NDMC, Palika Kendra, New Delhi:- to ensure the occupancy as

2. The Manger, M/s Hard Rock Café (A Unit of JSM JG Foods LLP) at 1st floor & 2nd floor located at show room no. 01, Atma Ram Mansion, Scindia House, Janpath Road, Connaught Circus, New Delhi-110001

MCD ID No. 2025082312816

Conditions for the validity of Fire Safety Certificate

- This FSC is valid for restaurant at first floor & second floor only. 2. All the fire safety arrangements provided therein shall be maintained in good working condition at all
- 3. Any loss of life or property due to non-functional fire safety measures shall be at the risk and responsibility of the management.
- 5. Any deviation, with regards to construction, ventilation, occupancy, electric installation etc. may be got The trained staff should be available round the clock.
- 6. This Fire Safety Certificate may not be treated in any case for regularizations of unauthorized construction /unauthorized use of land if any,
- 7. The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rule 2010. The form is available on www.dfs.delhigovt.nic.in
- 8. The owner / occupier shall apply for renewal of this Fire Safety Certificate of the Director in Form 'J' [sub rule (1) of rule (37)] along with a copy of this Certificate, Six Months prior to its expiry.

Name & address of the building : M/s Hard Rock Café (A Unit of JSM JG Food LLP) at 1st floor & 2nd floor located at show room no. 01, Atma Ram Mansion , Scidia House, Janpath Road, Connaught Place, New Delhi-110001

The building comprised : Ground, Mezzanine plus two upper floors but

restaurant is running at 1st floor & 2nd floor only

3. Type of Occupancy : Assembly (Class-D)

Type of Case : Renewal

: F.6/DFS/MS/EH/ 2022/NDZ/239 dated 30/08/2022 Details of Previous NOC letter 5.

Fire Safety directive letter No : N/A : 09/09/2025

7. Date of Inspection

: ADO (Shd.) Deepak Kumar 8. Name of the Inspecting officers

Name and designation of Officer

: Sh. Dev, Manager from the building side Year of Construction : Old Heritage

: 2025082312816 Dated- 23/08/2025 Applicant's letter No

Sr. No.	Minimum Standards on Fire Prevention and Fire Safety U/R33	Requirement/ BBL	Provided at Site	Remarks MR/NMR		
01	Access to Building					
	Road width	12 m	18 m	MR		
١ .	Gate width	N/A	N/A	N/A		
1	Width of internal road	N/A	N/A	N/A		
02	Number, Width, Type and Arranger	nent of Exits				
	a. Number of Staircases					
	Upper floor	02 nos.	02 nos.	MR		
	Basement	N/A	N/A	N/A		
	B. Width of Staircases					
	Upper floorBasement	0.80 m & 1.25 m	02 nos. 1.20 m to 1.30m each	N/A		
		N/A	N/A	N/A		
	c. Protection of Exits					
Ш	Fire check door	N/A	N/A	N/A		
	Pressurization	N/A	N/A	N/A		
	d. No. of Continuous Staircases to Terrace	N/A	N/A	N/A		
	e. Width of Corridor	N/A	N/A	N/A		
	f. Door Size	02 m & 1.12m	02 m & 1.12m	MR		
03	Compartmentation.					
	 Fire check door Sealing of electrical shafts Fire rating of shaft door 	N/A	N/A	N/A		
		N/A	N/A	N/A		
		N/A	N/A	N/A		
	Water curtain	N/A	N/A	N/A		
-	Fire dampers	N/A	N/A	N/A		
04	Smoke Management System.					
touist.	Basement	N/A	N/A	N/A		
1	Upper floor	12 ACPH	Natural	MF		
05.	Fire Extinguishers					
	Total numbers	05 nos	07 nos	MR		
	Types	ABC /CO ₂	ABC /CO ₂	MR		
	IS marking	Required	Provided	MR		

NIP

00	6 First-Aid-Hose Reels.					
	Total numbers on each floor	01 nos	01 nos	MR		
	 Length of hose reel hose 	30 mtr	30 mtr	MR		
	Nozzle diameter	05 mm	05 mm	MR		
07	Automatic Fire Detection and Alarming System:-					
	Type of detectors	N/A	N/A	T		
	 Location of main panel 	N/A	The state of the s	N/A		
	 Location of repeater panel 	N/A	N/A	N/A		
	 Alternate source of power 	N/A	N/A	N/A		
	Hooter		N/A	N/A		
80	MOEFA	N/A	N/A	N/A		
09	Public Address System.	Required	Provided	MR		
10	Automatic Sprinkler System.	N/A	N/A	N/A		
	Basement	· ·				
	upper floor	N/A	N/A	N/A		
	sprinkler above false ceiling	N/A	Provided	N/A		
11	Internal Hydrants	N/A	N/A	N/A		
	 size of riser/down-comor 	400				
	Number of hydrants per floor	100 mm	100 mm	MR		
10	1 lose box	01 nos.	01 nos.	MR		
12	Yard Hydrants.	01 nos.	01 nos.	MR		
	Total number of hydrants	1 3 7				
	HOSE DOX	N/A	N/A	N/A		
13	Pumping Arrangements.	N/A	N/A	N/A		
	> Ground Level					
	 Discharge of main pump Head of main pump 	N/A	N/A	NI/A		
	Number of main pumps	N/A	N/A	N/A		
	Jockey pump out put	N/A	N/A	N/A N/A		
	Jockey pump head	N/A	N/A	N/A		
	Standby pump out put	N/A	N/A	N/A		
	 Standby pump head 	N/A	N/A	N/A		
	Auto starting /manual stopping	N/A N/A	N/A	N/A		
	Pump house access		N/A	N/A		
	> Terrace Level	N/A	N/A	N/A		
	Discharge of pump	450 lpm	AEO Imp	- 107		
	 Head of the pump 	30 m	450 lpm 30 m	MR		
	 Power supply 	Required	Provided	MR		
	Auto starting of pump	Required	Provided	MR MR		
	Captive Water Storage for Fire Fighting			5-3.404		
	Underground tank capacity	N/A	N/A	N/A		
	Draw-off connection	N/A	N/A	N/A		
	Fire service inlet	N/A	N/A	N/A		
	 Access to tank 	N/A	N/A	N/A		
		10,000 ltr	The second secon	MR		
	 Overhead tank capacity 	וט,טטט ונו	10,000 ltr	I IVIK		

3 1	Provision of Lifts. Lift not Installed		N/A	N/A			
-	 Pressurization of lift shaft 	N/A	N/A	N/A			
	Pressurization of lift lobby	N/A		N/A			
-	Communication in lift car Firemen's grounding switch	N/A	N/A	N/A			
1		N/A	N/A	N/A			
		N/A	N/A				
	Lift signage	Required	Provided	MR			
7	Standby Power Supply						
18	Refuge Area.	N/A	N/A	N/A			
_	Total area Location		N/A	N/A			
		N/A					
19	Fire Control Room						
	 Detector system panel Flow switch panel PA system panel Battery backup 	N/A		N/A			
		N/A	N/A	N/A			
		N/A	N/A	N/A			
		N/A	N/A	N/A			
		N/A	N/A	N/A			
	Building floor plans Systems for	N/A	N/A	IN/A			
20	Special Fire Protection Systems for Protection of Special Risks, if Any:						

The fire protection systems provided in the building were tested/checked and found functional at the time of inspection.

Keeping in view the deemed compliance of the minimum standards on fire prevention and fire safety required under the rule. The earlier FSC issued vide letter no. F.6/DFS/MS/EH/ 2022/NDZ/239 dated 30/08/2022 renewal under Rule 35 of the Delhi Fire Service Rules 2010, is recommended.

Signature of the Inspecting Officer

Name

:- Deepak Kumar

Designation

:- A.D.O (Shd)

Do (CD)

C.F.O

Live

16 91 sorr

Mincipal Director

Ofo to

18/29

Asso (Chas)

Do yes

8 91 2005