GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE, NEW DELHI-110001

No. F.6/DFS/MS/GH/NDZ/2025/394

Dated: 18/09/2025

To

The Commissioner,

Municipal Corporation of Delhi,

Dr. SPM Civic Centre, New Delhi - 02.

Sub: Regarding renewal of Fire Safety Certificate (FSC) in r/o M/s Hare Rama Guest House located at T-416, T-298, Main Bazar, Pahar Ganj, New Delhi- 110055.

Sir,

This has reference to MCD portal online application Id No.2025082812966 dated 28.08.2025 on the subject cited above. In this connection, it is to inform you that the above mentioned premise was visited by the officer concerned of this department on dated 08.09.2025 in presence of Mr. Galib (Manager) and observed that the shortcomings intimated vide letter of even No.F6/DFS/MS/GH/NDZ/311 dated 01/07/2025 (copy enclosed) have not been complied yet.

In view of above shortcomings, the application for issuance Fire Safety Certificate is rejected. The occupancy of the building /premises in absence of requisite fire safety arrangements shall be at the risk and liability of the owner/occupier. The Licensing authority/ Statutory Authority may take suitable necessary action as deemed fit.

Encl: As above.

Yours faithfully,

(Virendra Singh) Chief Fire Officer Delhi Fire Service

Copy to:-

The Licensee,

M/s Hare Rama Guest House at T-416, T-298, Main Bazar, Pahar Ganj, New Delhi- 110055.

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEAD QUARTERS : DELIII FIRE SERVICE : NEW DELHI – 1 10001

No.F6/DFS/MS/GH/NDZ/311

Dated: QL/D.7/2025

To.

The Manager, M/s Hare Rama Guest House, T-146, T-298, Main Bazar, Pahar Ganj, New Delhi.

Sub: Issuance of FSC (Fire Safety Certificate) in r/o M/s Hare Rama Guest House, T-146, T 298, Main Bazar, Pahar Ganj, New Delhi.

Sir.

This has reference to on line ID No. 2025052609090 dated 19.06.2025, on the subject cited above. In this regard, it is to inform you that the site was inspected by the officer concerned of this department on 25/06/25 in the presence of Mr. Galib Manager and following shortcomings were observed:

- 1. Smoke management system is found nonfunctional.
- 2. Co detectors are not provided in some rooms and some are found nonfunctional.
- 3. MCP & PA found nonfunctional.
- 4. Further, 08 nos of rooms are shown in the building plans and same are operating whereas only 03 rooms are filled in application form, accordingly clarification is required to be submitted to use of extra rooms.

In view of above c, the case is rejected and Fire Safety Certificate (FSC) cannot be renewed at this stage due to above shortcomings. Therefore, you are requested to rectify/ clarify the above shortcomings and re-submit for further consideration in the matter.

Yours fathfully.

Delhi Fire Service

Copy to:

1. The Commissioner MCD, Civic Center, New Delhi.