

## GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE, NEW DELHI-110001

No.

F.6/DFS/MS/School/NDZ/2025/ 425

Dated: 21/05/2025

To

The Principal,

Hira Lal Jain Senior Secondary School,

Sadar Bazar, Delhi - 110006.

Regarding issuance of Fire Safety Certificate (FSC) from fire safety point of view in r/o Sub: Hira Lal Jain Senior Secondary School, Sadar Bazar, Delhi.

Sir,

This has reference to your letter No. HLJ/B/2025/7970 dated 01.05.2025 received in this department through outdoor diary no. 1239 dated 01.05.2025 on the subject cited above. In this connection, it is to inform you that the above mentioned premise was visited by the officer concerned of this department on dated 15.05.2025 and observed that the shortcomings intimated vide letter of even No.F6/DFS/MS/2019/School/NDZ/7236 dated 05/12/2019 (copy enclosed) have not been complied yet.

In view of above shortcomings, the application for issuance Fire Safety Certificate is rejected. The occupancy of the building/premises in absence of requisite fire safety arrangements shall be at the risk and liability of the owner/occupier.

Encl: As above.

Yours faithfully,

Delhi Fire Service

Tel: 011-2**3**41400

Copy to:-

The Director of Education, Govt. of NCT of Delhi, Old Secretariat, Delhi.

Not

## GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI-110001

No. To, PEIDISINS/2019/Jeh-C/HD2/7236

Dated: 05/12/14

The Principal,
Hira Lal Jain Sr. Sec. School,
Sadar Bazar, Delhi,

Sub: - Regarding issuance of "Fire Safety Certificate" from fire safety point of view in rio Hira Lal Jain Sr. Sec. School, Sadar Bazar, Delhi

Madam/Sir.

Please refer to your letter no. HLJ/B/2019/6518 dated 20.09.2019 on the subject cited above. In this connection this is to inform you that officer concerned of this department inspected the school on 25.11.2019 to verify the fire safety arrangements in accordance with the circular No. F.16/Estate/CC/Fire Safety/2011/3298 to 3398 dated 01.03.11 issued by the Director of Education. At the time of inspection Principal of the school was present and it was observed that the school building is comprised of ground plus three upper floors and have following shortcomings:-

- 1. First Aid Hose reels not provided at each floor.
- 2. Fire pump having capacity 450 LPM out put with 40 m head not provided.
- 3. Over head water storage tank of 10,000 liters capacity is required exclusively for firefighting.
- 4. Exit signs are not found provided.

In view of above, the fire safety certificate cannot be issued. You are suggested to rectify the above said shortcoming under the intimation to this department for further course of action.

Yours faithfully,

(Sunil Chaudhary)
Dy. Chief Fire Officer
Delhi Fire Service
Tel: 011-23414262

Copy to:-.

The Director of Education,
Govt of NCT of Delhi, Old Secretariat, Delhi