## GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEAD QUARTERS: DELHI FIRE SERVICE: NEW DELHI-110001

No. F6/DFS/MS/GH/SZ/2025/519

Dated:

08/10/2025

## **FIRE SAFETY CERTIFICATE**

Certified that M/s. Hotel Kyron, located at 15A/45, WEA, Saraswati Marg Karol Bagh, New Delhi-110005, in a building comprised of basement (storage), stilt (parking), ground floor (store & 05 guest rooms,) 1<sup>st</sup>, 2<sup>nd</sup> and 3<sup>rd</sup> floor each having 06 guest rooms total 23 guest rooms, was issued FSC vide letter No.F.6/DFS/MS/GH/SZ/2022/470 dated 12/10/2022. the premises was re-inspected by the officer concerned of this department on 25/09/2025 in the presence of Sh. Parvesh Kumar and found that the premises have deemed complied with fire prevention and fire safety requirements in accordance with Rule 33 of Delhi Fire Service Rules,2010 and that the premises is fit for occupancy class Residential, (guest house) (ground floor (reception + 05 guest rooms), 1<sup>st</sup> to 3<sup>rd</sup> floor (06 guest rooms at each floor), (total 23 guest rooms only), validity upto 31/03/2028 in accordance with Rule 36 unless renewed under Rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under Rule 38 of the Delhi Fire Service Rules, 2010. Conditions mentioned below.

Issued on 08 10 2025 at New Delhi by.

Dr. Sanjay Kumar Tomar Dy. Chief Fire Officer

New Delhi Zone

Copy to: -

 The Commissioner, MCD, Civic Centre, New Delhi. to ensure the occupancy as detailed above & deviation if any.

2. The owner/occupier, M/s Kyron Guest House, 15A/45, WEA, Karol Bagh, New Delhi-110005.

## Conditions for the Validity of Fire Safety Certificate: -

- 1. All the fire safety arrangements provided therein shall be maintained in good working condition at all times.
- Any loss of life or property due to nonfunctional fire safety measures shall be at the risk and responsibility of managements.
- 3. The trained firefighting staff should be available round the clock.
- 4. Any deviation, with regards to construction shall be verified by the concerned building sanctioning agencies.
- 5. The Fire Safety Certificate may not be treated in any case for regularizations of unauthorized construction / unauthorized use of land if any.
- The means of escapes shall be kept unobstructed/unlocked for unhindered evacuation in case of an emergency.
- 7. The owner /occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rule 2010. The form is available on
- 8. The owner / occupier shall apply for renewal of this Fire Safety Certificate to the Director in 'Form J' (sub Rule (1) of Rule 37) along with copy of the certificate, six months prior to its expiry.
- No occupancy used above third floor and basement used for storage purpose only shall be strictly adhered by owner/occupier.

8/10/2W

		INSPI	ECTION RE	PORT				
1.	Name & address of the building	me & address of the building M/s. Hotel Kyron, 15A/45, WEA, Saraswati Marg, K						
			n, New Delhi-				i Marg, Karol	
2.	Type of Occupancy	Lodg	ging House/G	uest Ho	ouse			
3.	Type of Case	Rene	ewal					
4.	Details of previous NOC	F.6/I	DFS/MS/GH/	SZ/202	2/470 dated 12/10	0/202	22	
5.	Fire Safety directives letter No	Nil						
6.	Date of inspection	25/0	9/2025					
7.	Name of the Inspecting Officers	Sara	bjeet Singh A	DO (M	N)			
8.	Name and designation of	Sh. Parvesh Kumar						
1	officers from the building side							
9.	Year of Construction	2010	(As per onlin	ne appli	icaton)			
10.	1 to the Ballion of the Control of t	Onli	ne application	ID No	.2025091213396	dated	d 12/09/2025	
The	said guest house building is r	unnir	ng at ground	d and	three upper fle	ors.	in a building	
com	prised of basement (storage), st	ilt (p	arking), gro	und fle	or (a recention	. sto	re & 05 guest	
roor	ns,) 1 <sup>st</sup> , 2 <sup>nd</sup> and 3 <sup>rd</sup> floor each h	aving	06 guest roo	ms to	tal 23 guest room	ms. v	vas issued FSC	
vide	letter No. F.6/DFS/MS/GH/SZ/2				.(For 23 guest re	ooms	only).	
S.	Minimum Standards on fire		s per Rule 35	5.5	Provided at site		Remarks	
No 1	prevention and fire safety U/R 33	33 DFS Rule 2010 MR/NM					MR/NMR	
1	Access to building							
	Road width	1	06 mts		Provided		MR	
	Gate width		NA		Directly accessible		NA	
	<ul> <li>Width of internal road</li> </ul>		NA		NA		NA	
2	Number, Width, Type & Arrang	gemen	t of Exits					
	a. Number of staircases							
	<ul> <li>Upper Floors</li> </ul>		01 Nos.	1	01 Provided	MR being old case		
	Basements		01 Nos.	78	01 Provided .	_	R being old case	
	b. Width of staircases							
	• Upper Floors		Programme and the second secon				R being old case R being old case	
	Basements							
	c. Protection of exits							
	Fire check door		NA		NA		NA	
	Pressurization		NA		NA	NA		
	d. No. of continuous staircases to te e. Width of Corridor	гтасе	01		01 Provided		MR	
	f. Door Size		1.20 mts	_	mts Provided		R being old case	
3	Compartmentation.		Old Case	Prov	rided (0.86 mt)	MR	being old case	
-	• Fire check door	_	374					
	Sealing of electrical shafts		NA Paguinal		NA Sector		NA	
	Fire Rating of shaft door		Required NA		Sealed		MR	
	Water Curtain		NA NA		NA . NA		NA NA	
	Fire Dampers		NA NA				NA NA	
4	Smoke Management System.		INA		NA NA		NA	
	Basements		Required		Exhaust Fan Provided		1 100	
	• Upper floors		Required		Exhaust Fan Provided			
5	Fire Extinguishers		Required		Exhaust Fan Provided MR		MK	
	Total numbers						1 (D	
		Types CO <sub>2</sub> , ABC		CO <sub>2</sub> , ABC type ABC & CO		-	MR MR	
	- Maring		Require	•	Provided		MR	

	Elma Ald Hass Deals	112(120					
6	First-Aid Hose Reels.	01	Provided	MR			
	<ul> <li>Total numbers on each floor</li> </ul>						
	<ul> <li>Length of hose reel hose</li> </ul>	30 mtr.	Provided	MR			
	<ul> <li>Nozzle diameter</li> </ul>	05 mm	Provided	MR			
7	Automatic fire detection and alarming system.						
	Type of detectors	Carbon Monoxide	Provided Provided near reception	MR MR			
	<ul> <li>Location of Main Panel</li> </ul>	Ground Floor					
	<ul> <li>Location of Repeater Panel</li> </ul>	NA	NA	NA			
	<ul> <li>Alternate source of power</li> </ul>	Required	Provided	MR			
	Hooters' Location	NA	NA NA	NA			
8	MOEFA	Required	Provided	MR			
9	Public Address System.	Required	Provided	MR			
10	Automatic Sprinkler System.						
	Basement	Required	Provided	MR			
	Upper Floor	NA	NA	NA			
	Sprinkler above false ceiling	NA	NA	NA			
11	Internal Hydrants	3 ,					
	Size of riser/down-comer	NA	NA	NA			
	Number of hydrants per floor	NA	NA	NA			
	Hose Box	NA	NA NA	NA			
12	Yard Hydrants.		30				
	Total number of hydrants	NA	NA NA	NA			
	Hose Box	NA	NA NA	NA			
13	1 Hose Box						
13	Pumping Arrangements.  • Ground Level						
	Discharge of main Pump	NA	NA	NA			
	> Head of Main pump	NA	NA	NA			
	Number of main pumps	NA	NA NA	NA			
	> Jockey Pump out put	NA	NA NA	NA			
	> Jockey pump head	NA	NA	NA			
	Standby Pump out put	NA	NA NA	NA			
	Standby Pump Head	NA	NA NA	NA			
	> Auto Starting/ Manual stopping	NA	NA NA	NA			
	Pump House Access	NA	NA	NA			
	Terrace level						
	<ul> <li>Discharge of pump</li> </ul>	450 LPM 54	0,456 LPM Provided	MR			
	Head of the pump	40 mts	Provided	MR			
	> Power Supply	Required	Provided	MR			
	Auto Starting of pump	Required	Provided	MR			
14	Captive Water Storage for fire fighting	ng.					
	Underground tank capacity	NA	NA NA	NA			
	➤ Draw-off connection	NA	NA	NA			
	> Fire service inlet	NA	NA	NA			
	> Access to tank	NA	NA .	NA			
		I .					
	Overhead Tank capacity	10,000 ltr.	Provided	MR			

1	NIX							
L	6 Provision of Lifts.							
16	Pressurization of Lift Shaft     Pressurization of Lift lobby     Communication In lift Car     Fireman's Grounding Switch     Lift Signage	NA	NA	NA				
1		NA	NA	NA				
		Required	Provided	MR				
		Required	Provided	MR				
		Required	Provided	MR				
17	Standby power supply	Required	Provided	MR				
18	Refuge Area.							
10	Total Area  Location	, NA	NA -	NA				
19		NA	NA	NA				
	Fire Control Room							
	Detector System Panel     Flow Switch Panel     PA System Panel	NA	NA	NA				
		NA	NA	NA				
		NA	NA	NA				
	Batter backup	NA	NA	NA				
	Building Floor Plans	NA	NA	NA				
20	Special Fire Protection Systems for Protection of special Risks, if any:	Required	One ABC type fire extinguisher found provided near elect.	MR				

The fire protection systems provided in the building were test checked and found functional at the time of inspection.

Keeping in view of the deemed compliance of minimum standards of fire prevention and fire safety measures as required under the rules, the NOC vide letter no F.6/DFS/MS/GH/SZ/2022/470 dated 12/10/2022, renewal under the rule 35 of the Delhi Fire Service rules 2010 is recommended.

Bolchand)

29/9/28

Signature of the Inspecting Officer

Name: Sarabjeet Singh

Designation: Assistant Divisional Officer

29/9 2025

Principal Director

by OFO

to Jane

Op Contraction

1 3/10/2r

DOD(Shrijeer)

die, f. T vis

put up for

tom kind persue