



Dated 30/01/2025

To,

C-67

The Joint Commissioner of Police (Lic.), 1<sup>st</sup> floor, Police Station Defence Colony, New Delhi – 110024.

Subject: - Regarding grant of Fire Safety Certificate in r/o M/s Hotel Ravin located at Plot no. A-383, NH - 08, Mahipalpur Extn., New Delhi - 110037.

Sir,

This has a reference to MHA application No. 2025011700641 dated 17/01/2025 on the subject cited above. In this connection, it is to inform you that premises was inspected by the officer concerned of this department on 24/01/2025 in the presence of Mr. Gaurav Sherawat (Owner) and observed that building comprised of Basement (Store & Office), Ground floor (Reception & Office), 1<sup>st</sup> & 2<sup>nd</sup> floor each having 07 guest rooms respectively (Total 14 guest rooms only).

## Following shortcomings were observed during time of inspection:

- 1. Fire Check door found removed.
- Smoke management system is not provided in basement.
- 3. Hose reel provided but not functional.
- 4. Sprinklers provided in basement but not functional.
- 5. Fire pump of 900 LPM provided but not functional
- 6. Overhead water storage tank capacity 5,000 liters is provided against requirement of 10,000 liters.

In view of above shortcomings, the application for issuance for Fire Safety Certificate is rejected. The occupancy of the building/premises in absence of requisite fire safety arrangements shall be at the risk and liability of the management. The Authority/Statutory Authority may take suitable necessary action as deemed fit.

Yours faithfully,

DIRECTOR

O C DELHI FIRE SERVICE

Copy to:-

 Mr. Gaurav Sherawat (Owner), M/s Hotel Ravin located at Plot no. A- 383, NH - 08, Mahipalpur Extn., New Delhi - 110037.