

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI FIRE SERVICE, NEW DELHI-110001



No. F6/DFS/MS/Metro/WZ/2025/ 19 0 To,

Dated: 24/64 /2025

Sh. Rajesh Agarwal, General Manager (E & M), Delhi Metro Rail Corporation Ltd., Metro Bhawan, 13 Fire Brigade Lane, Barakhamba Road, New Delhi-110001.

Sub: - Inspection report in r/o Inderlok Metro Station (Line-5, Inderlok to Mundka Line) located at Trinagar, Delhi- 110035.

Sir,

This has reference to your application no. DMRC/O&M/Fire/NOC/Line-5/2025/02/43 dated 04/03/2025 received through outdoor diary number 14164 dated 06/03/2025 on the subject cited above. In this connection, it is to inform you that the inspection of above said metro station has been carried out by officer concerned of this department on 16/04/2025 to see the compliance of the requisite fire safety measures. Sh. Sanyam Jain (Manager Fire) & Sh. Sundar Lal (J.E., Electrical) were present at the time of inspection.

During the course of inspection it was observed that the metro station building comprised of Ground + Concourse + Platform. Your request for renewal of FSC is rejected as the following shortcomings were observed:

1. First aid hose reels found provided but not functional at some places.

2. Smoke/ Heat detectors found removed at some places.

3. Internal hydrants found provided but not functional at some places.

4. Yard hydrant found provided but not functional at some places.

In view of the above shortcomings, the application for renewal of Fire Safety Certificate is not considered at this stage & rejected. The occupancy of the Building/ premises in absence of requisites fire safety arrangements shall is at the risk and liabilities of the Owner/ Occupier.

Yours faithfully,

Director