

C/230

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEAD QUARTERS : DELHI FIRE SERVICE : NEW DELHI - 110001

No.F.6/DFS/MS/NDZ/2025/ 394

Dated:- 19.08/2025

To,

Executive Engineer (E),
Delhi Electrical Division-202,
CPWD, I.G.I. Stadium,
New Delhi-110002.

Sub: Regarding inspection for renewal of FSC in r/o Indira Gandhi Stadium complex at Indraprastha Estate, New Delhi.

Sir,

This has reference to your letter No.24(2)EE(E)/DED-202/2025/556 dated 07/07/25, on the subject cited above. In this regard, it is to inform you that the two block Gymnastic block and KD Jahadhav/wrestling block were inspected by the officer concerned of this department on 07/08/2025 in the presence of Mr. Sanjeev (AE) & Mr. Rohit (AE) CPWD, and the following shortcomings were observed:-

Gymnastic block (Gr. + 2 upper floor)

1. MOEFA found nonfunctional.
2. Smoke Management system found nonfunctional and same is not integrated with detection /alarm system.

KD Jhadav / Wrestling block (Gr.+2)

1. Installation/integration of detection work found under installation.
2. PA system found nonfunctional.
3. MCP found non functional
4. Diesel Pump not in auto mode provision.
5. Yard hydrant found nonfunctional and hoses and branched not provided in some hydrants boxes.
6. Draw off connection & fire service inlet not approach for fire tender due to dumping of malba and other scrape item on approach road.

In view of above of above shortcomings, the Fire Safety Certificate (FSC) cannot be renewed at this stage. Therefore, you are requested to rectify above mentioned shortcomings and re-submit for further consideration in the matter.

Yours faithfully,


(Virendra Singh)
Chief Fire Officer
Delhi Fire Service

Copy to:-

1. Administrator, Sport Authority of India, IGI Stadium Complex, New Delhi.