



C/108



GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI-110001

No. F.6/DFS/MS/School/2025/SZ/621
To

Dated: 08/08/2025

M/s Amity International School,
Sector-7, Pushp Vihar Sector-7, M.B Road,
New Delhi- 110017

Sub: Regarding issuance of Fire Safety Certificate in r/o M/s Indraprastha Hindu Girls Senior Secondary School located at Pushp Vihar Sector-7, M.B Road, New Delhi-110017.

Sir,

This has reference with your letter no nil dated 15/07/2025 received through DFS outdoor diary no 3872 dated 17/07/2025 on the subject cited above. In this connection, it is to inform you that the inspection of above said building have been carried out by the officer concerned of this department on 29/07/2025 in the presence of Mr. Harshit to verify the fire safety measures installed in the building. During inspection, following points were observed:

1. Fire check door self closing door device found removed at some places.
2. First aid hose reel hose found non functional.
3. Automatic sprinkler system found non functional.
4. Internal hydrant found non functional.
5. Electrical Fire Pump capacity 2280 LPM, Diesel Engine Pump 2280 LPM and Jockey Pump 180 LPM found not on auto mode.
6. Exit signagc found removed at some places.

In view of above Shortcomings, the **application for issuance Fire Safety Certificate is rejected**. The occupancy of the building/premises in absence of requisite fire safety arrangements shall be at the risk and liability of the owner/occupier.

Yours Faithfully,

8/8/2025

(VIRENDRA SINGH)
CHIEF FIRE OFFICER
DELHI FIRE SERVICE

Copy to:-

1. The Directorate of Education, Govt. of NCT of Delhi, Old Secretariat, New Delhi-54.