

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI **HEADQUARTERS: DELHI FIRE SERVICE, NEW DELHI-110001**



No. F6/DFS/MS/2025/WZ/Hostel/ 302

FIRE SAFETY CERTIFICATE

Certified that the M/s International Youth Hostal Trust located at No.5 Nyaya Marg, Chankyapuri, New Delhi-110021, comprised of basement + ground + 03 upper floors but hostel is running at ground + 03 upper floor only, Gr. floor-Reception & Office, 1st floor-16 rooms, 2nd floor-19 rooms & 3rd floor-04 rooms, total-39 rooms only, has already been issued FSC by this department vide letter No. F.6/DFS/MS/SZ/Hostel/2021/531 dated 17.12.2021. The premises was reinspected by the officer concerned of this department on 23.04.2025 in the presence of Mr. Jogender Singh Walia and found that the said building have deemed complied with the fire prevention and fire safety requirements in accordance with Rule 33 of the Delhi Fire Service Rules, 2010 and that the premises fit for occupancy class Residential & Lodging 'Group-A' (Hostel Building) for ground + 03 upper floor only, total -39 rooms with effect from 2 0.5 2025 for a period of three years in accordance with Rule 36 unless renewed under Rule 37 or sooner cancelled under Rule 40 and subjected to compliance of the conditions under Rule 38 of the Delhi Fire Service Rules, 2010.

Issued on 02 05 2025 at New Delhi by

DIRECTOR Ph; 011-23414000

Ole

Copy to: -

1. MCD Portal ID-2025040105176 dated 06.04.2025.

CHL 2. The Joint Commissioner of Police (Lic.) 1st floor, Licensing unit, Police Station, Defence Colony, New Delhi-

Conditions for the validity of Fire Safety Certificate:

- 1. All the fire safety arrangement provided there-in shall be maintained in good working conditions at all times.
- 2. Loss of life or property due to non functional fire safety measure shall be at the responsibility of the management.
- 3. The trained fire fighting staff should be available round the clock.
- 4. Any deviation with regard to the construction etc shall be verified by the concerned building sanctioning agency.
- 5. This certificate cannot be treated in any case for regularizations of unauthorized construction.
- 6. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director of Form 'J' [sub rule (1) of rule 37] along with a copy of this Certificate, six months prior to its
- 7. The owner / occupier shall submit a declaration every year in form "K" provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on
- 8. All the means of escape shall be kept free of any obstruction all the time to evacuate the occupant, in a safe manner, in the event of emergency.

http://www.delhi.gov.in/wps/wcm/connect/doit_fire/FIRE/Home/Fire+Safety+Acts+and+ http://www.delhi.gov.in/wps/wcm/connect/doit_fire/FIRE/Home/Forms

		INSPI	ECTION REPO	RT		
address of the building N			M/s International Youth Hostal Trust located at No.5 Nyaya Marg, Chankyapuri, New Delhi-110021.			
	e address of the building	Chan	kvanuri N	th Hostal Trust located		
	/ wince	Pagid	lantial of L	lhi-110021.	at No.5 Nyaya Marg.	
	Type of Occupancy norised of building	Resid	lential & Lodging	'Group-A'	8,	
1	type of Occupancy Comprised of building	Dasei	ment + Ground + o	03 upper floors		
1	Comprise Type of Case	Gr fl	war (Ground + 03	03 upper floors 3 upper floors, Total-3 ffice, Kitchen & Dining		
(1.13	1 st flo	or-16 re-	ffice, Kitchen & Dining	9 rooms)	
	£	2 nd flo	Gr. floor-Reception, Office, Kitchen & Dining hall 2 nd floor-19 rooms			
		3 rd flo	or-04 rooms			
1	5. Details of Previous NOC	F.6/D	FS/MS/SZ/Hostal	/2021/-		
1	6. Fire Safety directives letter No	-NA-	or ozar ozar i ostel	/2021/531 dated 17.12.2	2021.	
1	7 Date of inspection	23.04.				
1	8. Name of Inspecting Officer	Sh. Aj	ay Kumar Sharma	(ADO P. LL		
-	Name and designation of officers	Mr. Jo	gender Singh Wal	(ADO Rohini)		
	From the building side		Bender Singil Wal	lia -		
	0. Year of Construction	1976 0	on MCD Portal			
		Online	annlication N. a.			
S.	Minimum Standards on fire preven	ntion	Old NOC	025040105176 dated 06	04.2025.	
No	Down I was a second to		Sid Moc	Provided at site	Remarks	
1.	Access to building		Requirement		MR/NMR	
	Road width		10			
	Gate width		12m	Provided	MR	
	Width of internal road		-NA-	-NA-	-NA-	
2.			-NA-	-NA-	-NA-	
2.	Number, Width, Type & Arrangen a. Number of staircases	ient of	Exits			
				9		
-	• Upper Floors		02nos.	02nos.	MR	
	• Basements		-NA-	-NA-	-NA-	
	b. Width of staircases					
	Upper Floor		1.25 & 1m	1.5m & 1m	MR	
	Basements		-NA-	-NA-	-NA-	
	c. Protection of exits					
	Fire check door		-NA-	-NA-	-NA-	
	Pressurization		-NA-	-NA-	-NA-	
	d. No. of continuous staircases to ter	race	01nos.	01nos.	MR	
	e. Width of Corridor		-NA-	-NA-	-NA-	
	f. Door Size		1m	1m	MR	
3.	Compartmentation					
	a) Fire check door		-NA-	-NA-	-NA-	
	b) Sealing of electrical shafts		-NA-	-NA-	-NA-	
	c) Fire Rating of shaft door		-NA-	-NA-	-NA-	
	d) Water Curtain	HAR!	-NA-	-NA-	-NA-	
	e) Fire Dampers	W 11	-NA-	-NA-	-NA-	
4.	Smoke Management System		-NA-	-NA-	-NA-	
	a) Basements	1000	12 a/c per hour	Natural ventilated	MR	
	b) Upper floors		12 we per nour 1	La La Callando		
5.	Fire Extinguishers a) Total numbers	1215	20nos.	Provided	MR	
	b) Types		ABC/CO2	ABC/CO2	MR	
	c) IS marking		ISI marked	Yes	MR	
	0) 10 111111111111111111111111111111111	W-1-1-1				

]	First-Aid Hose Reels		Provided	MR
	a) Total numbers on each floor	01nos.	Provided	MR
	b) Length of hose reel hose	30mm	Provided	MR
	c) Nozzle diameter	5m	Plovides	NIA
	Automatic fire detection and alarming system	em	-NA-	-NA-
	a) Type of detectors	-NA-	-NA-	-NA-
	b) Location of Main Panel	-NA-	-NA-	-NA-
	c) Location of Repeater Panel	-NA-	-NA-	-NA-
	d) Alternate source of power	-NA-	-NA-	MR
	e) Hooters' Location	-NA-	Provided	MR
	MOEFA	Required	Provided	WIIC
	Public Address System	Required		-NA-
0.	Automatic Sprinkler System	NIA	-NA-	-NA-
	a) Basement	-NA-	-NA-	-NA-
	b) Ground & Upper Floors		-NA-	-11/22
	c) Sprinkler above false ceiling	-NA-		MR
1.	Internal Hydrants	Required	Provided	MR
	a) Size of riser/down-comer	02nos.	Provided	MR
	b) Number of hydrants per floor	02nos.	Provided	IVIIC
	c) Hose Box	021100.		-NA-
2.	Yard Hydrants	-NA-	-NA-	-NA-
	a) Total number of hydrants	-NA-	-NA-	-NA-
	b) Hose Box	1		MR
13.	Pumping Arrangements	Required	Provided	MR
	Ground Level Ground Level Ground Level	1500lpm	Provided	
,	Discharge of main Pump	40m	Provided	MR
	Head of Main pumpNumber of main pumps	01nos.	Provided	MR
	- 1 Dumn out put	-NA-	-NA-	-NA-
	- 1 mumn head	-NA-	-NA-	-NA-
	> Jockey pump nead > Standby Pump out put	-NA-	-NA-	-NA-
	Grandby Pump Head	-NA-	-NA-	-NA-
	> Auto Starting/Manual Stopping	-NA-	-NA-	-NA-
	> Pump House Access	-NA-	-NA-	-NA-
	Terrace level			
	> Discharge of pump	450lpm	Provided	MR
	> Head of the pump	35m	Provided	MR
	> Power Supply	Required	Provided	MR
	Auto Starting of pump	Required	Provided	MR
14	Captive Water Storage for fire fighting			
14	Underground tank capacity	50,000ltr	Provided	MR
	> Draw-off connection	-NA-	-NA-	
	> Fire service inlet	Required	The same of the sa	-NA-
	> Access to tank	Required	Provided	MR
	Overhead Tank capacity	10,000ltr	Provided	MR
	G' a ga	Required	Provided	
	· i-n of Lifts	required	Provided	MR
1	a) Pressurization of Lift Shaft	27.4		MR
	b) Pressurization of Lift lobby	-NA-	-NA-	
	0) 11000	-NA-		
			-NA-	-NA-

M	١.		1	
14	1	5)	
	1	_	-	

an's Grounding Switch	Required	Provided	
amunication In Switch	Required	Provided	MR
	Required	Provided	MR
in Signage	Required		MR
No power supply		Provided	MR
Apply power supply Apply Area. Area Area	-NA-	-NA-	
Total Area	-NA-	-NA-	-NA-
a) location b) location		MA-	-NA-
h) Tocation Fire Control Room Detector System Panel a) Detector Panel	-NA-	-NA-	NA
a) Blow Switch Panel	-NA-	-NA-	-NA-
pA System Paller	-NA-	-NA-	-NA-
d) Battery backup	-NA-	-NA-	-NA-
Building Floor Plans	-NA-	-NA-	-NA-
Special Fire Protection System for	-NA-	-NA-	-NA-
protection of special Risks, if any:			
Accordingly, the fire protection systems pr	ovided in the building	g were tested/ checke	d randomly ar

Accordingly, the fire protection systems provided in the building were tested/ checked randomly and found in working condition at the time of inspection.

In view of the deemed compliance of the minimum standards of the fire prevention and fire safety measures as required under the rules the NOC issued vide letter no. F.6/DFS/MS/SZ/Hostel/2021/531 dated 17.12,2021 is recommended for renewal under rule 37 of the Delhi Fire Service rules 2010.

> Signature of the Inspecting Officer Name Ajay Kumar Sharma Designation ADO(Rohini)

DO (S

up for said benesal and