

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUATERS: DELHI FIRE SERVICE: NEW DELHI-110001



No. F.6/DFS/MS/Hospital/2025/SZ/1558

Dated: 04 / 09 /2025

To

Sh. Bijender Singh, Dy. Chief Security Officer, Administrative Block, AIIMS, New Delhi–110029

Sub: Renewal of Fire Safety Certificate in r/o JPN Apex Trauma Centre, AIIMS, Raj Nagar, New

Delhi-110029

Sir,

This has a reference to your letter No. Nil dated 11/08/2025 received in this department vide outdoor diary No. 4759 dated 12/08/2025, on the subject cited above. In this connection, it is informed that the said premise was inspected by the officer concerned of this department on dated 20/08/2025 in the presence of Sh. Manoj Kumar (AEE) & Sh. Sailesh Kumar, ASO (Fire Safety) to verify the compliance of shortcomings issued vide this office letter No. F.6/DFS/MS/Hospital/2025/SZ/307 dated 23/06/2025 and observed that the maintenance work is under progress and system was not inspection worthy also lift was under found repair/rectification. Hence, inspection from fire safety point of view could not be conducted.

In view of the above, renewal of fire safety certificate cannot be considered at this stage. you are requested to apply afresh as and when maintenance/repair work is completed for further action in the matter.

Yours faithfully,

(Virendra Singh) Chief Fire Officer Delhi Fire Service

2148

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE CONNAUGHT PLACE: NEW DELHI-110001

No. F.6/DFS/MS/Hospital/2025/SZ/ 3 07

Dated: 23/06/2025

To

Sh. Salesh Kumar, ASO (Fire Safety), Administrative Block, AIIMS, New Delhi–110029

Sub: Renewal of Fire Safety Certificate in r/o JPN Apex Trauma Centre, (AIIMS), Raj Nagar, New Delhi-110029

Sir,

This has reference to the email received from Id: salesh@aiims.gov.in dated 22/05/2025, on the subject cited above. In this connection, the officer concerned of this department visited the premise on dated 11/06/2025 in the presence of Sh. B.S. Yadav (Dy. CSO) to verify the compliance of shortcomings issued by this department vide letter No. F.6/DFS/MS/Hospital/SZ/2024/85 dated 29/02/2024 and the status of shortcoming observed is as below.

S. No.	Shortcomings issued	Present Status
1.	Half of the smoke ventilation system in basement found non-functional.	Not Complied
2.	Some of the sprinklers are above ventilation duct in basement.	Not Complied
3.	Hose Reels provided but non-functional in Blk A.	Complied
4.	The internal hydrants non-functional and rusted/corroded.	Not Complied
5.	Some of the yard hydrant hose boxes without hoses and branch	Complied
6.	Fire pumps still not on auto mode.	Complied

Additional observation :-

1. Lifts provided found under repair/replacement.

In view of the above, the renewal of fire safety certificate cannot be considered at this stage. You are requested to complete the repair/renovation work under intimation to this department for further action in the matter.

Yours faithfully

DIRECTOR Ph 041 23414000

Ph. 011-23414000