GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE, CONNAUGHT PLACE

NEW DELHI- 110001

No. F.6/DFS/MS/EH/2025/SZ/ 132

Dated: 17/04/2025

FIRE SAFETY CERTIFICATE

Certified that the M/s Kadimi's Food Pvt. Ltd. running at second floor only in a building comprised of ground plus three upper floors, located at Plot No. 7, Sector- 11, Pkt-IV, Dwarka, Delhi-110075, was issued Fire Safety Certificate vide Letter F.6/DFS/MS/EH/SZ/2021/329 dated 09.11.2021. The Restaurant building was re-inspected by the officer concerned of this department on dated 09.04.2025 in the presence of Sh. Manish Jain and found that the restaurant have deemed complied with the fire prevention and fire safety requirements in accordance with Rule 33 of the Delhi Fire Service Rules, 2010 and that the restaurant building/premises (Second Floor only) is fit for occupancy class Group "D" Assembly Building" with effect from 17/04/2025 and valid up-to 31.03.2028, in accordance with Rule 36 unless renewed under Rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under Rule-38 of the Delhi Fire Service Rules, 2010 printed below.

Issued on 17 04 2025 at New Delhi.

Delhi Fire Service

Online application Id 2025031904009 dated 20.03.2025

Conditions for validity of Fire Safety Certificate: -

- 1. This FSC is valid only for Second floor.
- 2. All the fire safety arrangements provided therein shall be maintained in good working condition at all times.
- 3. The means of escape shall be kept unlocked and unobstructed for unhindered evacuation
- 4. Any loss of life or property due to non-functional fire safety measures shall be at the risk
- 5. The trained staff should be available round the clock.
- 6. Any deviations w.r.t. construction shall be verified by the concerned building
- 7. The certificate may not be treated in any case for the regularization of the unauthorized construction, if any.
- 8. The owner/occupier shall submit a declaration every year in the form 'K' provided in the first schedule of Delhi Fire Service Rules 2010, form is available on
- 9. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in the Form 'J' [sub rule (1) of rule 37] along with a copy of this Certificate, six months prior to its expiry.

INSPECTION REPORT 1. Name & address of the building:

M/s. Kanimi Food Pvt. Ltd. at 2nd floor, Plot No. 7, Sector-11, Pkt-

2. Building is comprised of IV, Dwarka, New Delhi- 110075.

3. Type of Occupancy G+3 upper floors (Restaurant running at 2nd floor only

4. Type of Case Group D (Assembly)

5. Details of Previous NOC Renewal

F.6/DFS/MS/EH/SZ/2021/329 dated 09.11.2021 6. Fire Safety directives letter No

7. Date of inspection N/A 09.04.2025

8. Name of Inspecting Officers A.D.O. R.K. Yadav (JKP)

9. Name and designation of officers From the building side

Mr. Manish Jain 10. Year of Construction Before, 2009

	11. Applicant's letter No.	: MHA Portal ID	2025031904000 dated 20 03 202	5		
S.	Minimum Standards on fire	: MHA Portal ID 2025031904009 dated 20.03.2025				
No.	prevention and fire safety U/R 33	Requirements Under 35 (6)	Provided at site	Remarks MR/NMI		
۱.	Access to building	(0)		WINT		
	Road width	06 m	D 11.1	14/0		
	 Gate width 	4.5 m	Provided	M/R		
	 Width of internal road 	NI/A	Direct accessible from road N/A	N/A N/A		
2.	Number, Width, Type & Arrangeme	nt of Exits	IVA	N/A		
	a. Number of staircases					
	Upper Floors	01 no's	01 no's	MR, old ca		
	 Basements 	N/A	****	_		
	b. Width of staircases	IN/A	N/A	N/A		
	Upper Floor	1.25 m	1.25 m (including railing)	MR, old cas		
	• Basements	N/A	N/A	N/A		
	c. Protection of exits	IVA	IVA	IVA		
	Fire check door	N/A	N/A	N/A		
	 Pressurization 	N/A	N/A	N/A		
		12	11/11	11/11		
	d. No. of continuous staircases to	01 No's	Provided	MR		
	terrace	N/A	N/A	N/A		
	e. Width of Corridor f. Door Size	02 m each	1.25 m & 1.0 m (including door frame)	MR, old case		
3.	Compartmentation		Jeer mane)			
	Fire check door	N/A	N/A	N/A		
	 Sealing of electrical shafts 	N/A	N/A	N/A		
	 Fire Rating of shaft door 	N/A	N/A	N/A		
	Water Curtain	N/A	N/A	N/A		
	Fire Dampers	N/A	N/A	N/A		
4.	Smoke Management System					
	Basements	N/A	N/A	N/A		
	Upper floors	12 ACPH	Natural Ventilation provided	MR		
5.	Fire Extinguishers					
	Total numbers in restaurant	04 no.'s	Provided	M/R		
	• Types	ABC/CO ₂	ABC- 04 & Co2- 04	M/R		
	IS marking	ISI marked	Provided	M/R		
6.	First-Aid Hose Reels					
	Total numbers at each floor	1 Nos.	Provided	M/R		
	 Length of hose reel hose 	30 m	Provided	M/R		
	Nozzle diameter	5 mm	Provided	M/R		

M	17
IV	1 3

7.	Automatic fire detection and alarming Type of detectors Smoke/User	MIX		
	• Type of day	system in restaurant		
	Type of detectors Smoke/Heat Location of Main Property o	N/A	0 1 "	
		N/A	Smoke/heat	N/
	Location of Repeater Panel Alternate and Alternate are a second and a second are a seco	N/A	N/A	N/.
	 Alternate source of power Hooters' Location 	N/A	N/A	N/.
8.		N/A	N/A	N/A
	MOEFA		N/A	N/A
9.	Public Address System	Required	Provided	M/I
10.	Automatic Sprinkler System	N/A	N/A	N/A
	Basement		P.	
	1	N/A	N/A	N/A
	• Upper floors	Required	Provided	MR
	Sprinkler above false ceiling	N/A	N/A	N/A
11.	Internal Hydrants		1771	IN/A
	• Size of riser/down-comer	100101		
	• Number of hydrants	100 MM	Provided	M/R
	Hose Box	01 no's	Provided	M/R
12.	Yard Hydrants	01 no's	Provided	M/R
	• Total number of hydrants	N/A	N/A	N/A
	Hose Box	N/A	N/A	N/A
13.	Pumping Arrangements			19/11
	Ground Level			
	Discharge of main Pump	N/A	NI/A	27/4
	➤ Head of Main pump	N/A	N/A	N/A
	Number of main pumps		N/A	N/A
	> Jockey Pump out put	N/A	N/A	N/A
	> Jockey pump head	N/A	N/A	N/A
	, Famp nead	N/A	N/A	N/A
	> Standby Pump out put	N/A	N/A	N/A
	Standby Pump Head	N/A	N/A	N/A
	➤ Water curtain Pump	N/A	N/A	N/A
	➤ Auto Starting/Manual	N/A	N/A	N/A
	Stopping			
		N/A	N/A	N/A
	> Pump House Access			
	Terrace level	Boosting pump	450 & 180 LPM	M/R
	Discharge of pump	40 m	Provided	M/R
	> Head of the pump	Required	Provided	M/R
	Power SupplyAuto Starting of pump	Required	Provided	M/R
	7 Auto starting of pump	Required	Flovided	IVI/K
14.	Captive Water Storage for fire-fighting		1	
	Underground tank capacity	N/A	N/A	N/A
	Draw-off connection	N/A	N/A	N/A
	> Fire service inlet	Required	Provided	M/R
	> Access to tank	N/A	N/A	N/A
	Overhead Tank capacity	5,000 ltrs	Provided	M/R
15.	Exit Signage.	Required	Provided	M/R
	Provision of Lifts			
16.	Di_tion of I ift Shaft	N/A	N/A	N/A
		N/A	N/A	N/A
	Pressurization of Lift lobby Output Description In lift Car.	N/A	N/A	N/A
	Communication In lift Car	N/A	N/A	N/A
	Fireman's Grounding Switch	N/A	N/A	N/A
	 Lift Signage 	IN/A	1 1/1 1	1 1/1 1

17.	Standby power supply	Required	Provided (DG Set)	M/R		
18.	Refuge Area.					
	> Total Area	N/A	N/A	N/A		
	> Location	N/A	N/A	N/A		
19.	Fire Control Room					
	 Detector System Panel Flow Switch Panel PA System Panel Battery backup 	N/A	N/A	N/A		
		N/A	N/A	N/A		
		N/A	N/A	N/A		
	Building Floor Plans	N/A	N/A	N/A		
		N/A	N/A	N/A		
20.	Special Fire Protection System for Protection of special Risks, if any:	Required	CO2 Fire Extinguisher provided near elect. Panel.	N/A		

The fire protection systems provided in the building were tested/checked and found functional at the time of inspection.

Note: - Shortcomings issued by this department letter No. F.6/DFS/MS/SZ/2024/524/524 dated 28.11.2024 have been rectified. Restaurant running at second floor in a building comprised of ground plus three upper floors.

Keeping in view of the deemed compliance of the minimum standards of fire prevention and fire safety measures as required under the rules the FSC issued vide letter No. F.6/DFS/MS/EH/SZ/2021/329 dated 09.11.2021, renewal under rule 37 of the Delhi Fire Service Rules 2010 is recommended.

Accordingly, DFA is put up for approval & signature please.

Signature of the Inspecting Officer

Name- R.K. Yadav Designation- ADO (JKP)

DO (8W)

11/4/25

nent)/M

Directer/ My

BIMI