GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI- 110001

No. F6/DFS/MS/BNQT/SZ/2025 42

Dated:-

आजादी का अमृत महोत्सव १५०७ २०२५

FIRE SAFETY CERTIFICATE

Certified that the M/s. La Fortuna Banquet, located at A-146, Mayapuri, Industrial Area Phase-II, New Delhi-110064, comprised of Basement ground plus two upper floors only, owned/occupied by M/s. La Fortuna (A Unit of Warner Hospitality), was issued Fire Safety Certificate by this department Vide Letter No. F6/DFS/MS/BNQT/2021/SZ/575 dated 23/11/2021. The said premise was re-inspected by the officer concerned of this department on 04/07/2025 in the presence of Shiv Hari Mongia (Director) and found that the banquet hall building have deemed complied with the fire prevention and fire safety requirements in accordance with the Rule 33 of the Delhi Fire Service Rules, 2010 and that the premises/building is fit for occupancy class "Assembly" Group D (Banquet Hall) for ground plus two upper floors only, with effect from 14 or sooner cancelled under Rule 40 and subject to compliance of the conditions under Rule 38 of the Delhi Fire Service Rules 2010, printed below.

Issued on 14/07/2025 at New Delhi by

Director Tel No. 011-23414000

Copy to:-

 The Commissioner, Municipal Corporation of Delhi, Civic Centre, Minto Road, New Delhi-110002:- in r/o computer id no. 2025062510563 dated 25/06/2025

2. The Joint Commissioner of Police, Licensing unit, 1st Floor, Police Station, Defence Colony, New Delhi

3. The Authorized Signatory, M/s. La Fortuna Banquet, A-146, Mayapuri Industrial Area Phase-II, New Delhi-110064.

Conditions for the validity of Fire Safety Certificate:-

1. All the means of escape shall be kept free of all type of obstruction all the time.

 All the employees shall be acquainted with the use and maintenance of all fire equipments and method of smooth and speedy safe evacuation of occupants in case of emergency.

3. All the fire fighting equipments shall be maintained in perfect working condition all the time and any lapse rendering non-functional if fire safety measures, management shall be responsible.

4. Any deviation, with regards to construction, ventilation, occupation, electric installation etc. may be got verified from the concerned authorities.

5. The Fire Safety Certificate may not be treated in any case for regularizations of unauthorized construction / unauthorized use of land if any.

6. All comments / directions of licensing Department shall always be permitted and followed.

7. The owner /occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rule 2010. The form is available on www.dfs.delhigovt.nic.in

8. The owner / occupier shall apply for renewal of this Fire Safety Certificate to the Director in 'Form J' (sub Rule (1) of Rule 37) along with copy of the certificate, six months prior to its expiry.

9. The basement shall be used as per BBL. Presently being used as storage.

1128

INSPECTION REPORT

1. Name & address of the building : M/s. La Fortuna Banquet, located at A-146, Mayapuri

Industrial Area Phase-II, New Delhi-110064

2. Type of Occupancy : Assembly Building (Group-D)

3. Type of Case : Renewal

4. Details of previous NOC : F6/DFS/MS/BNQT/2021/SZ/575 dated 23/11/2021

5. Fire Safety directives Letter No.: Nil

6. Date of inspection : 04/07/2025

7. Name of the Inspecting Officer : Aman Kumar Lathar, ADO (JWP)

Name and designation of Officer

from the building side : Sh. Shiv Hari Mongia (Director)

9. Year of Construction : 2009

10. Applicant's Online ID. : 2025062510563 dated 25/06/2025

S No	Minimum standards on fire prevention and fire safety U/R 33	Requirements as pe earlier FSC issued dated 23/11/2021	r Provided at site	Remarks MR/NMR			
1.	Access of building MR						
	Road width	09 m	12 m-	NA			
	Gate width	4.5 m	Direct accessible from road	PAGENTAL SE			
	Width of internal road	NA	NΛ	NA			
2.	Number, width, Type & Arrangements of exits						
	a. Number of staircases						
	Upper floors Basements	02 nos.	Provided	MR			
		02 nos.	Provided	MR			
	b. Width of staircases						
	Upper floors Basements	1.5 m each	1.5 m each	MR			
		1.5 m each	1.5 m each	MR			
	c. Protection of exits						
	 Fire check door Pressurization d. No of continuous staircase to terrace e. Width Of Corridor f. Door Size 	Required	Provided	MR			
		NΛ	NA	NA			
		02 nos.	Provided	MR			
		n	0	MD			
		Required	Opening in hall	MR			
		2.0 m	3.75 m, 2.70 m & 1.70 m	MR			
3.	Compartmentation						
	 Fire check door Sealing of electrical shafts Fire Rating of shaft door Water Curtain Fire Dampers 	Required	Provided	MR			
		Required	Provided	MR			
		NA	NA	NA			
		NA	NA	NA			
		NA	NA	NA			
4.	Smoke managements System						
	Basements	Required	Provided'	MR			
	Upper floors	Required	Provided	MR			
5	Fire Extinguishers						
5.	Total numbers	20 nos.	Provided	MR			
	Types	ABC & CO ₂	Provided	MR			
	ISI marking	ISI marked	Provided	MR			
				1411			
6.	Total numbers on each	02	Provided	MR			
	floor	30 m	Provided	MD			
	 Length of hose reel hose Nozzle diameter 	05 mm	Provided	MR MR			

	91.		127				
7. At	Automatic fire detection and alarming system			-			
	 Type of detectors 	Required	Provided	MR			
	 Location of Main Panel 	Required	Provided	MR			
	 Location of Repeater Panel 	NA	NA	NA			
	 Alternate source of power 	Required	Provided	MR			
	 Hooters' Location 	Required	Provided	MR			
4	OEFA	Required	Provided	MR			
	ublic Address System	Required	Provided	MR			
10. A	utomatic Sprinkler System						
	Basements	Required	Provided	MR			
	Upper Floor	Required	Provided	MR			
	Sprinkler above false ceiling	Required	Provided	MR			
11. In	nternal Hydrants:	100					
	Size of riser/down-comer	100 mm	Provided	MR			
	Number of hydrants per floor	02 nos.	Provided	MR			
	Hose Box	02 nos.	Provided	MR			
12. Y	ard Hydrants	02 1103.	riovided	MIK			
	Total number of hydrants	Required	02 nos.	MR			
	Hose Box	Required	02 nos.	MR			
13. P	umping Arrangements:	12-		114			
	Ground Level						
	Discharge of main pump	2280 lpm	Provided	MR			
	➤ Head of main pump	60 m	Provided	MR			
	Number of main pumps	01	Provided	MR			
	 Jockey pump out put 	180 lpm	Provided	MR			
	Jockey pump head	60 m	Provided	MR			
	Standby Pump out put	2280 lpm	Provided	MR			
	 Standby Pump Head Auto Staring/Manual 	60 m	Provided	MR			
	Auto Staring/Manual stopping	Required	Provided	MR			
	> Pump House Access	Required	Provided	MR			
	Terrace level	required	Trovided	ATIA			
	Discharge of pump	900 lpm	Provided	MR			
	Head of the pump	40 m	Provided	MR			
	Power supply	Required	Provided	MR			
	Auto starting of pump	Required	Provided	MR			
14.	Captive water Storage for fire fighting:						
	 Under ground tank capacity 	50,000 ltrs.	Provided	MR			
	Draw off connection	NA	NA	NA			
	Fire service inlet	Required	Provided	MR			
	Access to tank Overhead Tank conneity	Required	Provided	MR			
15 1	Overhead Tank capacity Exit Signage	10,000 ltrs. Required	Provided Provided	MR MR			
	Provision of Lifts	Required	Tovided	NIK			
	➤ Pressurization of Lift Shaft	NA	NA	NA			
	➤ Pressurization of lift lobby	NA	NA	NA			
	 Communication in lift Car 	NΛ	, NA	NA			
	Fireman's Grounding	Required	Provided	MR			
	Switch Lift Signage	Required	Provided	MR			
17.	Standby power supply	Required	Provided	MR			
1	Refuge Area						
	➤ Total area	NA	NA	NA			
	> Location	NA	NA	NA			
19.	Fire control room	b 1444 1	era III	V 4 44			
	 Detector system panel 	NΛ	NA NA	NA			
	Flow Switch Panel	NA NA	NA.	NA			
	PA System Panel	NA NA	NA NA	NA NA			
	 Battery backup Building Floor Plans 	NA NA	NA NA	NA NA			
20.	Special Fire Protection Systems for	0 10	NA NA	NΑ			
Kell.	Protection of special Risks, if any;	W.	, 37.3				

The fire protection systems provided in the building were checked and found functional at the time of inspection. The shortcomings issued vide letter no. F6/DFS/MS/Banquet/2024/SZ/108 dated 10/09/2024 found rectified.

In view of the deemed compliance of minimum standards of fire prevention and fire safety measured as required under the rules, the FSC issued vide letter no. F6/DFS/MS/BNQT/2021/SZ/575 dated 23/11/2021 for ground plus two upper floors only, renewal under rule 37 of the Delhi Fire Service Rule 2010 is recommended.

Accordingly, DFA is prepared & put up for approval please.

Aman Kumar Lathar ADO (JWP)

F.T. letter is put-up for your rignature A.