

## GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI **HEAD QUARTERS: DELHI FIRE SERVICE: NEW DELHI – 110001**



No F 6/DFS/MS/EH/2025/SZ/ 255

Dated: 03/07/2025

## FIRE SAFETY CERTIFICATE

Certified that the M/s Mala Akbari Restaurant (A Unit of Mala Akbari Hospitality North Pvt. Ltd.) located at T-304, 3rd Floor, Ambience Mall, Plot No. 2, Nelson Mandela Marg, Vasant Kunj, New Delhi-110070 in a building comprised of Three tier Basement, ground plus three upper floors was issued FSC by this department vide letter No F6/DFS/MS/EH/2022/SZ/172 dated 13.06.2022. The premise was re-inspected by the officer concerned of this department on 25.06.2025 in the presence of Ms. Kavi and observed that all the fire prevention and fire safety arrangements as provided in the premises found in good working condition. The premises have therefore complied with fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and that the building/ premise is fit for occupancy "Assembly (Group D)" (Restaurant at 3rd floor only) with effect from and valid up to 31/03/2028 in accordance with the Rule 36 unless renewed under Rule 37 or sooner cancelled under Rule 40, subject to compliance of the conditions under Rule 38 of the Delhi Fire Service Rules, 2010.

Issued on .... 0.3. 0.7. 2.2.5. at New Delhi, by

Delhi Fire Service

## Copy to: -

- 1. Owner/ occupier, M/s Mala Akbari Restaurant (A Unit of Mala Akbari Hospitality North Pvt. Ltd.) located at T-304, 3rd Floor, Ambience Mall, Plot No. 2, Nelson Mandela Marg, Vasant Kuni, New Delhi-110070 .
- 2. The Dy. Health Officer, MCD, South Zone, Public Health Department, Aurobindo Marg, Green Park, New Delhi.
- MCD Portal, ID No. 2025052208909.

## Conditions for the validity of Fire Safety Certificate:

- 1. All the fire safety arrangement provided there-in shall be maintained in good working conditions at all times.
- 2. Loss of life or property due to non functional fire safety measure shall be at the responsibility of the management.
- 3. The trained fire fighting staff should be available round the clock.
- 4. Any deviation with regard to the construction etc shall be verified by the concerned building sanctioning agency.
- 5. This certificate cannot be treated in any case for regularizations of unauthorized construction.
- 6. The owner/occupier shall apply for renewal of this Fire Safety Certificate through MCD portal (https://www.mcdonline.nic.in) along with a copy of this Certificate, six months prior to its expiry".
- 7. The owner / occupier shall submit a declaration every year in form "K" provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in
- 8. The basement shall be used as per BBL.

INSPECTION REPORT

1. Name & address of the building: M/s Mala Akbari Restaurant (A Unit of Mala Akbari Hospitality North Pvt. Ltd.) located at Shop No. T-304, 3<sup>rd</sup> Floor, Ambience Mall, Plot No.

2, Nelson Mandela Marg, New Delhi- 110070.

Type of Occupancy Type of Case

Assembly (Restaurant) at 3<sup>rd</sup> floor.

4. Details of Previous NOC

Renewal

5. Fire Safety directives letter No

F6/DFS/MS/EH/2022/SZ/172 Dated 13/06/2022

6. Date of inspection

Nil

7. Name of Inspecting Officer

25/06/2025

8. Name and designation of officers

R.K.Sinha, ADO (BW)

From the building side

Ms. Kavi

9. Year of Construction

2006 as per MCD Portal

10. Applicant's letter No.

MCD Application ID No. 2025052208909 dated 12/06/2025

The said restaurant is running at 3rd floor in Ambience Mall, Vasant Kunj in a building comprised of three tier basement, ground plus three as renewed ESC vide letter no F6/DFS/MS/Mall/2023/SZ/35

0.	Minimum Standards on fire prevention and fire safety U/R 33	As per inspection report dated 04/06/2022	Provided at site	Remarks MR/NMR				
•	Access to building F6/DFS/MS/Mall/2023/SZ/35 dated 25/01/2023							
	Road width	Restaurant within mall	As above	MR				
	Gate width		As above	NA				
	Width of internal road	NA	As above	NA				
	Number, Width, Type & Arrangement of Exits							
		Mall Mall						
	a. Number of staircases		02 As above					
	Upper Floors		NA NA	NA				
	Basements	NA NA	1471					
	b. Width of staircases		ovided & Maintained by Ambience Mall  As above MR					
	Upper Floor	Required		NA				
	Basements	NA	NA					
	c. Protection of exits	Provided & Maintained by Ambience Mall  As above MR						
	Fire check door	Required	As above					
	Pressurization	NA	NA	NA				
	d. No. of continuous staircases to terrace	Required	As above	MR				
	e. Width of Corridor	NA	NA	NA				
	f. Door Size	2 exits	2 m, 2 × 1 m	MR				
3.	Compartmentation	Provided & Maintained by Ambience Mall						
э.		Required	As above	MR				
	Fire check door	NA NA	As above	NA				
	Sealing of electrical shafts	NA	NA	NA				
	Fire Rating of shaft door	NA NA	NA	NA				
	Water Curtain	NA NA	NA -	NA				
	Fire Dampers	Provided & Maintained by Ambience Mall						
4.	SHOKE Management of							
	Basements	NA NA		MR				
	Upper floors	Required	Exhaust fan provided					
5.	Fire Extinguishers	04 Nos.	Provided	MR				
	Total numbers		Provided	MR				
	Types	ABC/Co2 Type	Provided	MR				
	IS marking	Required Provided & Maintained		IVLK				
6.	First-Aid Hose Reels	05 for restaurant	Provided Provided	MR				
	Total numbers on each floor	30 m	Provided	MR				
	Length of hose reel hose	5 mm	Provided	MR				
7.	Automatic fire detection and alarm	Smoke/Heat						
	Type of detectors	Required	As above	MR MR				
	Location of Main Panel	NA	NA NA					
	Location of Repeater Panel	100000000000000000000000000000000000000		NA NA				
	Alternate source of power	Required	uired As above MR					

		,						
	Hooters' Location	Requir	ed	As abov	e	N		
8.	MOEFA	Requir	ed	As abov	re	N		
9.	Public Address System			е	N			
10		Provided &	Provided & Maintained by Ambience Mall					
100	Basement		Required As above			MR		
1	Upper Floor	Required in	restaurant	Provided		MR		
	Sprinkler above false ceiling	NA NA	1	NA		NA		
11.	- 11 10 75 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1							
	Size of riser/down-comer		Required As above			MR		
	Number of hydrants per floor	Require	Required		As above			
	Hose Box	Require	d	As above		MR MR		
12.	Yard Hydrants	Provided & N	Provided & Maintained by Ambience Mall					
	Total number of hydrants	NA As above				NA		
	Hose Box	NA				NA		
13.	11050 201							
	Ground Level							
	Discharge of main Pump	4500 lpm	i	As above	1	MR		
	Head of Main pump	70 m		As above		MR		
	Number of main pumps	02		As above				
	Jockey Pump out put	450 lpm				MR		
	Jockey pump head	70 m		As above		MR		
	Standby Pump out put	4500 lpm		As above		MR		
	Standby Pump Head	70 m		As above		MR		
	Auto Starting/Manual Stopping	Required		As above		MR		
				As above		MR		
	Pump House Access	Required		As above	1	MR		
ě.	Terrace level							
	Discharge of pump	NA		NA		NA		
	Head of the pump	NA		NA		NA NA		
	Power Supply	NA		NA		NIA		
	Auto Starting of pump	NA		NA		NA NA		
4.								
	Underground tank capacity	500,000 ltrs		As above		) (D		
. 1	Draw-off connection	Required		A CONTRACTOR OF THE CONTRACTOR		MR		
1	Fire service inlet	Required		As above		MR		
t	Access to tank			As above		MR		
+	Overhead Tank capacity	Required		As above		MR		
5.	Exit Signage.	20,000 ltrs Required		As above Provided		MR		
		Required	.4	Flovided		MR		
5.	Provision of Lifts. Provided & Maintained by Ambience Mall							
-	Pressurization of Lift Shaft	NA		NA		NA		
	Pressurization of Lift lobby	NA		NA		NA		
	Communication In lift Car	NA		NA		NA NA		
	Fireman's Grounding Switch	NA						
	Lift Signage		-	NA		NA		
	Standby power supply	NA Paris I		NA		NA		
	CAS 1800 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	Required	a	Provided		MR		
R	Refuge Area.							
	otal Area	NA		NA		TA.		
	ocation	NA		NA		NA NA		
L	ocation	Fire Control Room Provided & Maintained by Ambience Mall						
	WASHINGTON COLUMN	Provided & Main	itained by A	ambience Mall				
Fi	re Control Room							
Fi De	re Control Room	NA	Asa	above		NA		
Fi De Flo	re Control Room  etector System Panel ow Switch Panel	NA NA	As a	above above		NA		
Fi De Flo PA	re Control Room  stector System Panel ow Switch Panel System Panel	NA NA NA	As a	above above above		NA NA		
PA Bat	re Control Room  etector System Panel ow Switch Panel	NA NA	As a	above above		NA		

	N-+		
NA	As above	NA	
	NA	NA As above	NA As above NA

The fire protection systems provided in the building were tested, checked and found functional at the time of inspection.

Keeping in view of the deemed compliance of the minimum standards of fire prevention and fire safety measures as required under rules it is recommended to renew the fire safety certificate issued vide letter no. F6/DFS/MS/EH/2022/SZ/172 dated 13/06/2022 under Rule 37 of the Delhi Fire Service Rules, 2010.

> Signature of Inspecting Officer Name: Rajeev Kumar Sinha Designation: ADO/B.W.