



No: F.6/DFS/MS/School/2025/WZ/ 358

Dated: 07 05 2015

To.

The Principal, MC Primary School, Sec A-10, Pocket-7, Narela, Delhi-110040.

Sub: - Regarding issuance of Fire Safety Certificate in r/o MC Primary School located at Sec. A-10, Pocket A-7, Narela, Delhi- 110040.

Sir,

This has reference to your e mail id dated 21/04/2025 on the subject cited above. In this connection, it is to inform you that the inspection of above said school building has been carried out by officer concerned of this department on 29.04.2025 to see the to see the compliance of shortcomings issued vide letter no. F6/DFS/MS/2013/School/2104 dated 27/08/2013. Smt. Manju Bala Tanwar (In-charge) was present at the time of inspection.

During the course of inspection it was observed that school building is comprised of 07 Blocks of Ground Floor only (06 Blocks- Porta Cabin & 01 Block- Pucca). Your request for issuance of FSC is rejected due to the following shortcomings:-

1. Road width found 4.5 m against the required width of 6 m.

2. Class room door width found 90 cm against the required width of 1 m.

3. Electrical meter installed inside the class room has to be removed to a safer place immediately.

You are advised to rectify the above-mentioned shortcomings under intimation to this department.

Yours Faithfully

Director 011-23414000

Ph. 011-23414000

Copy to:-

1. Director of Education, MCD, Civic Centre, New Delhi.