

00

No. F6/DFS/MS/WZ/2025/ Sol 7 6

Dated: 29/01 /2025

To,

The Principal, M.C. Primary Co-ed School, Onkar Nagar, A- Block, New Delhi- 110035.

## Sub: - Inspection report in r/o M.C. Primary Co-ed School located at Onkar Nagar, A Block, Delhi- 110035.

Sir,

This is in reference to your e mail id dated 26/12/2024 on the subject cited above. In this connection, it is to inform you that the above said school building was re-inspected by the officer concerned of this department on 22/01/2025 in the presence of Smt. Archna Gupta (Principal) to verify the compliance of shortcomings communicated vide this department letter No. F6/DFS/MS/WZ/2020/23 dated 15/01/2020.

The status of shortcoming is as under:-

Sr. No	Shortcomings	Status
1.	The width of staircase is less than the required 1.5 m clear width.	Not Rectified
2.	Hose Reel of 30 m length with nozzle of 5 mm on each floor found non functional.	Rectified
3.	Terrace pump of 450 lpm with 40 m head found non functional in auto mode.	Not Rectified
4.	Exit Signages not provided	Rectified

In addition to the above mentioned shortcoming it is to inform you that electrical panel installed under the staircase has to be removed to a safer place.

In view of the above shortcomings, the request for issuance of Fire Safety Certificate can't be considered at this stage & rejected. You are advised to rectify the above mentioned shortcomings under intimation to this department for further necessary action in this regard.

Yours faithfully,

b. 011-23414000

Copy to:-

1. The Director, Directorate of Education, Old Secretariat, Delhi.