

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE, NEW DELHI-110001



No: F.6/DFS/MS/School/2025/WZ/ 387

Dated:

14/05/2025

To,

The Principal, M.C. Primary Co-ed School, Phase-II, Block-C, Site-3, Holambi Kalan, Delhi-110082.

Sub: - Regarding issuance of Fire Safety Certificate in r/o M.C. Primary Co-ed School located at Phase-II, Block-C, Site-3, Holambi Kalan, Delhi- 110082.

Sir,

This has reference to your email id dated 03.04.2025 on the subject cited above. In this connection, it is to inform you that the inspection of above said school building has been carried out by officer concerned of this department on 07.05.2025 to see the to see the compliance of the requisite fire safety measures. Sh. Vinay Kumar (Principal) was present at the time of inspection.

During the course of inspection it was observed that school building is comprised of Ground plus Two upper floors. Your request for issuance of FSC is rejected due to the following shortcomings:-

1. Width of staircases found 1.50 m & 1.20 m against the required width of 1.50 m each.

2. First aid hose reels found not provided.

3. Terrace level pump of 450 lpm discharge capacity found not provided.

4. Overhead tank of 10,000 ltrs capacity found not provided.

5. Exit signage's are not provided.

6. Electrical panel and electric meter installed under the staircase has to be removed to a safer place or been segregated..

You are advised to rectify the above-mentioned shortcomings under intimation to this department.

Yours/Faithfully

Director

PK. 011-23414000

Copy to:-

1. Director of Education, MCD, Civic Centre, New Delhi.

915