



GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: CANNAUGHT PLACE NEW DELHI- 110 001

No.F.6/DFS/MS/School/2025/NDZ/ 365

Dated: 09 05 2025

To,

The Principal, MCD Pratibha Vidaylaya Shastri Park Extension, Delhi-110053

Subject:-Regarding Issuance of Fire Certificate in r/o MCD Pratibha Vidaylaya at Shastri Park Extension, Delhi- -110053.

Sir,

This is in reference to your letter no. nil dated 18/03/2025 on the subject cited above. In this connection, it is to inform you that the officer concerned of this department has visited the school on dated 03/05/2025 in presence of Mrs. Evelyn Pratima, Principal and observed that the shortcomings as communicated earlier vide letter No. F.6/DFS/MS/School/2021/NDZ/647 dated 13/12/2021 (copy enclosed) have not been complied yet.

In view of the above, Fire Safety Certificate cannot be considered at this stage. You are requested to rectify the shortcomings communicated vide above mentioned letter under intimation to this office for further action.

Encl:- As above

DIRECTOR DELHI FIRE SERVICE

Yours faithful

Copy to:-

The Director of Education (MCD)
15th Floor, E-Block, Dr. S.P. Mukahrjee Civic Center, JLN Marg, New Delhi-110002

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI- 110001

No. F.6/DFS/MS/School/2021/NDZ/647

Dated: [3/12/2021

To,

The Principal, EDMC Primary School, Buland Masjid, Shastri Park Extension Delhi-110053

Subject:- Request for site visit.

Sir,

With reference to letter No. E.E. (Elect.)-II/Shah (S)/2021-2022/D-570 dated 27/10/2021 on the subject cited above, it is informed that officer concerned of this department inspected the school from fire safety point of view in presence of Sh. Manoj Kumar Aggarwal, Principal of the school & Sh. Kuldeep Kumar Singh, J.E. (Elect.) Shahdara South Zone on dated 29/11/2021. The school building comprises of ground plus two upper floors. During the course of inspection following observations was made:-

1. One staircase of width 1.50 meter or an additional staircase of 0.75 meter width is not provided.

In view of the above, the school building cannot be considered for issuance of Fire Safety Certificate at this stage. Therefore, you are requested to provide the above mentioned fire safety arrangements under intimation to this office for further course of action.

Copy to:-

- The Director of Education, EDMC Udyog Sadan, Plot No. 419, FIE, Patparganj Industrial Area, Delhi-110092
- The Ex. Engr. (Elect,)-II/SSZ
 EDMC, Office of Executive Engineer (Elect.)-II/SSZ,
 2nd Floor Technical Laboratory,
 Near NH-24 Gazipur, Delhi-110096