clip



GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI EADQUARTERS: DELHI FIRE SERVICE: NEW DELHI-110001

NO. F-6/DFS/MS/EH/2025/SZ/ 185

Dated 0 / 05 / 2025

The Joint Commissioner of Police (Lic/Branch) 1st Floor PS Defence Colony, New Delhi 110049.

Sub: -Regarding issuance of fire safety certificate in r/o M/s MEIRAS BAKEHOUSE at D-2, Ground Floor Defence colony, New Delhi 110024.

Sir,

This has reference to with **MCD Portal 2025040305412 dated 03/04/2025** on the subject cited above. In this connection, this is to inform you that the above mentioned premise was visited by the officer concerned of this department on 23.04.2025 in the presence of Mr. Chander Pal (Supervisor) to verify the fire safety measures installed in the building and observed that restaurant running at Ground and First Floor only. During inspection, following points were observed:

- 1. There are two exit doors having width of 1.50 mtr & 1.35 mtr against the required width of 1.50 mtr each at first floor level.
- 2. Kitchen need to be segregated by means of fire check door.
- 3. First aid hose reel not working.
- 4. MOEFA not working.
- 5. Internal hydrant not working.
- 6. Terrace level fire fighting pump capacity 450 LPM not provided.
- 7. Overhead tank capacity 20,000 ltrs not provided
- 8. Exit Signage not provided.

In view of above Shortcomings, the application for issuance Fire Safety Certificate is rejected. The occupancy of the building/premises in absence of requisite fire safety arrangements shall be at the risk and liability of the owner/occupier. The Licensing authority/ Statutory Authority may take suitable necessary action as deemed fit.

Yours faithfully

PIRECTOR

DELHI FIRE SERVICE